

SMS Incident Report

30/01/2025 14:04:17

Summary

CAD Number F4126543 **Status** Closed

Station Kawakawa Volunteer Fire Brigade

Incident Started 13/01/2025 18:01:23 **Incident Ended** 14/01/2025 14:15:16

Incident Type 1101: Structure fire with damage

Common Name

Address 9(2)(a) Mason Avenue Moerewa

Alarm Method 111 Telephone **Alarm Level** 2

PFA Number

Zone 127401

Map Grid E 1691692 **Map Grid N** 6083408

First Caller 9(2)(a) **First Caller Contact** 9(2)(a)


Incident Closed 14/01/2025 14:15:16

Report Completed 13:38, Fri 17 Jan 2025 by Out of Scope

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
KAWA747	PR	18:02:11 13 Jan 2025	18:08:23 13 Jan 2025	18:13:21 13 Jan 2025	20:33:03 13 Jan 2025
KAWA741	P1	18:02:11 13 Jan 2025	18:16:39 13 Jan 2025	18:23:32 13 Jan 2025	20:33:34 13 Jan 2025
KAWA7411	WT	18:18:10 13 Jan 2025	18:18:21 13 Jan 2025	18:23:41 13 Jan 2025	20:08:19 13 Jan 2025
PAIH751	P1	18:09:38 13 Jan 2025	18:14:51 13 Jan 2025	18:36:30 13 Jan 2025	19:56:39 13 Jan 2025
PAIH757	PR	18:09:38 13 Jan 2025	18:20:20 13 Jan 2025	18:51:31 13 Jan 2025	19:49:25 13 Jan 2025
VSONORTH02	VSO		19:06:01 13 Jan 2025	19:38:18 13 Jan 2025	22:09:00 13 Jan 2025
VSONORTH01	VSO	19:01:29 13 Jan 2025	19:02:16 13 Jan 2025	19:50:46 13 Jan 2025	22:38:00 13 Jan 2025
FINORTH04	FSO	18:47:12 13 Jan 2025	18:58:09 13 Jan 2025	20:23:14 13 Jan 2025	13:22:58 14 Jan 2025
KERI671	P1	20:42:25 13 Jan 2025	20:42:29 13 Jan 2025	20:44:25 13 Jan 2025	21:56:21 13 Jan 2025
CDNORTH	OF				18:37:07 13 Jan 2025

Start->Alert 7 min 10 min



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
KAWA747	00:00:48	00:11:10	00:11:58	02:31:40
KAWA741	00:00:48	00:21:21	00:22:09	02:32:11
KAWA7411	00:16:47	00:05:31	00:22:18	02:06:56
PAIH751	00:08:15	00:26:52	00:35:07	01:55:16
PAIH757	00:08:15	00:41:53	00:50:08	01:48:02
VSONORTH02			01:36:55	04:07:37
VSONORTH01	01:00:06	00:49:17	01:49:23	04:36:37
FINORTH04	00:45:49	01:36:02	02:21:51	19:21:35
KERI671	02:41:02	00:02:00	02:43:02	03:54:58
CDNORTH				00:35:44

Notifications

Date	Time	Party Notified
13 Jan 2025	18:03:59	CFO/DCFO KAWAKAWA PAGED RE MULTIPLE CALLS
13 Jan 2025	18:05:11	EVENT COPIED TO POLICE
13 Jan 2025	18:08:42	TOP ENERGY
13 Jan 2025	18:09:51	TOP ENERGY RE 2ND ALARM
13 Jan 2025	18:10:55	CDNORTH PAGED 2ND ALARM
13 Jan 2025	18:10:58	CDNORTH Out of Scope ACKNOWLEDGED VIA AMS
13 Jan 2025	18:11:00	CDNORTH Out of Scope ACKNOWLEDGED VIA AMS
13 Jan 2025	18:12:19	LOCAL AUTHORITY (FAR NORTH DISTRICT COUNCIL)
13 Jan 2025	18:13:08	VSO NORTH01 (Out of Scope) - PAGE SENT
13 Jan 2025	18:13:28	VSONORTH01 Out of Scope ACKNOWLEDGED VIA AMS
13 Jan 2025	18:24:47	CDNORTH PAGED SITREP
13 Jan 2025	18:25:03	CDNORTH Out of Scope ACKNOWLEDGED VIA AMS
13 Jan 2025	18:26:09	VSO MURI WHENUA GROUP PAGED K99

Message Log

Time	Message
18:01:54	https://web.pcl.govt.nz/?ecn=9(2)(a)
18:01:56	** LOI search completed at 13/01/25 18:01:56

18:01:57 INC INFO: GARAGE FIRE

18:02:03 ** Recommended unit KAWA741 for requirement PUMP (>5.0 km)
** Recommended unit

18:02:03 KAWA747 for requirement PUMP (>5.0 km)

18:02:04 Station Selcal used to Initiate Alerting. (KAWA741 at 1274 KAWAKAWA 181743)

18:02:05 Station Selcal used to Initiate Alerting. (KAWA747 at 1274 KAWAKAWA 181743)

18:02:10 GARAGE IS NEXT TO FENCE AND HOUSE AND 9(2)(a)

18:02:10 .

18:02:11 ALERTING_COMPLETED KAWA741

18:02:11 ALERTING_COMPLETED KAWA747

18:02:22 GARAGE IS 9(2)(a)

18:02:31 CALLER 9(2)(a)

18:02:31 .

18:02:34 SHED BEHIND THE HOUSE

18:03:00 CLOSE TO HOUSE

18:03:04 SHED BEHIND A RESIDENTIAL HOUSE ON FIRE. CALLER IS LOOKING FROM MAIN RD.

18:05:06 FIR2POL FYI ONLY BRIGADE RESPONDING TO MULTIPLE CALLS FOR A GARAGE FIRE - YOUR A

18:05:06 TTENDANCE IS NOT REQUIRED AT THIS STAGE

18:05:10 ** Event P061273933 of NZP/WE copied from F4126543 of NZFS/NT at: 13/01/25 18:05

18:05:10 :10

18:07:30 FIR2POL JUST WAITING FOR VOLUNTEERS TO GET TO STATION THEN WILL BE ON THE WAY

18:08:14 FIR2POL COPY THANKS

18:08:23 Unit KAWA747 [K1 : PROCEEDING TO INCIDENT]

18:09:10 Unit KAWA747 [COMCEN COM : MESSAGE] MULTIPLE CALLS RECEIVED. WELL INVOLVED GARAG

18:09:10 E OR SHED ON FIRE AT REAR OF PROPERTY ALSO POSSIBLY CLOSE TO A HOUSE. POLICE IN

18:09:10 ATTENDANCE. NEAREST HYDRANT NEXT DOOR OUTSIDE 26 MASON AVE.

18:09:18 Unit KAWA747 [KP : PRIORITY MESSAGE] K99 PROCEEDING TX 2ND ALARM

18:09:28 INC INFO: GARAGE FIRE - K99 PROCEEDING TX 2ND ALARM

18:09:33 ** Recommended unit PAIH751 for requirement PUMP (>14.0 km)
** Recommended unit

18:09:33 ** Alarm level updated to 2

18:09:33 PAIH757 for requirement PUMP (>14.0 km)

18:09:35 Station Selcal used to Initiate Alerting. (PAIH757 at 1275 PAIHIA 181753)

18:09:35 Station Selcal used to Initiate Alerting. (PAIH751 at 1275 PAIHIA 181753)

18:09:38 ALERTING_COMPLETED PAIH757

18:09:38 ALERTING_COMPLETED PAIH751

18:09:58 ----- 2ND ALARM -----

18:10:14 FIR2POL COPY THANKS

18:12:34 FIR2POL CONFIRM TWO GARAGES ON FIRE?

18:13:12 Unit KAWA747 [COMCEN COM : MESSAGE] TWO GARAGES NOW ON FIRE AT BOTH [REDACTED] AND [REDACTED] MA

18:13:12 SON AVE

18:13:17 Unit KAWA747 [SITREP :] ETA 30 SECONDS

18:13:21 Unit KAWA747 [K99 : PROPERTY FIRE WELL INVOLVED]

18:13:30 INC INFO: TWO GARAGES ON FIRE - K99 PROCEEDING TX 2ND ALARM

18:14:00 TOP ENERGY ETA - 20 MINS

18:14:15 FIR2POL FIRE ON SCENE

18:14:52 Unit PAIH751 [K1 : PROCEEDING TO INCIDENT]

18:16:13 AMS PAIHIA SHOWS 2 CREWS AVAILABLE

18:16:39 Unit KAWA741 [K1 : PROCEEDING TO INCIDENT]

18:16:47 Unit KAWA741 [K1 : PROCEEDING TO INCIDENT]

18:17:34 Unit KAWA741 [K1 : PROCEEDING TO INCIDENT]

18:18:09 Phone used to Initiate Alerting.

18:18:10 ALERTING_COMPLETED KAWA7411

18:18:18 Unit KAWA747 [KC : UNIT CALLING]

18:18:21 Unit KAWA7411 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]

18:18:21 Unit KAWA7411 [K1 : PROCEEDING TO INCIDENT]

18:19:09 Unit KAWA747 [KC : UNIT CALLING]

18:20:14 Unit KAWA7411 [KC : UNIT CALLING]

18:20:20 Unit PAIH757 [K1 : PROCEEDING TO INCIDENT]

18:20:42 Unit KAWA747 [SITREP :] CFO [REDACTED] - ONE SHED WELL INVOLVED, ONE EXPOSURE AT N

18:20:42 UMBER [REDACTED] ONE SHED WELL INVOLVED, AT WORK WITH BA, LPD, HIGH ESTABLISHING WATER.

18:20:47 Unit KAWA7411 [KC : UNIT CALLING]

18:21:22 Unit KAWA7411 [SITREP :] LOGGING SPEED CAMERA ACTIVATION SH 1 MOEREW A

18:23:32 ENTERED BY FIRECOM AS PER AVL

18:23:32 Unit KAWA741 [K2 : IN ATTENDANCE AT INCIDENT] ENTERED BY FIRECOM AS PER AVL

18:23:41 Unit KAWA7411 [K2 : IN ATTENDANCE AT INCIDENT]

18:25:09 CDNORTH [REDACTED] K38 VIA AMS

18:36:30 Unit PAIH751 [K2 : IN ATTENDANCE AT INCIDENT]

18:37:07 Unit CDNORTH [K6 : ON PAGER (STATE LOCATION)]

18:44:29 Unit KAWA747 [KC : UNIT CALLING]

18:46:20 Unit KAWA747 [SITREP :] FIRE NOW CONTAINED OF BOTH SHEDS, WE ARE NOW IN OVERHA

18:46:20 UL, MULTIPLE BA, ONE LPD, ONE HPD, K11F.

18:46:24 Unit KAWA747 [K11F : SPECIALIST FIRE INVESTIGATOR REQUIRED]

18:46:59 INC INFO: TWO GARAGES ON FIRE - 2ND ALARM - TOC: 18:01 TOA: 18:13

18:47:11 Pager used to Initiate Alerting.

18:47:12 ALERTING_COMPLETED FINORTH04

18:47:12 ALERTING_COMPLETED FINORTH04

18:51:31 Unit PAIH757 [K2 : IN ATTENDANCE AT INCIDENT]

18:54:26 KERI671 ADV THEY HAVE ARRIVED AT KAWAKAWA STATION FOR THE COVER

18:55:55 FINORTH04 (Out of Scope) ACK PAGE - UNABLE TO GET THROUGH TO CFO
Out of Scope TO PATC

18:55:55 H CALL THROUGH. Out of Scope WILL START HEADING TO SCENE. IF COMMS GETS A HOLD
OF CFO Out of S

18:55:55 Out of Scope PLEASE PATCH HIM THROUGH TO Out of Scope.

18:58:10 Unit FINORTH04 [K1 : PROCEEDING TO INCIDENT]

18:58:35 Unit KAWA7411 [K2 : IN ATTENDANCE AT INCIDENT]

18:58:43 Unit KAWA7411 [K2 : IN ATTENDANCE AT INCIDENT]

18:59:57 Alarm Timer Extended: 0

19:00:45 Unit KAWA747 [COMCEN COM : MESSAGE] FIRECOM CALLS NIL RESPONSE

19:01:02 Unit KAWA747 [KC : UNIT CALLING]

19:01:28 Pager used to Initiate Alerting.

19:01:29 ALERTING_COMPLETED VSONORTH01

19:01:29 ALERTING_COMPLETED VSONORTH01

19:01:52 Unit VSONORTH01 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT
ADDRESS)]

19:01:52 VIA PHONE

19:02:01 Unit VSONORTH01 [K39-1 : TRANSMIT K1]

19:02:05 Unit VSONORTH01 [K6 : ON PAGER (STATE LOCATION)]

19:02:16 Unit VSONORTH01 [K1 : PROCEEDING TO INCIDENT]

19:02:49 WAYNE MARTIN TRANSFERRED TO FINORTH04

19:05:00 Unit VSONORTH01 [K1 : PROCEEDING TO INCIDENT]

19:06:01 Unit VSONORTH02 [K1 : PROCEEDING TO INCIDENT]

19:10:28 Alarm Timer Extended: 0

19:24:40 Alarm Timer Extended: 0

19:28:56 Unit VSONORTH01 [K1 : PROCEEDING TO INCIDENT]

19:29:04 Unit VSONORTH01 [K1 : PROCEEDING TO INCIDENT]

19:38:18 Unit VSONORTH02 [K2 : IN ATTENDANCE AT INCIDENT]

19:41:47 Unit VSONORTH02 [SITREP :] (VIA PHONE) I AM K2 AT KAIKOHE BASE GETTING
EQUIPME

19:41:47 NT. I WILL NOTIFY ON THE RADIO ONCE I AM K2 AT SCENE

19:49:26 Unit PAIH757 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

19:50:20 Alarm Timer Extended: 0

19:50:46 Unit VSONORTH01 [K2 : IN ATTENDANCE AT INCIDENT]

19:56:39 Unit PAIH751 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

20:08:19 Unit KAWA7411 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

20:09:00 Unit KAWA747 [KC : UNIT CALLING]

20:10:11 Unit FINORTH04 [K1 : PROCEEDING TO INCIDENT]

20:11:49 Unit KAWA747 [STOP : MESSAGE] OVERHAUL COMPLETE CREWS MAKING UP
AWAITING ARRIVA

20:11:49 L OF FIRE SAFETY

20:23:05 Alarm Timer Extended: 0

20:23:14 Unit FINORTH04 [K2 : IN ATTENDANCE AT INCIDENT]

20:31:08 Alarm Timer Extended: 0

20:32:41 Unit KAWA747 [KC : UNIT CALLING]

20:32:59 Unit KAWA747 [SITREP :] SCENE HANDED OVER TO FIRE INVESTIGATOR

20:33:03 Unit KAWA747 [K10 : RE-COMMISSIONING APPLIANCE]

20:33:34 Unit KAWA741 [K10 : RE-COMMISSIONING APPLIANCE]

20:41:23 Unit FINORTH04 [KP : PRIORITY MESSAGE]

20:42:16 Unit FINORTH04 [KP : PRIORITY MESSAGE] KAWAKAWA APPLIANCE TO RETURN TO
SCENE GA

20:42:16 S BOTTLES LEAKING

20:42:22 MSU Selcal used to Initiate Alerting. (KERI671 D0BF12)

20:42:25 ALERTING_COMPLETED KERI671

20:42:29 Unit KERI671 [K1 : PROCEEDING TO INCIDENT]

20:43:27 DISP NOTE : KERI671 ATTACHED AS THEY WERE DRIVING PAST THE SCENE AS KP
ENTERED B

20:43:27 Y FINORTH04

20:44:25 Unit KERI671 [K55 : SPECIAL SERVICE INCIDENT]

20:50:35 Unit KERI671 [KC : UNIT CALLING]

20:51:56 Unit KERI671 [SITREP :] SO **Out of Scope** - REMOVING LPG CYLINDERS FROM SHED
TWO IN

20:51:56 BA ONE COVERING HPD

20:55:00 Unit KERI671 [KC : UNIT CALLING]

20:55:59 Unit KERI671 [SITREP :] CYLINDERS REMOVED FROM SHED ONE CYLINDER LEAKING
COVER

20:55:59 ING WITH HPD

21:00:19 Unit VSONORTH02 [KC : UNIT CALLING]

21:01:50 Unit VSONORTH01 [KC : UNIT CALLING]

21:01:52 Unit VSONORTH02 [SITREP :] LEAVING KAIKOHE BASE HEADING TO KAWAKAWA
THEN PAIHI

21:01:52 A WITH LEVEL 2 GEAR AND BA

21:02:05 Unit VSONORTH01 [SITREP :] SAME TRAFFIC

21:10:32 Alarm Timer Extended: 0

21:14:46 Unit KERI671 [KC : UNIT CALLING]

21:15:27 Unit KERI671 [K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]

21:36:37 Unit FINORTH04 [KC : UNIT CALLING]

21:37:28 Unit FINORTH04 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

21:37:32 Unit FINORTH04 [SITREP :] FIRE INVESTIGATION COMPLETED WILL BE RETURNING
IN MO

21:37:32 RNING

21:39:36 Alarm Timer Extended: 0

21:51:04	Unit VSONORTH02 [KC : UNIT CALLING]
21:51:42	Unit VSONORTH02 [SITREP :] LEAVING KAWAKAWA TO HEAD FOR PAIHIA NOW
21:52:36	Unit KERI671 [KC : UNIT CALLING]
21:52:55	Unit KERI671 [STOP : MESSAGE] SCENE LEFT IN HANDS OF OWNER
21:55:36	Unit VSONORTH01 [KC : UNIT CALLING]
21:56:21	Unit KERI671 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
22:09:00	Unit VSONORTH02 [K9 : OFF RT (STATE LOCATION)]
22:21:15	Unit VSONORTH01 [K2 : IN ATTENDANCE AT INCIDENT]
22:38:00	Unit VSONORTH01 [K6 : ON PAGER (STATE LOCATION)]
07:10:22	FIRE INVESTIGATION
07:10:28	** Event F4126543 has been reopened at: 14/01/25 07:10:28
07:10:29	** LOI search completed at 14/01/25 07:10:29
07:10:46	Unit FINORTH04 [K1 : PROCEEDING TO INCIDENT]
07:10:54	Unit FINORTH04 [K1 : PROCEEDING TO INCIDENT]
07:13:07	FINORTH04 - CAN I BE ATTACHED TO THE ^{9(2)(a)} MASON AV JOB? (K38 RECEIVED, K39-1)
08:27:11	Unit FINORTH04 [K1 : PROCEEDING TO INCIDENT]
08:47:57	Unit FINORTH04 [K2 : IN ATTENDANCE AT INCIDENT]
09:32:37	Alarm Timer Extended: 0
09:32:39	Alarm Timer Extended: 0
13:22:22	Unit FINORTH04 [KC : UNIT CALLING]
13:22:52	Unit FINORTH04 [STOP : MESSAGE] FIRE INVESTIGATION
13:22:59	Unit FINORTH04 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

Incident

CAD Number F4126543
Incident Reporter Out of Scope
Incident Controller
Distance Travelled (km)
Delay In Receiving Call

Property Details

Occupant 9(2)(a)
Building Owner Owner occupied
General Property Use Single house
Special Property Use Single house
Purpose Group

Actions

Persons Reported

Trapped

Evacuation Status Fully evacuated

Action Prior 1

Action Prior 2

Action Taken Extinguishment only: Includes isolating fuel/power

Civilians

Civilians Rescued 0

Civilians Extricated 0

Civilians Assisted 0

Civilians Evacuated 0

Origin

Location Garage, Carport, Vehicle storage, Storage Shed

Level Ground level

Equipment Used

Quantity	Equipment
1	Low pressure delivery
1	Hose reel, high pressure delivery

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition Totally involved fire

Heat Source Unable to classify

Termination Stage

First Object Ignited

First Object Material

Second Object Ignited

Second Object Material

Indicated Cause Undetermined

Certainty of Cause Low

Age of Person No person involved

Ethnicity

Gender

FAIP Service Offered Unknown

RELEASED UNDER THE OFFICIAL INFORMATION ACT 1982

Exposure Number 1

Incident Type 1101: Structure fire with damage
Address Moerewa
Distance Exposure Travelled
Surface Material of Exterior Wall
Construction Material of Roof
Method of Heat Transfer

Property Details

Occupant 9(2)(a)
Building Owner Owner occupied
General Property Use Single house
Special Property Use Garage
Purpose Group

Actions

Persons Reported Trapped
Evacuation Status Fully evacuated
Action Prior 1
Action Prior 2
Action Taken Extinguishment only: Includes isolating fuel/power

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	0
Civilians Deceased	0

Origin

Location Garage, Carport, Vehicle storage, Storage Shed
Level Ground level

Equipment Used

Quantity	Equipment
1	Hose reel, high pressure delivery
1	Low pressure delivery

Equipment Involved

Equipment Involved

Year

Make

Model

Comments

1/17/2025 1:38:10 PM

Reporter Comments

Incident F4126543 - [REDACTED] Mason Ave Morewa 14/01/2025 FI Comments for SMS

Fire and Emergency received multiple calls to a garage on fire at [REDACTED] Mason Ave Morewa, which spread to timber fence-lines then to a neighbouring garage at [REDACTED] Mason Ave Morewa. A FENZ 2nd alarm response, fires were extinguished with multiple hose lines.

The initial garage, 6m x 6 m concrete floor base, timber framed construct on, timber T & G interior lining, ply timber sheet exterior cladding and a corrugated iron roof, divided into a separate sleepout and garage storage was totally consumed by fire.

The 2nd structure at [REDACTED] Mason Ave, a standalone garage 6m x 6m, concrete floor base, timber framed, non-lined interior, metal sheeting exterior clad, corrugated iron roofing suffered intensive damage, but the main structure remained standing. An attached timber lean too suffered structural damage also. A large section of timber fence-line was destroyed between the two properties.

A fire investigator was requested & responded to determine the area of origin and cause.

Investigation confirmed the initial garage at [REDACTED] Mason Ave was the overall area of origin structure. This structure had an 9(2)(a) [REDACTED]

Investigation confirmed no live electrical power was present to the garage at the time of the incident, and several other possible causes from within the garage were eliminated. Inspection of fire spread patterns indicated the area of origin appeared to be on the 9(2)(a) [REDACTED] area side the garage. Possible causes such as a possible candle left burning, or a portable gas cooker which had been used a few hours earlier, did not appear to be in the probable area of origin.

Thorough inspection of the probable area of origin, no item or possible cause was identified, including any suspicious activity, so as a result this incident is classified as Undetermined.

Greg Hartwell
Specialist Fire Investigator

Greg Hartwell

1/17/2025 1:38:44 PM

Reporter Comments

A garage structure fire which has spread along a fence-line and into a neighbour's property, engulfing a 2nd garage and lean-too.

Greg Hartwell