From: Minnie To: Ripul

Traffic Engineering (AT) Cc. Danny

Subject: RE: 261 Twilight Rd - LGOIMA Friday, 3 March 2017 14:12:03 Date:

Attachments: image001.jpg

image002.jpg image003.jpg image004.jpg image005.jpg image006.jpg image007.png image008.ipg image009.ipg image010.jpg image011.ipg image012.ipg image013.jpg

Hi Ripul,

The road widening to 7m is to accommodate the heavy vehicles generated from the cleanfil activity, hence the consent was granted based on the road widening condition. The current works has not fulfil this consent condition hence not acceptable to AT.

Also road shoulder has not been provided. When the road is widened the developer has removed the existing shoulder however did not replace with a new one. A minimum of 500mm shoulder should be provided to comply with Council / AT standard.

Several power poles are right against the edge line after the road widening, which become road side safety hazards and should be relocated to achieve suitable clearance.

Regards, Minnie

From: Danny

Sent: Friday, 24 February 2017 8:35 a.m.

To: Minnie

Subject: FW: 261 Twilight Rd - LGOIMA

From: Ripul Sent: Thursday, 23 February 2017 5:32 p.m. ; Kimdon **Cc:** Road Safety Engineering (AT) ; Jasmine ; Traffic Engineering (AT)

Subject: RE: 261 Twilight Rd - LGOIMA

Hi Irene, all

Thanks for coming back on this, LGOIMA request has been extended till 24 Mar, so will try and answer that before 2nd week of March. Also please see attachment, not happy about it.

I will give you a call tomorrow on this.

Thanks Regards, Ripul

From: Irene

Sent: Wednesday, 22 February 2017 10:20 p.m.

To: Ripul

Cc: Road Safety Engineering (AT) ; Jasmine

Subject: FW: 261 Twilight Rd - LGOIMA

Hi Ripul

Thanks for your email, do you know where about is the proposed guardrail site?? Do you have a copy of the guardrail design — as we would like to ensure that both the selection of the guardrail, the shy line and the design complies with the NZTA standard.

Please can you help?

Many thanks

Irene

From: Ripul

Sent: Monday, 20 February 2017 5:37 p.m.

To: Danny | Irene | ; Peter | ; Angela | ; Dayal | Kimdon

Cc: Traffic Engineering (AT) ; Road Safety Engineering (AT)

Subject: RE: 261 Twilight Rd - LGOIMA

Hi everyone,

Veer ____ (Council Development Engineer team leader) has sent me a list of to do things for 261 Twilight Rd – see below. He has also mentioned that in his opinion where there is an actual physical constraint on site such that pole is on one side and cliff on the other – it is hard to achieve 7m road widening but not for a continuous part of the chain-age.

In terms of moving forward, what do we want from the applicant before signing off? Your response will also help me answer LGOIMA request that AT has received and myself and Dayal (AT Senior Quality Assurance Engineer) will ensure that it's provided before sign-off. Please let us know

Note -

- Road safety audit has been provided and they have confessed that Armco barrier is something they haven't done and rest everything else has been done.
- Tree was removed by settling \$40,000 payment to resident where it encroached half the tree. (point #9)

Veer has ensured me that until all AT issues are resolved, Auckland Transport should not be sign off and in fact he is not happy with the improvements that have been done to this section of the road so far. If meeting for half hour (over skype) helps, I am happy to schedule that but both myself and Dayal need

clear directions to where we are heading for this.

Also note that I am still waiting for Veer/Doug (Council DE) to come back to me outlining how much involvement Auckland Transport had during Engineering Approval application.

Many Thanks Regards, Ripul

This email was sent on 25 Nov from Veer (Council) to applicant.

Hi Kevin

Have you addressed the issues listed on 25/11:

- 1 Trucks on road carrying "material" to the landfill
- 2 Road Width measurements are even as low as 5.6m at places.
- What is the governing speed limit and is there any proposal to reduce it
- What is happening about the engine breaking noise
- 5 Has the channel been set out in accordance with the approved plans
- 6 Road corner visibility at Jill's corner?
- 7 Are trucks allowed only between 7a.m-5.30p.m?
- 8 Channel needs clean up and can it be extended (to near Jill's corner)
- 9 Big tree near Jill's property is to be removed; Council has asked the developer to proceed from the road side if 'right of entry' issue is not resolved.
- What about other trees
- 11 Can there be any house stability issues for Jill after the tree is removed
- Arborists report may be needed to ascertain any damage to the native trees on Jill's property due to road works
- Rock support may be required around chainage 650-680m
- What is the difference between the URS and AECOM drawings
- 15 The distance from the seal to the road edge is not 500mm at all places
- Dead tree near chainage 780 needs to be cut and the property owner is happy to allow access
- 17 Side batters are a matter of concern near chainage 850m 990
- 18 Electric wires seem to be low at chainage 1000m
- 19 Catchpit leads near Ch:1100?

20	Geotech advice for the Tree near Ch:1150?
21	There are steep slopes at places that may need retaining. Has the Geotech engineer looked at the downhill side slopes (like near Leane's property)
22	Power poles close to the seal area
23	Can there be speed cameras to monitor speeds
24	Why is the road widening undertaken only in a small stretch and not for the full length from Kimpton Rd to the landfill access point
25	Visibility from 314 Twilight Road (turning right)
26	There are trucks going towards Clevedon from landfill (turning right)
27	Caution Signs?
28	Downhill slope failure near 70m short of the landfill entrance
29	Any tracking curves
30	Road safety audit
Thanks	
Veer	
From: Gro	up Services CRT (AT)
Sent: Mon To: Kimdo	nday, 20 February 2017 10:22 a.m. Veer
Cc: Ripul	Dayal
Susana Fui	; Douglas iono (AT)
Subject: F	W: 261 Twilight Rd
Importanc	e: nigii
Hi All,	
Following	up on the below as this LGOIMA is due tomorrow, please advise asap
Many than	nks
8 Noleon 51	reet Auskland CBD 1010
	reet, Auckland CBD, 1010 92250, Auckland 1142

Working together to create an awesome journey - first time, every time



From: Kimdon
Sent: Friday, 17 February 2017 10:51 a.m.
To: Veer ; Ripul
Cc: Dayal
Douglas
Subject: RE: 261 Twilight Rd

Hi Veer,

Are you able to provide any info about the input AT had into the EPA, in particular around the deviations from 7m wide road requirements?

I'm hoping we were involved and there is a record showing our comments which we can provide for the LGOIMA.

Ripul,

Could you see if there is anything in Sharepoint for this?

Failing that, we may need to undertake/engage a RSA, to assess the road and determine what is required to provide to the developer to complete.

Regards



Hi Ripul

Doug is away sick (for last few weeks) and he was involved in engineering approval process. In the meantime please proceed with the list that is required to make this a safe and functional road. The applicant will be asked to complete this before a sign off can be provided

Regards

Veer | Team Leader Development Engineering (South)

Auckland Council, Level 4 Kotuku House, 4 Osterley Way, Manukau

Visit our website: www.aucklandcouncil.govt.nz

From: Ripul

Sent: Thursday, 16 February 2017 6:05 p.m.

To: Veer Kimdon

Cc: Dayal

Subject: 261 Twilight Rd

Hi Veer,

As per our discussion yesterday, could you place let me know how much involvement Auckland Transport had while processing EPA for 261 Twilight Rd signed off by D.Mitchell - 2 Sept2016 – as attached.

Road safety and Maintenance team at Auckland Transport have raised issues regarding pavement failure as well as safety of the drivers "The road will be carrying heavy truck loads and as a result good edge support is required to the road pavement otherwise the road will fail"

- I will be able to respond to LGOIMA request after that.

Many thanks

Regards,

WARNING This email may contain information which is CONFIDENTIAL and may be subject to LEGAL PRIVILEGE. If you are not the intended recipient, you must not peruse, use, disseminate, distribute or copy this email or attachments. If you have received this in error, please notify us immediately by return email, facsimile or telephone (call us collect) and delete this email. Thank you. Phone: +64 9 355 3553 or Fax: +64 9 355 3550. AUCKLAND TRANSPORT ACCEPTS NO RESPONSIBILITY FOR CHANGES MADE TO THIS EMAIL OR TO ANY ATTACHMENTS AFTER TRANSMISSION FROM AUCKLAND TRANSPORT. Nothing in this email designates an information system for the purposes of section 11(a) of the New Zealand Electronic Transaction Act 2002, unless expressly stated otherwise.



CAUTION: This email message and any attachments contain information that may be confidential and may be LEGALLY PRIVILEGED. If you are not the intended recipient, any use, disclosure or copying of this message or attachments is strictly proh bited. If you have received this email message in error please notify us immediately and erase all copies of the message and attachments. We do not accept responsibility for any viruses or similar carried with our email, or any effects our email may have on the recipient computer system or network. Any views expressed in this email may be those of the individual sender and may not necessarily reflect the views of Council.