

6 Henderson Valley Road, Henderson, Auckland 0612 Private Bag 92265, Auckland 1142, New Zealand **Ph** 09 355 3553 **Fax** 09 355 3550

22 May 2017

Walter Stone fyi-request-5782-2cc01a34@requests.fyi.org.nz

Dear Walter

Local Government Official Information and Meetings Act 1987 CAS-449666-X8B0R6

Thank you for contacting Auckland Transport on 24 April 2017 requesting details of all motor vehicle accidents and complaints and correspondence relating to the vicinity of 91 Point View Drive, East Tamaki Heights.

A search was conducted within the New Zealand Transport Agency Crash Analysis System for all crashes (fatal, serious, minor and non-injury crashes) reported to New Zealand Police over the past 10 years (2007-2016) within the vicinity of 91 Point View Drive, East Tamaki. Please note, this information does not include crashes that have not been reported to the Police. See map below.

HEYINGTON LINK B	ROOT
POINT VIEW DR TW	VONT RISE
DUNLOY	
GILFORD	
GLASTRY	VIEW
Iowbank	+ + + + + + +
school 47 House Staon NS	
2000 AL	1 + + + 1 - 1- 1-



It was found that over the past 10 years, seven loss of control crashes (five minor and two non-injury) have been reported within this search criteria as follows:

- Minor crash August 2007- Car westbound on Point View Drive, lost control on right a right hand bend, road wet, dark and light rain. Crashes into fence of 95 Point View Drive.
- Minor crash March 2013 Car westbound on Point View Drive, lost control on right a right hand bend, road wet, dark and heavy rain. Crashes drives into of 91 Point View Drive.
- Minor crash April 2013 Car westbound on Point View Drive, lost control on a right hand bend, road wet, overcast and heavy rain. Car crashes into letterbox and wire fence of 91 Point View Drive.
- Minor crash May 2014 Car westbound on Point View Drive, lost control on a right hand bend, road wet, overcast and light rain. Crashes drives into fence of 91 Point View Drive
- Minor crash April 2015 Car westbound on Point View Drive, travelling too fast for conditions, lost control on a right hand bend, road wet, dark and mist. Car drives into post outside 91 Point View Drive.
- Non-injury crash February 2014 Car westbound on Point View Drive, lost control on a right hand bend, road wet, overcast and light rain. Car came to rest in front of 90 Point View Drive.
- Non-injury crash May 2016 Car westbound on Point View Drive, lost control under heavy braking on a right hand bend, road wet, overcast and fine. Car drives into fence of 91 Point View Drive.

Please also find attached copies of correspondence relating to speed, traffic volumes and roading conditions at this location from our Customer Relationship Management (CRM) system. Please note that staff names have been redacted under section 7(2)(a) of the LGOIMA as withholding the information is necessary to protect the privacy of natural persons.

We trust this information has addressed the matters raised however you have the right in accordance with section 27(3) of the Local Government Official Information and Meetings Act 1987 (LGOIMA) to make a complaint to the Office of the Ombudsman if you are not satisfied with our response.

Yours sincerely

Randhir Karma Group Manager - Network Management and and Safety

Enc. CRM Cases 91 Point View Dr_Redacted

