# **SMS Incident Report**

06/06/2017 11:26:17

**Summary** 

CAD Number F2302585 Status Closed

**Station** Piha Fire Brigade

Incident Started 07/05/2017 01:35:01 Incident Ended 07/05/2017 08:16:22

Incident Type 1101: Structure fire with damage

**Common Name** 

Address / 23 Marine Parade South Piha

Alarm Method 111 Telephone Alarm Level 2

**PFA Number** 

**Zone** 147600

 Map Grid E
 1730781
 Map Grid N
 5909000

**First Caller** 

**Incident Closed** 10/05/2017 10:54:37

**Report Completed** 16:50, Fri 26 May 2017 by

### Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
PIHA761	P1	01:35:43 07 May 2017	01:42:12 07 May 2017	01:46:39 07 May 2017	04:48:44 07 May 2017
TITI691	P1	01:47:49 07 May 2017	01:52:48 07 May 2017	02:19:58 07 May 2017	03:20:28 07 May 2017
GLEN641	P1	01:47:46 07 May 2017	01:50:02 07 May 2017	02:20:50 07 May 2017	04:48:37 07 May 2017
REGION1G	OF	01:55:06 07 May 2017	01:55:07 07 May 2017	02:28:39 07 May 2017	03:12:29 07 May 2017
AUCKOSU2	SV	01:53:27 07 May 2017	01:53:35 07 May 2017	02:32:47 07 May 2017	03:26:06 07 May 2017
WAIA711	P1 (7	01:47:04 07 May 2017	01:54:42 07 May 2017	02:36:12 07 May 2017	03:00:02 07 May 2017
FIWAITEM2	FSO	02:28:52 07 May 2017	02:37:05 07 May 2017	03:02:19 07 May 2017	12:55:11 07 May 2017
EVENTNCC1	OT	04:48:16 07 May 2017	04:48:24 07 May 2017	04:48:25 07 May 2017	10:42:20 10 May 2017
WAIA7129	VN	02:03:13 07 May 2017	02:03:42 07 May 2017		02:06:07 07 May 2017
AUCKOSU1	SV				02:56:13 07 May 2017
KARE7371	RP	01:47:03 07 May 2017	01:55:18 07 May 2017		02:00:18 07 May 2017
COMMGR1	OF	01:50:36 07 May 2017			01:55:17 07 May 2017

First Caller Contact

Start->Alert 7 min 10 min

Alert->1st Arrival

# **Elapsed Times**

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
PIHA761	00:00:42	00:10:56	00:11:38	03:13:43
TITI691	00:12:48	00:32:09	00:44:57	01:45:27
GLEN641	00:12:45	00:33:04	00:45:49	03:13:36
REGION1G	00:20:05	00:33:33	00:53:38	01:37:28
AUCKOSU2	00:18:26	00:39:20	00:57:46	01:51:05
WAIA711	00:12:03	00:49:08	01:01:11	01:25:01
FIWAITEM2	00:53:51	00:33:27	01:27:18	11:20:10
EVENTNCC1	03:13:15	00:00:09	03:13:24	81:07:19
WAIA7129	00:28:12			00:31:06
AUCKOSU1				01:21:12
KARE7371	00:12:02		0	00:25:17
COMMGR1	00:15:35	,c.(C)		00:20:16
			1	

# **Notifications**

Date	Time	Party Notified
07 May 2017	01:39:57	K35 PIHA FIRE. AWAITING CREW
07 May 2017	01:46:13	VECTOR
07 May 2017	01:47:11	OSU AUCKLAND VIA PAGER
07 May 2017	01:47:46	NATIONAL COMCEN MGR 2ND ALARM
07 May 2017	01:48:04	AAC AUCKLAND CITY 4 2ND ALARM
07 May 2017	01:51:11	SELCAL FAIL TO KAREKARE ON T/O, ADHOC SUCCESSFUL
07 May 2017	01:52:38	AAC AK CITY 4 ACK PAGE
07 May 2017	03:03:07	VSO BARRETT (CURRENTLY ON LEAVE) CALLS IN FOR DETAILS - HE WAS JUST
07 May 2017	16:41:21	PRESTIGE DUTY PAGED
07 May 2017	16:41:21	ATTENDANCE LIST EMAILED TO PIHA COMMAND AT 1143
07 May 2017	16:41:21	MRF AUCKLAND PAGED RE 2ND HELO
07 May 2017	16:41:21	SHEL8825 ETA 1 HOURS @ 1049HRS
07 May 2017	16:41:21	UPDATED ATTENDANCE LIST EMAILED AT 1240
07 May 2017	16:41:21	RFOAUCKSTH CALLS IN - ADVISES BETHELLS TANKER IS QUITE SMALL - GET WAITAKERE
07 May 2017	16:41:21	MET SERVICE ADVISE VERBALLY LIGHT SOUTH WEST ALONG THE COAST, ALTHOUGH WINDS
07 May 2017	16:41:21	AAC AK CITY 4 REMAINING TO COVER CITY AS 3 OTHER EXECS RESPONDING

SMS Incident Report I	F2302585	3/13 <b>06/06/2017 11:26:17</b>
07 May 2017	16:41:21	PRESTIGE THROUGH TO PIHA COMMAND RE ORGANISING TOW TRUCK
07 May 2017	16:41:21	PRESTIGE1 PHONED RE PIHA761 - MESSAGE LEFT
07 May 2017	16:41:21	CFO LAINHOLM CALLS IN - REQUESTS LAIN7010 ATTACHED AS THEY ARE PART OF A 2ND
07 May 2017	16:41:21	REGION 1G
07 May 2017	16:41:21	WEST672 MANNED ON STATION
07 May 2017	16:41:21	RFOAUCKNTH ACK PAGE - HE ADVISES TO PAGE RFOAUCKSOUTH AND HAVE HIM CONTACT
07 May 2017	16:41:21	CALLED WHENUAPAI FIRE THEY ARE CALLING BACK WITH TANKER AVAILABILITY
07 May 2017	16:41:21	POLICE CALL IN FOR SOME MORE DETAILS/CLARIFICATION - DETAILS PASSED ABOUT 2
07 May 2017	16:41:21	MRF AUCKLAND
07 May 2017	16:41:21	PRESITIGE ETA 25 MINUTES @ 0819HRS
07 May 2017	16:41:21	PRESTIGE (CAN BE CONTACTED ON
07 May 2017	16:41:21	- SHEL8825 K2 @ PIHA DRIVER +2
07 May 2017	16:41:21	RFO AUCK NORTH RE PAGED
07 May 2017	16:41:21	AC WAITEMATA 1
07 May 2017	16:41:21	PRESTIGE1 REQ TO BE TRANSFERRED TO COMMAND UNIT - NO 2 STROKE AVAIL
07 May 2017	16:41:21	SKYWORKS HELICOPTERS PAGED TO PHONE IN RE 2ND HELO
07 May 2017	16:41:21	MET WEATHER SERVICE
07 May 2017	16:41:21	MET WEATHER SERVICE - THEY ARE UNABLE TO PROVIDE THE FIRE FUEL MOSITURE
07 May 2017	16:41:21	FIRE FUEL MOISTURE CODE FOR YESTERDAY AND TODAY IS 75-88
07 May 2017	16:41:21	ICU.AUCKLAND ATTENDANCE VIA E-MAIL
07 May 2017	16:41:21	PAGED PRESTIGE TO PHONE IN - WHEN THEY DO PLEASE TELL THEM WHAT IS NEEDED AS
07 May 2017	16:41:21	PAGED PRESTIGE1
07 May 2017	16:41:21	OF WAIATARUA ADVISES BOTH WHENUAPAI TANKERS ARE ON BASE
07 May 2017	16:41:21	WHENUAPAI ADVISE THEY ARE UNABLEABLE TO TURN OUT
07 May 2017	16:41:21	NORTHCOM1 ACK PAGE
07 May 2017	16:41:21	PRESTIGE1 ADVISE TITI691 HAS BEEN RESTARTED AND IS NOW MOBILE
07 May 2017	16:41:21	AUCK2018 ADVISED RE PIHA761 SO THEY CAN ALSO ADVISE PRESTIGE1 WHEN HE GETS
07 May 2017	16:41:21	SHEL8825 TURNED OUT VIA 8871 PAGER AS PER REQUEST
07 May 2017	16:41:21	SILV STATION TRANSFERRED TO COMMAND UNIT
07 May 2017	16:41:21	SHEL8825 RING TO ADVISE THEY ARE LEAVING PIHA @ 1636HRS - RETURNING TO
07 May 2017	16:41:21	- PUHO7425, MURU8725, SHEL8825 (NOT IN THE SYSTEM YET, CAN TURN
07 May 2017	16:41:21	RFO AUCKLAND SOUTH ( ) VIA PAGER TO CONTACT RFO AUCKLAND NORTH
07 May 2017	16:41:21	AAC AUCKLAND CITY 4
07 May 2017	16:41:21	PIHA761 REQ COMMAND UNIT TO RESPOND TO PIHA DOMAIN

SMS Incident Report	F2302585	4/13	06/06/2017 11:26:17

07 May 2017	16:41:21	PRESTIGE1 PAGED RE PIHA761
07 May 2017	16:41:21	PRESTIGE1 ADVISED TO CHECK IN WITH PIHA COMMAND IN CASE ANY OTHER APPLIANCES
07 May 2017	16:41:21	WAITEMATA AREA 3RD ALARM
07 May 2017	16:41:21	CALLS IN FROM TITIRANGI FIRE AND REQUESTS TITI6929 ATTACHED
07 May 2017	16:41:21	WAITEMATA1 ACK WILL HEAD OUT
07 May 2017	16:41:21	FROM AS IS TOO BUSY TO PHONE IN, A HELICOPTER HAS JUST
07 May 2017	16:41:21	AAC MONRAD PAGED TO PHONE FIRECOMMS

# **Message Log**

01:35:17 INC INFO: FIRE IN VICINITY  01:35:18 ** LOI search completed at 07/05/17 01:35:18  01:35:28 ** Recommended unit PIHA761 for requirement PUMP (>0.5 km)  01:35:58 CALLER LOOKING FROM ABOVE ADDRESS AND CAN SEE FIRE IN THE VICINITY OF TO 01:35:58  01:42:12 Unit PIHA761 [ K1 : PROCEEDING TO INCIDENT]	HE SURF
01:35:28 ** Recommended unit PIHA761 for requirement PUMP (>0.5 km) 01:35:58 CALLER LOOKING FROM ABOVE ADDRESS AND CAN SEE FIRE IN THE VICINITY OF TO CLUB	HE SURF
01:35:58 CALLER LOOKING FROM ABOVE ADDRESS AND CAN SEE FIRE IN THE VICINITY OF TO CLUB	HE SURF
01:35:58 CLUB	HE SURF
01:42:12 Unit PIHA761 [ K1 : PROCEEDING TO INCIDENT]	
01:42:50 INC INFO:	
01:42:50 Duplicate Event:Location = MARINE PDE SOUTH,PIHA,AUCKLAND, Caller Ph Number =	
01:42:50 , Call Source = 111, Event Source = Fire 111	
01:42:50 End of Duplicate Event data	
01:44:50 Unit PIHA761 [ KC : UNIT CALLING]	
01:45:17 Unit PIHA761 [ KP : PRIORITY MESSAGE]	
01:45:58 Unit PIHA761 [ KP : PRIORITY MESSAGE] STRU FIRE AT SURF CLUB, 2ND ALARM	
01:46:16 INC INFO: STRU FIRE , 2ND ALARM	
01:46:17 Duplicate Event:Location = MARINE PDE SOUTH,PIHA,AUCKLAND, Type = STRU -	
01:46:17 INC INFO: EDDIES TAKEAWAYS ON FIRE	
01:46:17 STRUCTURE FIRE, Caller Ph Number = , Call Source = 111Inc InfoEDDIES	
01:46:17 TAKEAWAYS ON FIRE, Event Source = Fire 111	
01:46:17 End of Duplicate Event data	
01:46:27 ** Event Type changed from MIN to STRU at: 07/05/17 01:46:27	
01:46:27	
01:46:30 AMBO EVENT 0064-1-2017/05/07-FIR LINKED AT 07/05/2017 01:46:31	
01:46:35 FIR2AMB: NOTIFICATION OF 2ND ALARM BUILDING FIRE	
01:46:39 Unit PIHA761 [ K99 : PROPERTY FIRE WELL INV]	
01:46:42 ** Recommended unit KARE7371 for requirement RPUMP (>4.7 km)	
01:46:42 ** Recommended unit WAIA711 for requirement PUMP (>10.0 km)	
01:46:43 FIR2POL: NOTIFICATION OF 2ND ALARM BUILDING FIRE	
01:46:50 RRRR	

SWS incident Report	<b>F2302585</b> 5/13	06/06/2017 11:26:17
01:47:03	AMBO update to 0064-1-2017/05/07-FIR:	
01:47:03	Location = 23 Marine Pde South,PIHA,:@PIHA SURF CLUB	
01:47:04	Caller Name = , Caller Address = PIHA ROAD,, Caller Phone =	,
01:47:04	Headline = STRU FIRE , 2ND ALARM	
01:47:05	Problem changed to: NOTIFICATION - Fire Event	
01:47:05	@PIHA SURF CLUB	
01:47:32	[FIR] AMB copies 2nd alarm	×
01:47:36	** Alarm level updated to 2	
01:47:36	** Recommended unit GLEN641 for requirement PUMP (>17.1 km)	
01:47:36	** Recommended unit TITI691 for requirement PUMP (>16.7 km)	
01:47:48	Caller Name = /, Caller Address = PIHA ROAD,, Caller Phone =	
01:47:48	Location = 23 Marine Pde South,PIHA,:@PIHA SURF CLUB	
01:47:48	AMBO update to 0064-1-2017/05/07-FIR:	
01:47:48	Headline = STRU FIRE , 2ND ALARM	
01:47:51	Caller Name = X/, Caller Address = PIHA ROAD,, Caller Phone =	,
01:47:51	Headline = STRU FIRE , 2ND ALARM	
01:47:53	Unit PIHA761 [ KC : UNIT CALLING]	
01:49:57	RRRR	
01:50:03	Unit GLEN641 [ K1 : PROCEEDING TO INCIDENT]	
01:50:04	Unit PIHA761 [ SITREP : ] FISH AND CHIP SHOP GTWW HPD ACESSING \	WATER. 2ND FIRE
01:50:04	AROUND BLUE POOLS AT SOUTH PIHA. UNABLE TO INV 2ND FIRE	
01:52:20	Unit PIHA761 [ KC : UNIT CALLING]	
01:52:44	Unit PIHA761 [ K12 : SUSPICIOUS FIRE]	
01:52:48	Unit TITI691 [ K1 : PROCEEDING TO INCIDENT]	
01:53:04	Unit PIHA761 [ K11P : POLICE REQUIRED] SUSPICIOUS FIRE	
01:53:35	Unit AUCKOSU2 [ K1 : PROCEEDING TO INCIDENT]	
01:54:43	Unit WAIA711 [ K1 : PROCEEDING TO INCIDENT]	
01:55:14	Unit REGION1G [ K1 : PROCEEDING TO INCIDENT]	
01:55:18	Unit COMMGR1 [ K6 : ON TELEPAGER]	
01:55:19	Unit KARE7371 [ K1 : PROCEEDING TO INCIDENT]	
01:56:35	Unit PIHA761 [ KC : UNIT CALLING]	
01:57:31	** Event Type changed from FIR2POL to 1F(2) at: 07/05/17 01:57:31	
01:57:43	Unit PIHA761 [ K11E : ELECTRICAL AUTHORITY REQUIRED] DCFO;	
01:57:44		
01:57:49	DCC AWARE @ 0157	
01:59:17	Unit TITI691 [ KC : UNIT CALLING]	
01:59:58	Unit TITI691 [ SITREP : ] TITI692 IS MANNED	
02:00:30	Unit PIHA761 [ KC : UNIT CALLING]	
02:01:25	Unit PIHA761 [ SITREP : ] 2ND FIRE VIC TASMAN LOOKOUT A NUMBER C	OF SEPERATE FIRES
02:02:39	Unit PIHA761 [ STOP : MESSAGE] GETTING FIRE UNDER CONTROL BUT	STILL ESTABLISHING

SWS incident Report	<b>F2302385</b> 6/13 <b>00/06/2017 11:20:17</b>
02:02:39	WATER SUPPLY. BUILDING SIZE APROX 6 X 25 MTRS EXT ATTACK GAS AND FAT IN BUILDING
02:02:39	AS FISH AND CHIP SHOP
02:03:42	Unit WAIA7129 [ K1 : PROCEEDING TO INCIDENT]
02:04:44	AWS3 AWARE @ 0204
02:05:00	DCC SPEAKING WITH AWC4
02:10:14	WHO LIVES AT RAYNER ROAD SAW A MAN CARRYING 3 DRINK
02:10:14	BOTTLES WALKING UP SYLVAN GLADE TRACK - THE MANS NAME IS HEADING TOWARDS 53
02:10:14	RAYNER ROAD WEARING JEANS AND A GREY PULLOVER
02:14:37	.\
02:14:38	
02:14:49	POL2FIRE CONFIRM THERE IS A STRUCTUR ON FIRE
02:14:54	AS WELL AS VEGETATION
02:15:49	PO; FROM FIRE; STRUCTURE FIRE AT FISH AND CHIP SHOP @ PIHA SURF CLUB AS WELL AS
02:15:49	REPORT OF SCRUB FIRE AT THE GAP/BLUE POOLS
02:16:11	
02:17:49	
02:17:55	<< <nli3 10="" 2<="" td=""></nli3>
02:17:58	SHORTLY
02:18:54	Unit TITI691 [ K1 : PROCEEDING TO INCIDENT]
02:19:58	Unit TITI691 [ K2 : IN ATTENDANCE AT INCIDENT]
02:20:47	INC INFO: STRU FIRE 2ND ALARM TOC 0135 TOA 0146
02:20:50	Unit GLEN641 [ K2 : IN ATTENDANCE AT INCIDENT]
02:21:20	AWC4 AWARE OF ALL UPDATES
02:23:37	Unit TITI691 [ KC : UNIT CALLING]
02:27:24	Unit TITI691 [ KC : UNIT CALLING]
02:28:11	Unit TITI691 [ SITREP : ] K45 PIHA SURF CLUB JOB. K11 FIRE SAFETY
02:28:39	Unit REGION1G [ K2 : IN ATTENDANCE AT INCIDENT]
02:28:43	AAD31 PUT THRU TO AWC4 CELL @ 0228
02:29:15	Unit TITI691 [ K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME]
02:32:47	Unit AUCKOSU2 [ K2 : IN ATTENDANCE AT INCIDENT]
02:34:59	Unit PIHA761 [ KC : UNIT CALLING]
02:35:59	Unit PIHA761 [ SITREP : ] GET SILVERDALE TANKER TO SOUTH PIHA SURF CLUB CAR PARK
02:36:13	Unit WAIA711 [ K2 : IN ATTENDANCE AT INCIDENT]
02:37:06	Unit FIWAITEM2 [ K1 : PROCEEDING TO INCIDENT]
02:38:01	Unit WAIA711 [ K2 : IN ATTENDANCE AT INCIDENT]
02:43:23	Unit WAIA711 [ KC : UNIT CALLING]
02:44:37	Unit WAIA711 [ SITREP : ] EST BASE PUMP AT BASE OF TASMAN VIEW TRACK REQUIRE 1
02:44:37	MORE PUMP FOR WATER SHUTTLE
02:48:29	[.
1	•

SMS Incident Report	F2302585 //13 06/06/2017 11:26:17
02:48:37	STRUCTURE FIRE AT TAKEAWAYS
02:48:43	
02:53:15	
02:53:40	Duplicate Event:Location = MARINE PDE SOUTH,PIHA,AUCKLAND, Type = MIN - MINOR,
02:53:40	INC INFO: FIRE SEEN FROM A DISTANCE
02:53:40	Caller Ph Number = Call Source = 111Inc InfoFIRE SEEN FROM A
02:53:40	DISTANCE, Event Source = Fire 111
02:53:40	End of Duplicate Event data
02:56:38	Unit TITI691 [ KC : UNIT CALLING]
02:58:36	Unit WAIA711 [ KC : UNIT CALLING]
03:00:04	Unit WAIA711 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
03:00:08	Unit WAIA711 [ SITREP : ] ; TASMAN VIEW LOOKOUT BEYOND FF
03:00:08	CAPABILITYS FOR DEL IVERY .AT TOP OF LOOKOUT.
03:00:39	Unit TITI691 [ KC : UNIT CALLING]
03:02:10	Unit TITI691 [ SITREP : ] ; POL AND FIRE SAFETY AND VECTOR ARE IN ATT
03:02:20	Unit FIWAITEM2 [ K2 : IN ATTENDANCE AT INCIDENT]
03:03:07	CONCERNED THAT FIRESAFETY SHOULD ATTEND DUE TO RECENT EVENTS IN PIHA AREA -
03:03:07	ADVISED FIWAITEM2 K1
03:10:33	Unit PIHA761 [ KC : UNIT CALLING]
03:12:30	Unit REGION1G [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
03:12:34	Unit TITI691 [ KC : UNIT CALLING]
03:12:42	Unit PIHA761 [ K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] K45
03:12:42	K11 POLICE
03:14:26	Unit TITI691 [ SITREP : ] DISREGARD
03:20:29	Unit TITI691 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
03:25:29	Unit AUCKOSU2 [ KC : UNIT CALLING]
03:26:04	Unit AUCKOSU2 [ SITREP : ] GOING K4 FROM SURF CLUB K38 TO SCRUB FIRE
03:26:07	Unit AUCKOSU2 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
04:07:00	Unit FIWAITEM2 [ SITREP : ] VIA PHONE: POLICE ARE GOING TO LEAVE A SCENE GUARD
04:07:00	AND I WILL BE BACK AT 1000
04:07:06	Unit FIWAITEM2 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
04:09:14	Unit FIWAITEM2 [ SITREP : ] GLEN EDENS CREW WITH PIHAS TRUCK STILL ON SCENE
04:48:25	Unit EVENTNCC1 [ K2 : IN ATTENDANCE AT INCIDENT]
08:14:21	STOP MESSAGE FROM GLEN641 K47 INCIDENT CLEARED AND LEFT WITH POLICE
08:16:23	Unit EVENTNCC1 [ K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] STOP
08:16:23	MESSAGE FROM GLEN641 K47 INCIDENT CLEARED AND LEFT WITH POLICE
09:59:36	Unit FIWAITEM2 [ K1 : PROCEEDING TO INCIDENT]
09:59:49	Unit FIWAITEM2 [ K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]
10:16:30	Unit FIWAITEM2 [ K2 : IN ATTENDANCE AT INCIDENT]

SMS Incident Report	<b>F2302585</b> 8/13 <b>06/06/2017 11:26:17</b>
12:53:56	FIR2AMB: COPIED THANKS. YOU CAN CLOSE YOUR EVENT. WE WILL SEND A NEW ONE SHOULD
12:53:56	YOU BE REQUIRED.
12:54:06	Unit FIWAITEM2 [ SITREP : ] GOING HOME NOW AND LEAVING WITH POLICE WHO WILL CALL
12:54:06	COUNCIL FOR FENCING. WILL RETURN WHEN INSURANCE COMPANY ASSIGNS AN INVESTIGATOR
12:54:06	AND THEN CAN DISCUSS REMOVING ASBESTOS.
12:55:12	Unit FIWAITEM2 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
16:41:21	INC INFO: SCRUB FIRE AT THE GAP
16:41:21	Type = FIR2AMB VEG 1F FIRE REQUEST AMBULANCE ASSIST VEGETATION FIRE ASSIST
16:41:21	RRRR
16:41:21	FIR2POL: REPORTS OF SCRUB FIRE @THE GAP / BLUE POOLS - WE HAVE AN BEEN ADVISED
16:41:21	TO NOTIFY YOU OF ANY SCRUB FIRES IN VICINITY
16:41:21	Duplicate Event:Location = NULL,OCEANIC,AUCKLAND: @THE GAP, Type = VEG -
16:41:21	VEGETATION FIRE, Caller Name = Caller Ph Number = C
16:41:21	MULTIPLE SUBSCRIBERS FOR CALLER NUMBER . TESA LOOKUP RECOMMENDED.
16:41:21	End of Duplicate Event data
16:41:21	INC INFO:
16:41:21	Duplicate Event:Location = MARINE PDE SOUTH,PIHA,AUCKLAND, Caller Ph Number =
16:41:21	AWS3 AWARE @0204
16:41:21	<< <do a="" have="" on="" seen<="" td="" this="" was="" we="" when=""></do>
16:41:21	нім
16:41:21	
16:41:21	<< <our calling="" car="" crime="" his="" is="" land="" line<="" on="" td="" the="" witness=""></our>
16:41:21	Duplicate Event:Location = PIHA RD,PIHA,AUCKLAND, Type = VEG - VEGETATION FIRE,
16:41:21	Caller Ph Number =, Call Source = 111Inc InfoFIRE IN VICINITY,
16:41:21	INC INFO: FIRE IN VICINITY
16:41:21	Event Source = Fire 111
16:41:21	End of Duplicate Event data
16:41:21	Duplicate Event:Location = NULL,OCEANIC,AUCKLAND: @THE GAP, Type = VEG -
16:41:21	INC INFO: VEGE FIRE
16:41:21	VEGETATION FIRE, Caller Ph Number =, Call Source = 111Inc InfoVEGE
16:41:21	End of Duplicate Event data
16:41:21	INC INFO: FIRE IN VICNITY
16:41:21	Duplicate Event:Location = NULL,OCEANIC,AUCKLAND: @THE GAP, Type = VEG -
16:41:21	VEGETATION FIRE, Caller Ph Number =, Call Source = 111Inc InfoFIRE IN
16:41:21	End of Duplicate Event data
16:41:21	ASAP - URGENTLY
16:41:21	INCIDENTS, THEY ARE SENDING 4 CARS INCLUDING A DOG HANDLER
16:41:21	·
16:41:21	·

16:41:21	
16:41:21	UK RISK TO RAYNER
16:41:21	<b> </b> .
16:41:21	<b> </b> .
16:41:21	*CORRECTION CFO LAINGHOLM
16:41:21	CLOUD ALL ALONG THE WEST COAST AT THE MOMENT, ODD LIGHT SHOWER ALONG THE COAST
16:41:21	QUITE UNLIKELY FOR IT TO DRIFT MUCH INLAND - JUST A LITTLE CLOUD AND LIGHT WINDS
16:41:21	CODES
16:41:21	Duplicate Event:Location = MARINE PDE SOUTH,PIHA,AUCKLAND, Caller Ph Number =
16:41:21	, Call Source = 111, Event Source = Fire 111
16:41:21	INC INFO:
16:41:21	End of Duplicate Event data
16:41:21	** Cross Referenced to Event # P029419671 at: 07/05/17 04:13:46
16:41:21	Duplicate Event:Location = NULL,OCEANIC,AUCKLAND: @THE GAP, Type = VEG -
16:41:21	INC INFO: SCRUB FIRE AT END OF
16:41:21	VEGETATION FIRE, Caller Name = STAPLES NEW ZEALAND LIMITED, Caller Ph Number =
16:41:21	INC INFO: SCRUB FIRE
16:41:21	, Caller Address = TELECOM CELLULAR 027, WELLINGTON CENTRAL,
16:41:21	End of Duplicate Event data
16:41:21	Duplicate Event:Location = MARINE PDE SOUTH,PIHA,AUCKLAND, Caller Name =
16:41:21	PARADE, PIHA, AUCKLAND CITY, Call Source = 111, Event Source = Fire 111
16:41:21	End of Duplicate Event data
16:41:21	PREMISES - ALL OTHER POLICE STAFF ARE LEAVING
16:41:21	POL; FIRE COPY TA
16:41:21	** Cross Referenced to Event # P029419846 at: 07/05/17 05:05:39
16:41:21	COVERING UNIT WEST672 DISPATCHED TO STATION WEST
16:41:21	Duplicate Event:Location = NULL,OCEANIC,AUCKLAND: @THE GAP, Type = VEG -
16:41:21	VEGETATION FIRE, Caller Name =, Caller Ph Number =
16:41:21	Duplicate Event:Location = UNNAMED RD,PIHA,AUCKLAND, Type = VEG - VEGETATION
16:41:21	INC INFO: FIRE IN VICINITY
16:41:21	AS PER AWC4
16:41:21	INC INFO: FIRE IN BUSHES
16:41:21	Duplicate Event:Location = UNNAMED RD,PIHA,AUCKLAND, Type = VEG - VEGETATION
16:41:21	FIRE, Call Source = 111Inc InfoFIRE IN BUSHES
16:41:21	End of Duplicate Event data
16:41:21	*****
16:41:21	*****
16:41:21	Duplicate Event:Location = UNNAMED RD,PIHA,AUCKLAND, Type = VEG - VEGETATION

Swis incluent Report	<b>F2302363</b> 10/13 <b>00/00/2017 11.20</b>
16:41:21	FIRE, Caller Name = HYNDS LIMITED, Caller Ph Number = , Caller Address
16:41:21	= NORTH PIHA ROAD, PIHA, AUCKLAND CITY, Call Source = 111Inc InfoFIRE IN THE
16:41:21	BUSHES, Event Source = Fire 111
16:41:21	why is amb required?
16:41:21	Location = Marine Pde South,PIHA,
16:41:21	AMBO update to 0210-1-2017/05/07-FIR:
16:41:21	Caller Name = , Caller Phone = UNKNOWN, Headline = SCRUB FIRE THIRD ALARM
16:41:21	Problem changed to: ON HOLD - Fire Event
16:41:21	Location = Marine Pde South,PIHA,
16:41:21	FIR2AMB: WE HAVE A 3RD ALARM SCRUB FIRE. ONE AMB IS REQUIRED ON STANDBY AT TI
16:41:21	FIRE COMMAND UNIT
16:41:21	AMBO update to 0210-1-2017/05/07-FIR:
16:41:21	Problem changed to: RED - Fire Event
16:41:21	FIR2POL: HEAVY TOW TRUCK REQ TO PULL FIRE TRUCK
16:41:21	FIR2POL: NEG WE ARE SORTING THE TOW NOW
16:41:21	****
16:41:21	FIR2POL ROGER
16:41:21	POL2FIR ROGER
16:41:21	cccc
16:41:21	AMBO update to 0210-1-2017/05/07-FIR:
16:41:21	Location = Marine Pde South,PIHA,
16:41:21	Caller Name = c, Caller Phone = UNKNOWN, Headline = SCRUB FIRE THIRD ALARM
16:41:21	THERE IN CASE HE MISSES THE PHONE AND PAGER MESSAGE
16:41:21	SHELLY BEACH
16:41:21	
16:41:21	
16:41:21	
10:36:37	** Event Location changed from "23 MARINE PDE SOUTH,PIHA,AUCKLAND: @PIHA SURF
10:36:37	CLUB" to "25 MARINE PDE SOUTH,PIHA,AUCKLAND" at: 08/05/17 10:36:37
10:36:39	** LOI search completed at 08/05/17 10:36:39
10:42:21	Unit EVENTNCC1 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
10:54:32	UNIT EVENTNCC1 RESPONSE TIME [NULL] ADJUSTED TO
10:54:36	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
10:54:36	UNIT REGION1G ALERT TIME [NULL] ADJUSTED TO
10:54:36	Qualifier 2:

# Incident

CAD Number	F2302585
Incident Reporter	
Incident Controller	

Distance Travelled (km) 5
Delay In Receiving Call

**Property Details** 

Occupant Ady's - Takeaway

Building Owner Rented property

General Property Use Shop, Shopping mall, Supermarket, Service station, Car yard, Other sales use

Special Property Use Takeaway bar, Lunch bar, Fish and chips, Fast food

**Purpose Group** 

#### **Actions**

Persons Reported Trapped No

**Evacuation Status** Evacuation to a place of safety inside

Action Prior 1 No action taken by Civilian/Occupant/Passerby

**Action Prior 2** 

Action Taken Extinguishment only: Includes isolating fuel/power supply

### **Civilians**

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	2

**Civilians Evacuated** 

#### Origin

Location Kitchen, Cooking area
Level Ground level

**Equipment Used** 

Quantity	Equipment
1	Vehicle Radio (LMR)
5	Handheld Radio (or Cellphone)
1,0	Hose reel, high pressure delivery
3	Low pressure delivery
4	BA set
1	Portable pump - large - output over 7 litres/sec
3	Hand tools - Crowbar, Saw, Hammer, Mop, Broom, Misc small gear
1	Lighting/lights/lighting apparatus

## **Equipment Involved**

**Equipment Involved** 

Year

Make

Model

Fire

Arrival Condition Totally involved fire

Heat Source Lighters

Termination Stage Unable to classify

First Object Ignited Cabinetry eg. Desks, Tables, Drawers,

Shelving, Wardrobe, Piano

First Object Material Wood: sawn, finished timber

Second Object Ignited Box, Carton, Bag

**Second Object Material** 

Indicated Cause Unlawful
Certainty of Cause High

Age of PersonPersons: 17 - 64 yrsEthnicityEuropean/Pakeha

**Gender** Male

FAIP Service Offered No FAIP Service Accepted No

#### Structure

Oli delai e		
Area of One Floor		65
Age of Building	1946 - 1969	
Structural Frame Type	Brick, Blocks etc	
Number of Floors		1
Number of Basements		0
Internal Wall Lining	Combination of materials	
Ceiling Lining	Gypsum board (e.g. Gib board, Elephant board)	
Material Generating Most Flame	Unable to classify	
Material Generating Most Smoke	Vinyl: Floor covering, Wallpaper	
Avenue of Flame Travel	Furniture, fixtures	
Avenue of Smoke Travel	Structural factor allowing vertical travel - not classified above	
Extent of Flame Damage	Confined to structure of origin	
Area of Flame Damage		65
Extent of Smoke Damage	Confined to structure of origin	
Area of Smoke Damage		65
Extent of Water Damage	Confined to structure of origin	
Area of Water Damage		65

SMS Incident Report F2302585 13/13 06/06/2017 11:26:17

**Extent of Fire Control Damage** 

Confined to structure of origin

**Area of Fire Control Damage** 65

#### **Comments**

Rey Peleased under the Official information and a seleased under the Official information and a selease of the Official information and a selection and a selectio 5/17/2017 1:51:31 PM **Reporter Comments** 

FSO Requested at incident F2302585 on 07 May 2017 01:35

**Chris Lewis**