SMS Incident Report

03/08/2017 08:41:56

Summary

CAD Number F2355187 Status Closed

Station Mount Maunganui Station

Incident Started 02/08/2017 09:21:10 Incident Ended 02/08/2017 09:42:09

Incident Type 7106: False alarm: Undetermined alarm activation

Common Name BAKELS EDIBLE OILS

Address 5 HUTTON PLACE MOUNT MAUNGANUI

Alarm Method Automatic PFA Call Alarm Level

PFA Number 220290 **Zone** 187201

Map Grid E 1882279 **Map Grid N** 5826928

First Caller

Incident Closed 02/08/2017 09:59:29


Report Completed 13:27, Wed 02 Aug 2017 by

Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
MOUN724	PM	09:21:29 02 Aug 2017	09:23:08 02 Aug 2017	09:25:35 02 Aug 2017	09:42:13 02 Aug 2017
TAUR717	PR	09:21:31 02 Aug 2017	09:24:13 02 Aug 2017	09:29:08 02 Aug 2017	09:37:27 02 Aug 2017
MOUN722	P2	09:21:26 02 Aug 2017			09:29:19 02 Aug 2017

First Caller Contact

Start->Alert 7 min 10 min



Alert->1st Arrival

Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
MOUN724	00:00:19	00:04:06	00:04:25	00:21:03
TAUR717	00:00:21	00:07:37	00:07:58	00:16:17
MOUN722	00:00:16			00:08:09

Message Log

Time	Message		
09:21:11	** LOI search completed at 02/08/17 09:21:11		
09:21:11	AL: 220290 09:21:10 INITIAL - AL		
09:21:11	PANEL: STAFF ROOM		
09:21:20	** Recommended unit MOUN724 for requirement PUMP (>0.9 km)		
09:21:20	** Recommended unit MOUN722 for requirement PUMP (>0.8 km)		
09:21:20	** Recommended unit TAUR717 for requirement CANBACKUP (>4.1 km)		
09:23:08	Unit MOUN724 [K1 : PROCEEDING TO INCIDENT]		
09:24:13	Unit TAUR717 [K1 : PROCEEDING TO INCIDENT]		
09:25:35	Unit MOUN724 [K77 : NOTHING SHOWING]		
09:26:43	Unit MOUN722 [KC : UNIT CALLING]		
09:26:58	Unit MOUN722 [SITREP :] AWAITING CREW		
09:27:41	Unit MOUN724 [KC : UNIT CALLING]		
09:28:25	Unit MOUN724 [SITREP :] SO		
09:28:25	EVAC CARRIED OUT. INV FURTHER		
09:28:30	Unit MOUN722 [KC : UNIT CALLING]		
09:29:08	Unit TAUR717 [K2 : IN ATTENDANCE AT INCIDENT]		
09:29:09	Unit MOUN722 [KE : UNABLE TO PROCEED - STATE REASON] INSUFFICIENT CREW		
09:29:20	Unit MOUN722 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]		
09:37:28	Unit TAUR717 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]		
09:41:52	Unit MOUN724 [KC : UNIT CALLING]		
09:42:09	Unit MOUN724 [K46-3 : STOP MESSAGE: FALSE ALARM DEFECTIVE APPARATUS]		
09:42:15	Unit MOUN724 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]		
09:59:29	** Assigned Result Code: STRU, Detailed Event Type: 7100, Qualifier 1: Q1,		
09:59:29	Qualifier 2:		

Incident

CAD Number F2355187
Incident Reporter
Incident Controller
Distance Travelled (km) 2
Delay In Receiving Call

False Alarm

Detector Type Thermal detector
False Alarm Cause Other | No apparent cause

Other Cause Undetermined

Property Details

Building Owner

Occupant

General Property Use

Special Property Use

Released under the Official Information Act **Purpose Group**

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside NZ Fire and Emergency without prior approval