SMS Incident Report

05/09/2017 08:14:40

Summary CAD Number

F2370744 Status Closed

Station Balmoral Station

Incident Started 29/08/2017 21:14:42 Incident Ended 30/08/2017 00:04:01

Incident Type 1101: Structure fire with damage
Common Name PULLMAN HOTEL AUCKLAND

Address UNKN0001 WATERLOO QUADRANT AUCKLAND CENTRAL

Alarm Method Manual PFA Call Alarm Level 3

PFA Number 116516 **Zone** 142004

Map Grid E 1757853 **Map Grid N** 5920514


First Caller First Caller Contact

Incident Closed 30/08/2017 01:26:09

Report Completed 16:22, Mon 04 Sep 2017 by Mark Griffin

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
BALM611	P1	21:16:02 29 Aug 2017	21:17:10 29 Aug 2017	21:19:02 29 Aug 2017	23:35:46 29 Aug 2017
PARN251	P1	21:16:08 29 Aug 2017	21:17:41 29 Aug 2017	21:19:50 29 Aug 2017	00:05:44 30 Aug 2017
GREY261	P1	21:15:59 29 Aug 2017	21:17:22 29 Aug 2017	21:20:11 29 Aug 2017	00:07:36 30 Aug 2017
BALM6117	SU	21:15:59 29 Aug 2017	21:17:22 29 Aug 2017	21:22:45 29 Aug 2017	23:35:32 29 Aug 2017
AUCK206	HPNP	21:16:05 29 Aug 2017	21:19:32 29 Aug 2017	21:22:54 29 Aug 2017	22:45:37 29 Aug 2017
PARN255	HPNP	21:22:43 29 Aug 2017	21:23:51 29 Aug 2017	21:26:33 29 Aug 2017	22:46:46 29 Aug 2017
AUCK2018	CUHU	21:22:45 29 Aug 2017	21:23:55 29 Aug 2017	21:30:11 29 Aug 2017	23:38:48 29 Aug 2017
AUCK207	PR	21:26:23 29 Aug 2017	21:26:52 29 Aug 2017	21:30:17 29 Aug 2017	00:04:03 30 Aug 2017
REMU211	P1	21:22:49 29 Aug 2017	21:23:48 29 Aug 2017	21:31:35 29 Aug 2017	23:02:20 29 Aug 2017
ELLE274	PM	21:22:52 29 Aug 2017	21:24:24 29 Aug 2017	21:34:23 29 Aug 2017	23:02:54 29 Aug 2017
AUCKOSU2	SV	21:28:07 29 Aug 2017	21:28:07 29 Aug 2017	21:46:11 29 Aug 2017	23:58:45 29 Aug 2017
AVON607	PR	21:53:15 29 Aug 2017	21:53:53 29 Aug 2017	21:57:28 29 Aug 2017	22:46:24 29 Aug 2017
ONEH221	P1	21:53:19 29 Aug 2017	21:54:59 29 Aug 2017	22:02:27 29 Aug 2017	22:42:44 29 Aug 2017
TEAT664	PM	21:53:05 29 Aug 2017	21:55:12 29 Aug 2017	22:07:03 29 Aug 2017	22:39:08 29 Aug 2017
AUCKCITY4	OF	22:00:01 29 Aug 2017	22:04:27 29 Aug 2017	22:09:09 29 Aug 2017	23:17:14 29 Aug 2017
AUCKOSU4	CV	21:53:09 29 Aug 2017	21:59:41 29 Aug 2017	22:11:50 29 Aug 2017	23:44:54 29 Aug 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
BALM611	00:01:20	00:03:00	00:04:20	02:21:04
PARN251	00:01:26	00:03:42	00:05:08	02:51:02
GREY261	00:01:17	00:04:12	00:05:29	02:52:54
BALM6117	00:01:17	00:06:46	00:08:03	02:20:50
AUCK206	00:01:23	00:06:49	00:08:12	01:30:55
PARN255	00:08:01	00:03:50	00:11:51	01:32:04
AUCK2018	00:08:03	00:07:26	00:15:29	02:24:06
AUCK207	00:11:41	00:03:54	00:15:35	02:49:21
REMU211	00:08:07	00:08:46	00:16:53	01:47:38
ELLE274	00:08:10	00:11:31	00:19:41	01:48:12
AUCKOSU2	00:13:25	00:18:04	00:31:29	02:44:03
AVON607	00:38:33	00:04:13	00:42:46	01:31:42
ONEH221	00:38:37	00:09:08	00:47:45	01:28:02
TEAT664	00:38:23	00:13:58	00:52:21	01:24:26
AUCKCITY4	00:45:19	00:09:08	00:54:27	02:02:32
AUCKOSU4	00:38:27	00:18:41	00:57:08	02:30:12
PAPA344	00:38:27	00:19:12	00:57:39	01:24:25
WAITEMATA1	00:47:03	00:13:37	01:00:40	01:20:05
AVON6015	00:38:30	00:26:25	01:04:55	02:26:43
GLEN641	00:40:25	00:25:16	01:05:41	02:27:21
AUCKCITY2	00:13:30	00:58:49	01:12:19	02:11:01
FIWAITEM3	01:40:12	00:34:28	02:14:40	03:05:34
MTRO621				00:39:14

Notifications

Date	Time	Party Notified
29 Aug 2017	21:22:25	VECTOR
29 Aug 2017	21:23:32	POL/AMB
29 Aug 2017	21:23:52	AAC AUCKLAND CITY PAGED
29 Aug 2017	21:23:53	POL&AMB
29 Aug 2017	21:27:21	AAC AUCKLAND CITY 2 PAGE ACK WIL RESPOND
29 Aug 2017	21:28:49	ETA FOR VECTOR 30 MINS
29 Aug 2017	21:29:12	AUCKLAND CITY 4 PAGE ACK
29 Aug 2017	21:53:24	VECTOR UPDATED - 3RD ALARM
29 Aug 2017	21:54:12	AMB BY PHNE, ATTENDANCE REQUIRED
29 Aug 2017	21:54:29	AMB/POL 3RD ALARM
29 Aug 2017	21:55:47	AUCKLAND CITY AREA 3RD ALARM GROUP PAGED
29 Aug 2017	21:55:53	AC WAITEMATA1 PAGED
29 Aug 2017	21:57:10	AAC AUCKLAND CITY 2 AND 4 PAGED
29 Aug 2017	21:59:49	AAC AUCKLAND CITY 4 PAGE ACK WILL RESPOND
29 Aug 2017	22:01:31	AC WAITEMATA 1 PAGE ACK WILL RESPOND
29 Aug 2017	22:02:36	AUCKCITY1 ACK PAGE, UPDATED
29 Aug 2017	22:03:14	COUNTIES1 ACK PAGE
29 Aug 2017	22:03:20	COUNTIES 1 PAGE ACK
29 Aug 2017	22:09:04	REQUEST K25 662
29 Aug 2017	22:16:19	ATTENDANCE EMAIL TO ICU AUCKLAND (AUCK2018)
29 Aug 2017	22:55:07	FI WAITEMATA3 PAGED

Message Log

Time	Message
21:14:43	AL: 116516 21:14:42 INITIAL - AL
21:14:43	PANEL: SPRINKLER VALVE HOUSE PRINCES STREET
21:14:44	** LOI search completed at 29/08/17 21:14:44
21:15:00	ACCESS NO: -C
21:15:06	Duplicate Event:Location = UNKN0001 WATERLOO QUAD,AUCKLAND CENTRAL,AUCKLAND:
21:15:06	INC INFO: BUILDING FIRE
21:15:06	@PULLMAN HOTEL AND RESIDENCES BUILDING, Type = STRU - STRUCTURE FIRE, Caller
21:15:06	Name = GPR HOTELS LIMITED, Caller Ph Number =, Caller Address = 2
21:15:06	WATERLOO QUADRANT, AUCKLAND CENTRAL, AUCKLAND CITY, Call Source = 111Inc
21:15:06	InfoBUILDING FIRE , Event Source = Fire 111
21:15:06	End of Duplicate Event data
21:15:15	** Event Type changed from SPRNKLR to STRU at: 29/08/17 21:15:15
21:15:15	INC INFO: CONIRMED FIRE

SMS Incident Report	F2370744 4/11 05/09/2	2017 08:14:40
21:15:34	** Recommended unit AUCK206 for requirement AERIAL (>1.4 km)	
21:15:34	** Recommended unit GREY261 for requirement PUMP (>1.4 km)	
21:15:34	** Recommended unit BALM611 for requirement PUMP (>1.4 km)	
21:15:34	** Recommended unit PARN251 for requirement PUMP (>1.2 km)	
21:15:43	Unit GREY261 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
21:17:12	Unit BALM611 [K1 : PROCEEDING TO INCIDENT]	
21:17:23	Unit GREY261 [K1 : PROCEEDING TO INCIDENT]	×
21:17:42	Unit PARN251 [K1 : PROCEEDING TO INCIDENT]	C
21:17:52	Unit BALM611 [KC : UNIT CALLING]	
21:18:23	Unit BALM611 [SITREP :] FURHTER INFO ON THIS CALL	
21:18:48	Unit BALM611 [COMCEN COM : MESSAGE] WE RECEIVED 1 PFA ACTIVATION AND FROM	I CALL
21:18:48	PREMISE ADV CONFIRMED FIRE DID NOT SAY WHERE	
21:19:03	Unit BALM611 [K77 : NOTHING SHOWING]	
21:19:33	Unit AUCK206 [K1 : PROCEEDING TO INCIDENT]	
21:19:51	Unit PARN251 [K2 : IN ATTENDANCE AT INCIDENT]	
21:20:12	Unit GREY261 [K2 : IN ATTENDANCE AT INCIDENT]	
21:20:29	Unit BALM611 [COMCEN COM : MESSAGE] FYI ACCESS NUMBER IS CHARLIE	
21:21:24	Unit BALM611 [KC : UNIT CALLING]	
21:21:59	Unit BALM611 [SITREP :] SO GRIFFIN IPS FIRE LVL 10 AND 11 REPORT OF FIRE RO	OOM
21:21:59	54 LEVEL 11 TRANSMIT 2ND ALARM	
21:22:20	INC INFO: CONIRMED FIRE TXT 2ND ALARM	
21:22:30	** Alarm level updated to 2	
21:22:30	** Recommended unit PARN255 for requirement AERIAL (>1.2 km)	
21:22:30	** Recommended unit AUCK2018 for requirement COMU (>1.4 km)	
21:22:30	** Recommended unit REMU211 for requirement PUMP (>3.5 km)	
21:22:30	** Recommended unit ELLE274 for requirement PUMP (>6.5 km)	
21:22:46	Unit BALM6117 [K2 : IN ATTENDANCE AT INCIDENT]	
21:22:55	Unit AUCK206 [K2 : IN ATTENDANCE AT INCIDENT]	
21:23:13	POL/AMB FROM FIRE; 2ND ALARM @ PULLMAN HOTEL	
21:23:26	AMBO EVENT 0849-1-2017/08/29-FIR LINKED AT 29/08/2017 21:23:26	
21:23:48	Unit REMU211 [K1 : PROCEEDING TO INCIDENT]	
21:23:52	Unit PARN255 [K1 : PROCEEDING TO INCIDENT]	
21:23:56	Unit AUCK2018 [K1 : PROCEEDING TO INCIDENT]	
21:24:01	NOPT OSU AUCKLAND PAGED	
21:24:25	Unit ELLE274 [K1 : PROCEEDING TO INCIDENT]	
21:26:33	Unit PARN255 [K2 : IN ATTENDANCE AT INCIDENT]	
21:26:53	Unit AUCK207 [K1 : PROCEEDING TO INCIDENT]	
21:27:03	Unit AUCK2018 [K39 : RE-TRANSMIT YOUR CURRENT STATUS] WHEN READY	
21:27:15	Unit ELLE274 [KC : UNIT CALLING]	
1	1	ı

SMS Incident Report	F2370744	5/11	05/09/2017 08:14:40	
21:27:34	CORRECTION TO	O ABOVE, AUCK207 K39 WHEN READY		
21:27:56	Unit ELLE274 [SI	Unit ELLE274 [SITREP :] DELAYED RESPONSE DUE TO PENROSE INTERCHANGE ON-RAMP		
21:27:56	CLOSED PROCE	CLOSED PROCEEDING TO GREENLANE ON RAMP		
21:28:08	Unit AUCKOSU2	Unit AUCKOSU2 [K1 : PROCEEDING TO INCIDENT]		
21:28:22	Unit AUCKOSU2	[K38 : ASSOCIATE THIS UNIT TO EVENT - EVE	ENT ADDRESS]	
21:28:26	Unit AUCKOSU2	[K39 : RE-TRANSMIT YOUR CURRENT STATU	S]	
21:28:48	Unit AUCKCITY2	[K1 : PROCEEDING TO INCIDENT]	×	
21:29:19	Unit AUCK207 [Co	OMCEN COM : MESSAGE] BE ADV ETA FOR V	ECTOR IS 30 MIN @ 2129	
21:30:11	Unit AUCK2018 [K2 : IN ATTENDANCE AT INCIDENT]		
21:30:18	Unit AUCK207 [K	2 : IN ATTENDANCE AT INCIDENT]		
21:30:25	Unit AUCKOSU2	[K1 : PROCEEDING TO INCIDENT]	.:.0	
21:31:35	Unit REMU211 [k	(2 : IN ATTENDANCE AT INCIDENT]		
21:32:22	COVERING UNIT	ONEH221 DISPATCHED TO STATION ELLERS	SLIE	
21:32:22	D0710063	<		
21:33:08	COVERING UNIT	AVON607 DISPATCHED TO STATION AUCKLA	AND	
21:33:08	TERMINAL: D071	0063		
21:34:23	Unit ELLE274 [K2	2 : IN ATTENDANCE AT INCIDENT]		
21:37:56	Unit AUCK2018 [KC : UNIT CALLING]		
21:38:58	Unit AUCK2018 [K44 : COMMAND OR CONTROL POINT ESTAB	LISHED - OIC AND LOCATION]	
21:38:58	PRINCES COMM	AND SSO DEVOE		
21:39:45	Unit AUCK2018 [KC : UNIT CALLING]		
21:40:13	Unit AUCK2018 [SITREP :] SSO DEVOE PULLMAN HOTEL HEA	VY SMOKE LOG ON LVL 11	
21:40:13	CREWS INV	/06		
21:46:11	Unit AUCKOSU2	[K2 : IN ATTENDANCE AT INCIDENT]		
21:48:39	Duplicate Event:L	ocation = UNKN0001 WATERLOO QUAD,AUCKI	LAND CENTRAL,AUCKLAND:	
21:48:39	INC INFO: CALLE	R CAN SEE THE FIRE ON THE OUTSIDE		
21:48:39	@PULLMAN HOT	EL AUCKLAND, Type = STRU - STRUCTURE F	IRE, Caller Ph Number =	
21:48:39	1021621948, Call	Source = 111Inc InfoCALLER CAN SEE THE FIF	RE ON THE OUTSIDE ,	
21:48:39	Event Source = Fi	re 111		
21:48:39	End of Duplicate E	Event data		
21:49:09	CALLER LOOKIN	G ACROSS AT BUILDING CAN SEE FIREMEN I	N THE ROOM BUT ITS COMING	
21:49:09	FROM THE ROOI	M BELOW		
21:50:54	Unit AUCK2018 [K2 : IN ATTENDANCE AT INCIDENT]		
21:51:45	Unit AUCK2018 [0	COMCEN COM : MESSAGE] FURTHER INFO PA	ASSED - CALLER CAN SEE FIRE	
21:51:45	ON THE LEVEL B	BELOW WHERE THE FIREFIGTERS ARE WORK	KING - NOONE IS ON THAT LEVEL	
21:51:54	Unit AUCK2018 [KP : PRIORITY MESSAGE]		
21:52:16	Unit AUCK2018 [KP : PRIORITY MESSAGE] TXT 3RD ALAM		
21:52:24	POL/AMB FROM	FIRE; NOW 3RD ALARM		
21:52:24	INC INFO: CONIR	RMED FIRE TXT 3RD ALARM		
21:52:53	** Alarm level upd	ated to 3		

SWS incident Report	F2370744 6/11 05/09/2017 08:14:40
21:52:53	** Recommended unit TEAT664 for requirement AERIAL (>10.8 km)
21:52:53	** Recommended unit PAPA344 for requirement AERIAL (>17.9 km)
21:52:53	** Recommended unit AVON6015 for requirement BAT (>8.2 km)
21:52:53	** Recommended unit AUCKOSU4 for requirement CANT (>11.9 km)
21:52:53	** Recommended unit AVON607 for requirement PUMP (>1.4 km)
21:52:53	** Recommended unit ONEH221 for requirement PUMP (>6.5 km)
21:53:54	Unit AVON607 [K1 : PROCEEDING TO INCIDENT]
21:53:57	Unit MTRO621 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
21:54:59	Unit ONEH221 [K1 : PROCEEDING TO INCIDENT]
21:55:08	Unit PAPA344 [K1 : PROCEEDING TO INCIDENT]
21:55:12	Unit TEAT664 [K1 : PROCEEDING TO INCIDENT]
21:56:27	AL: PAGING ACK TIMED OUT FOR STATION: 1466 at 29/08/17 21:56:27
21:56:50	Unit GLEN641 [K1 : PROCEEDING TO INCIDENT]
21:57:29	Unit AVON607 [K2 : IN ATTENDANCE AT INCIDENT]
21:59:30	Unit AUCK2018 [KC : UNIT CALLING]
21:59:39	Unit AUCK2018 [KC : UNIT CALLING]
21:59:42	Unit AUCKOSU4 [K1 : PROCEEDING TO INCIDENT]
21:59:48	Unit AUCK2018 [KC : UNIT CALLING]
22:00:21	Unit AUCKOSU4 [K1 : PROCEEDING TO INCIDENT]
22:00:35	Unit AUCK2018 [SITREP :] CONFIRMED FIRE ON LVL 11 2ND SMOKE LOGGING ON LVL 10
22:00:35	AND 12 1 LPD FROM RISER MAIN IN USE FIRE PERSONNEL INV UPPER LEVELS FOR SMOKE
22:00:35	SPREAD CAN YOU ADV ALL RESPONDING APPLIANCES THE COMMAND UNIT IS ON CNR BOWEN
22:00:35	AND PRINCESS
22:01:25	Unit AUCK2018 [COMCEN COM : MESSAGE] ALL 3RD ALARM APPLIANCES RESPONDING, DID
22:01:25	YOU COPY?
22:01:56	Unit ONEH221 [SITREP :] COPY
22:01:56	Unit TEAT664 [SITREP :] COPY
22:01:56	Unit GLEN641 [SITREP :] COPY
22:01:57	Unit PAPA344 [SITREP :] COPY
22:02:28	Unit ONEH221 [K2 : IN ATTENDANCE AT INCIDENT]
22:03:13	Unit GLEN641 [KC : UNIT CALLING]
22:03:34	Unit AUCK2018 [KC : UNIT CALLING]
22:03:46	Unit GLEN641 [SITREP :] CAN YOU ACTIVATE AVONDALES GENERAL ALARM
22:03:49	Unit AUCK2018 [KC : UNIT CALLING]
22:04:24	Unit AUCK2018 [K44 : COMMAND OR CONTROL POINT ESTABLISHED - OIC AND LOCATION]
22:04:24	AAC WOON
22:04:27	Unit AUCKCITY4 [K1 : PROCEEDING TO INCIDENT]
22:05:34	Unit GLEN641 [COMCEN COM : MESSAGE] [BELLS PUT DOWN AT AVONDALE STATION FOR
22:05:34	TEAT644 TO UPLIFT AVON6015] WAS THAT SUCCESSFUL?

SWS incident Report	F2370744 //TI	05/09/2017 08:14:40
22:05:45	Unit GLEN641 [SITREP :] AFFIRM	
22:06:43	Unit AVON6015 [K1 : PROCEEDING TO INCIDENT]	
22:06:57	Unit WAITEMATA1 [K1 : PROCEEDING TO INCIDENT]	
22:07:03	Unit TEAT664 [K2 : IN ATTENDANCE AT INCIDENT]	
22:09:03	Unit GLEN641 [KP : PRIORITY MESSAGE]	
22:09:03	COVERING UNIT TEAT662 DISPATCHED TO STATION TE ATATU AT	
22:09:03	D0710063	×
22:09:09	Unit AUCKCITY4 [K2 : IN ATTENDANCE AT INCIDENT]	
22:09:35	Unit GLEN641 [KP : PRIORITY MESSAGE] DISREGARD	
22:11:50	Unit AUCKOSU4 [K2 : IN ATTENDANCE AT INCIDENT]	
22:11:50	COVERING UNIT MTWE237 DISPATCHED TO STATION ELLERSLIE	
22:11:50	D0710063	
22:12:22	Unit PAPA344 [K2 : IN ATTENDANCE AT INCIDENT]	
22:12:34	COVERING UNIT BIRK821 DISPATCHED TO STATION AUCKLAND	
22:12:34	TERMINAL: D0710063	
22:13:40	Duplicate Event:Location = UNKN0001 WATERLOO QUAD,AUCKLAND CENTRA	L,AUCKLAND:
22:13:40	INC INFO: CALLERS WIFE IN ROOM 1122	
22:13:40	@PULLMAN HOTEL AUCKLAND, Type = STRU - STRUCTURE FIRE, Call Sourc	e = 111Inc
22:13:40	InfoCALLERS WIFE IN ROOM 1122	
22:13:40	End of Duplicate Event data	
22:14:31	Unit AUCK2018 [COMCEN COM : MESSAGE] THERE IS A WOMAN IN ROOM 17 GET	122 UNABLE TO
22:14:31	OUT DUE TO ALL THE SMOKE	
22:14:45	Unit AUCK2018 [SITREP :] COPY MESSAGE	
22:15:22	Unit WAITEMATA1 [K2 : IN ATTENDANCE AT INCIDENT]	
22:19:38	Unit AVON6015 [K2 : IN ATTENDANCE AT INCIDENT]	
22:20:23	Unit GLEN641 [K2 : IN ATTENDANCE AT INCIDENT]	
22:27:01	Unit AUCKCITY2 [K2 : IN ATTENDANCE AT INCIDENT]	
22:34:48	Unit WAITEMATA1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
22:39:08	Unit PAPA344 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
22:39:09	Unit TEAT664 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
22:42:45	Unit ONEH221 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
22:45:39	Unit AUCK206 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
22:46:25	Unit AVON607 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
22:46:47	Unit PARN255 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
22:47:41	Unit AUCK2018 [KC : UNIT CALLING]	
22:50:07	Unit AUCK2018 [SITREP :] AAM WOON; THIS IS A BUILDING OF 18 LEVELS, A	APROX 20 X
22:50:07	40 MTRS USED AS A HOTEL. FIRE LOC ATED ON LEVEL 10. FIRE EXTINGUIS	HED USING
22:50:07	DELIVERY FROM RISER MAIN. CURRENTLY IN VENTILATION MODE	
22:53:04	Unit AUCK2018 [KC : UNIT CALLING]	

22:53:12	owio incluent Report 1	0/11	13/03/2017 00.14.40
22.54.18	22:53:12	Unit AUCK2018 [KC : UNIT CALLING]	
22:59:13	22:53:40	Unit AUCK2018 [K11F : FIRE SAFETY REQUIRED]	
23.01:56	22:54:18	INC INFO: 3RD ALARM, TOC 2114 TOA 2119	
23.02:21	22:59:13	Unit AUCK2018 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SS	O DEVOE
23:02:56	23:01:56	Unit REMU211 [KC : UNIT CALLING]	
23:08:54	23:02:21	Unit REMU211 [K10 : RECOMMISSIONING]	
23:16:38	23:02:56	Unit ELLE274 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	*
23:16:46	23:08:54	Unit FIWAITEM3 [K1 : PROCEEDING TO INCIDENT]	
23:17:15	23:16:38	Unit AUCK2018 [KC : UNIT CALLING]	
23:17:15	23:16:46	Unit AUCK2018 [KC : UNIT CALLING]	
23:17:15 DISTABLISHING FROM INCIDENT SSO DEVOE CITY207 23:25:44 Unit AUCKCITY2 [K6 : ON TELEPAGER] 23:26:11 Unit AUCK2018 [KC : UNIT CALLING] 23:27:13 Unit AUCK2018 [SITREP :] ETA FOR THE FI WAITEM3 23:27:26 Unit FIWAITEM3 [SITREP :] APPROX 3 MIN 23:27:31 Unit AUCK2018 [SITREP :] APPROX 3 MIN 23:29:23 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] 23:34:36 Unit BALM6117 [KC : UNIT CALLING] 23:35:36 Unit BALM6117 [KC : UNIT CALLING] 23:35:33 Unit BALM6117 [KC : UNIT CALLING] 23:35:34 Unit BALM6117 [KC : UNIT CALLING] 23:35:48 Unit BALM611 [KC : UNIT CALLING] 23:36:49 Unit AUCK2018 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:41:26 Unit AUCK0015 [K7 : AT NORMAL STATION] 23:42:10 Unit AUCK0014 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:44:56 Unit AUCK0014 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:44:56 Unit AUCK0014 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:03:31 Unit AUCK0012 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:04:01 Unit AUCK007 [K6 : UNIT CALLING] 00:04:01 Unit AUCK207 [K6 : UNIT CALLING] 00:05:45 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:05:45 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:26:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:25:56 UNIT BURM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO 01:26	23:17:15	Unit AUCKCITY4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
23:25:44	23:17:15	Unit AUCK2018 [K44 : COMMAND OR CONTROL POINT ESTABLISHED - OIC A	ND LOCATION]
23:26:11 23:27:13 Unit AUCK2018 [KC: UNIT CALLING] Unit AUCK2018 [SITREP:] ETA FOR THE FI WAITEM3 23:27:26 Unit FIWAITEM3 [SITREP:] APPROX 3 MIN Unit AUCK2018 [SITREP:] COPIED 23:29:23 Unit FIWAITEM3 [K2: IN ATTENDANCE AT INCIDENT] 23:34:36 Unit BALM6117 [K2: IN ATTENDANCE AT INCIDENT] 23:35:16 Unit BALM6117 [KC: UNIT CALLING] Unit BALM6117 [KC: UNIT CALLING] 23:35:34 Unit BALM611 [KC: UNIT CALLING] 23:35:34 Unit BALM611 [KC: UNIT CALLING] 23:35:48 Unit BALM611 [KC: UNIT CALLING] 23:36:49 Unit AUCK2018 [K4: ON RT INSIDE NORMAL TURNOUT AREA] 23:41:26 Unit AVON8015 [K7: AT NORMAL STATION] Unit GLEN641 [K3: ON RT OUTSIDE NORMAL TURNOUT AREA] 23:44:56 Unit AUCK2018 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCKOSU4 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [KC: UNIT CALLING] 00:04:01 Unit AUCK207 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4: ON RT INSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4: ON RT INSIDE NORMAL TURNOUT AREA] UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO	23:17:15	DISTABLISHING FROM INCIDENT SSO DEVOE CITY207	
23:27:13 Unit AUCK2018 [SITREP :] ETA FOR THE FI WAITEM3 23:27:26 Unit FIWAITEM3 [SITREP :] APPROX 3 MIN Unit AUCK2018 [SITREP :] COPIED 23:29:23 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] 23:34:36 Unit BALM6117 [K2 : IN ATTENDANCE AT INCIDENT] 23:35:16 Unit BALM6117 [KC : UNIT CALLING] 23:35:34 Unit BALM6117 [K10 : RECOMMISSIONING] 23:35:34 Unit BALM611 [K10 : RECOMMISSIONING] 23:35:48 Unit BALM611 [K10 : RECOMMISSIONING] 23:38:49 Unit AVON6015 [K7 : AT NORMAL TURNOUT AREA] 23:41:26 Unit AVON6015 [K7 : AT NORMAL STATION] 23:42:10 Unit GLEN641 [K3 : ON RT INSIDE NORMAL TURNOUT AREA] 23:44:56 Unit AUCK2018 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:58:46 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K7 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] HANDED 00:04:01 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit BALM6117 RESPONSE TIME [NULL] ADJUSTED TO UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO	23:25:44	Unit AUCKCITY2 [K6 : ON TELEPAGER]	
23:27:26	23:26:11	Unit AUCK2018 [KC : UNIT CALLING]	
23:27:31 Unit AUCK2018 [SITREP :] COPIED 23:29:23 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] 23:34:36 Unit BALM6117 [K2 : IN ATTENDANCE AT INCIDENT] 23:35:16 Unit BALM6117 [KC : UNIT CALLING] 23:35:33 Unit BALM6117 [K10 : RECOMMISSIONING] 23:35:34 Unit BALM611 [K10 : RECOMMISSIONING] 23:35:48 Unit BALM611 [K10 : RECOMMISSIONING] 23:38:49 Unit AUCK2018 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:41:26 Unit AVON6015 [K7 : AT NORMAL STATION] 23:42:10 Unit GLEN641 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 23:44:56 Unit AUCKOSU4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 20:03:31 Unit AUCKOSU2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:03:31 Unit AUCK207 [KC : UNIT CALLING] 00:04:01 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:04:01 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:05:45 Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT INSIDE NORMAL TURNOUT AREA] 01:25:56 Unit BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:25:56	23:27:13	Unit AUCK2018 [SITREP :] ETA FOR THE FI WAITEM3	
23:29:23 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] 23:34:36 Unit BALM6117 [K2 : IN ATTENDANCE AT INCIDENT] 23:35:16 Unit BALM6117 [KC : UNIT CALLING] 23:35:33 Unit BALM6117 [K10 : RECOMMISSIONING] 23:35:34 Unit BALM611 [K10 : RECOMMISSIONING] 23:35:48 Unit BALM611 [K10 : RECOMMISSIONING] 23:38:49 Unit AUCK2018 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:41:26 Unit AVON6015 [K7 : AT NORMAL STATION] 23:42:10 Unit GLEN641 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 23:45:6 Unit AUCKOSU4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 20:03:31 Unit AUCK207 [KC : UNIT CALLING] 00:04:01 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:04:01 BACK TO HOTEL MANAGEMENT 00:04:04 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:05:45 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:20:18 Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	23:27:26	Unit FIWAITEM3 [SITREP :] APPROX 3 MIN	
23:34:36 Unit BALM6117 [K2 : IN ATTENDANCE AT INCIDENT] 23:35:16 Unit BALM6117 [KC : UNIT CALLING] 23:35:33 Unit BALM6117 [K10 : RECOMMISSIONING] 23:35:34 Unit BALM611 [K10 : RECOMMISSIONING] 23:35:48 Unit BALM611 [K10 : RECOMMISSIONING] 23:38:49 Unit AUCK2018 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:41:26 Unit AVON6015 [K7 : AT NORMAL STATION] 23:42:10 Unit GLEN641 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 23:44:56 Unit AUCKOSU4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:03:31 Unit AUCKOSU2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:04:01 Unit AUCK207 [KC : UNIT CALLING] 00:04:01 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:05:45 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:05:45 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:20:18 Unit GREY261 [K3 : ON RT INSIDE NORMAL TURNOUT AREA] 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	23:27:31	Unit AUCK2018 [SITREP :] COPIED	
23:35:16 Unit BALM6117 [KC : UNIT CALLING] 23:35:33 Unit BALM6117 [K10 : RECOMMISSIONING] 23:35:34 Unit BALM611 [KC : UNIT CALLING] 23:35:48 Unit BALM611 [K10 : RECOMMISSIONING] 23:38:49 Unit AUCK2018 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:41:26 Unit AVON6015 [K7 : AT NORMAL STATION] 23:42:10 Unit GLEN641 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 23:44:56 Unit AUCKOSU4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:58:46 Unit AUCKOSU2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:03:31 Unit AUCK207 [KC : UNIT CALLING] 00:04:01 Unit AUCK207 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] HANDED 00:04:01 BACK TO HOTEL MANAGEMENT 00:04:04 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT INSIDE NORMAL TURNOUT AREA] 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	23:29:23	Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT]	
23:35:33 Unit BALM6117 [K10 : RECOMMISSIONING] 23:35:34 Unit BALM611 [KC : UNIT CALLING] 23:35:48 Unit BALM611 [K10 : RECOMMISSIONING] 23:38:49 Unit AUCK2018 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:41:26 Unit AVON6015 [K7 : AT NORMAL STATION] 23:42:10 Unit GLEN641 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 23:44:56 Unit AUCKOSU4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:58:46 Unit AUCKOSU2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:03:31 Unit AUCK207 [KC : UNIT CALLING] 00:04:01 Unit AUCK207 [K7 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] HANDED 00:04:01 BACK TO HOTEL MANAGEMENT 00:04:04 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:05:45 Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:20:18 Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO	23:34:36	Unit BALM6117 [K2 : IN ATTENDANCE AT INCIDENT]	
23:35:34 Unit BALM611 [KC : UNIT CALLING] 23:35:48 Unit BALM611 [K10 : RECOMMISSIONING] 23:38:49 Unit AUCK2018 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:41:26 Unit AVON6015 [K7 : AT NORMAL STATION] 23:42:10 Unit GLEN641 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 23:44:56 Unit AUCKOSU4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:58:46 Unit AUCKOSU2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:03:31 Unit AUCK207 [KC : UNIT CALLING] 00:04:01 Unit AUCK207 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] HANDED 00:04:01 BACK TO HOTEL MANAGEMENT 00:04:04 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:05:45 Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:20:18 Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	23:35:16	Unit BALM6117 [KC : UNIT CALLING]	
23:35:48 Unit BALM611 [K10 : RECOMMISSIONING] 23:38:49 Unit AUCK2018 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:41:26 Unit AVON6015 [K7 : AT NORMAL STATION] 23:42:10 Unit GLEN641 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 23:44:56 Unit AUCKOSU4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:58:46 Unit AUCKOSU2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:03:31 Unit AUCK207 [KC : UNIT CALLING] 00:04:01 Unit AUCK207 [K4 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] HANDED 00:04:01 BACK TO HOTEL MANAGEMENT 00:04:04 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:05:45 Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:20:18 Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	23:35:33	Unit BALM6117 [K10 : RECOMMISSIONING]	
23:38:49 Unit AUCK2018 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:41:26 Unit AVON6015 [K7 : AT NORMAL STATION] 23:42:10 Unit GLEN641 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 23:44:56 Unit AUCKOSU4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:03:31 Unit AUCK207 [KC : UNIT CALLING] 00:04:01 Unit AUCK207 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] HANDED 00:04:01 BACK TO HOTEL MANAGEMENT 00:04:04 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:05:45 Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:20:18 Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	23:35:34	Unit BALM611 [KC : UNIT CALLING]	
23:41:26 Unit AVON6015 [K7 : AT NORMAL STATION] 23:42:10 Unit GLEN641 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 23:44:56 Unit AUCKOSU4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:58:46 Unit AUCK207 [KC : UNIT CALLING] 00:03:31 Unit AUCK207 [KC : UNIT CALLING] 00:04:01 Unit AUCK207 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] HANDED 00:04:01 BACK TO HOTEL MANAGEMENT 00:04:04 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:05:45 Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:20:18 Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	23:35:48	Unit BALM611 [K10 : RECOMMISSIONING]	
23:42:10 Unit GLEN641 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 23:44:56 Unit AUCKOSU4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:58:46 Unit AUCKOSU2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:03:31 Unit AUCK207 [KC : UNIT CALLING] 00:04:01 Unit AUCK207 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] HANDED 00:04:01 BACK TO HOTEL MANAGEMENT 00:04:04 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:05:45 Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:20:18 Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	23:38:49	Unit AUCK2018 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
23:44:56 Unit AUCKOSU4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 23:58:46 Unit AUCKOSU2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:03:31 Unit AUCK207 [KC : UNIT CALLING] 00:04:01 Unit AUCK207 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] HANDED 00:04:01 BACK TO HOTEL MANAGEMENT 00:04:04 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:05:45 Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:20:18 Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	23:41:26	Unit AVON6015 [K7 : AT NORMAL STATION]	
23:58:46 Unit AUCKOSU2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:03:31 Unit AUCK207 [KC : UNIT CALLING] 00:04:01 Unit AUCK207 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] HANDED 00:04:01 BACK TO HOTEL MANAGEMENT 00:04:04 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 00:05:45 Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:20:18 Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	23:42:10	Unit GLEN641 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
00:03:31 00:04:01 00:04:01 00:04:01 Dnit AUCK207 [KC : UNIT CALLING] Unit AUCK207 [K47 : STOP MESSAGE : MESSAGE UNCHANGED FROM INFORMATIVE] HANDED 00:04:01 BACK TO HOTEL MANAGEMENT Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	23:44:56	Unit AUCKOSU4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
00:04:01 Unit AUCK207 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] HANDED 00:04:01 BACK TO HOTEL MANAGEMENT Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	23:58:46	Unit AUCKOSU2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
00:04:01 00:04:04 Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	00:03:31	Unit AUCK207 [KC : UNIT CALLING]	
Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	00:04:01	Unit AUCK207 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFOR	MATIVE] HANDED
00:05:45 Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:20:18 Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	00:04:01	BACK TO HOTEL MANAGEMENT	
00:07:37 Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] 00:20:18 Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	00:04:04	Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
00:20:18 Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	00:05:45	Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	00:07:37	Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
01:25:56 UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO 01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	00:20:18	Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
01:26:08 UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	01:25:56	UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO	
	01:25:56	UNIT BALM6117 RESPONSE TIME [NULL] ADJUSTED TO	
01:26:08	01:26:08	UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO	
	01:26:08	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,	

01:26:08	Qualifier 2:
01:26:09	UNIT BALM6117 ALERT TIME [NULL] ADJUSTED TO
01:26:09	UNIT BALM6117 ALERT TIME [NULL] ADJUSTED TO

Incident

CAD NumberF2370744Incident ReporterMark GriffinIncident ControllerS.O Griffin

Distance Travelled (km) 2

Delay In Receiving Call

Property Details

Occupant Pullman Hotel
Building Owner Occupied

General Property Use Hotel, Motel, Lodge, Timeshare

Special Property Use Hotel, Motel, Lodge: Without liquor licence

Purpose Group

Actions

Persons Reported Trapped No

Evacuation Status Evacuation in progress

Action Prior 1
Action Prior 2

Action Taken Extinguishment, salvage and ventilation

Civilians

Civilians Rescued

Civilians Extricated

Civilians Assisted

0

Civilians Evacuated

Origin

Location Ceiling and roof assembly

Level 5th - 10th floor

Equipment Used

Quantity	Equipment
2	Fixed installations for Fire Service use
1	Thermal Imaging Camera

SMS Incident Report	F2370744	10/11	05/09/2017 08:14:40
---------------------	----------	-------	---------------------

2	Ladder
1	Hand tools - Crowbar, Saw, Hammer, Mop, Broom, Misc small gear
1	Lighting/lights/lighting apparatus
6	BA set
1	Dry/Wet vacuum eg. Aquavac
10	Handheld Radio (or Cellphone)

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition Small fire

Heat Source Heat from electrical equipment: Defective or

faulty

Termination Stage Flame

First Object Ignited Electronic componentry

First Object Material PVC eg. Floor Tiles, Guttering/Pipes, Plastic

Bags, Elec. Insulation

Second Object Ignited Ceiling coverings

Second Object Material Wood: sawn, finished timber

Indicated Cause Other electrical failure

Certainty of Cause High

Age of PersonNo person involvedEthnicityNo person involved

Gender

FAIP Service Offered No FAIP Service Accepted No

Alarms

Type of Alarm Initiating Call Smoke Detector System (Monitored)

Performance of System Alerted occupants - detector in room of origin

Failure/Ineffectiveness of

system

Number of sprinkler heads

operated

Structure

Area of One Floor 800

0

Age of Building 1946 - 1969

Structural Frame Type Reinforced concrete with non-combustible cladding

SMS Incident Report F2370744	11/11	05/09/2017 08:14:40
Number of Floors		15
Number of Basements		3
Internal Wall Lining	Gypsum board (e.g. Gib board, Elephant board)	
Ceiling Lining	Gypsum board (e.g. Gib board, Elephant board)	
Material Generating Most Flame	Wood: Sawn, Finished timber	
Material Generating Most Smoke	PVC	
Avenue of Flame Travel	Failure of rated assembly	×
Avenue of Smoke Travel	Service shaft, pipe shaft	
Extent of Flame Damage	Confined to room of origin	
Area of Flame Damage		16
Extent of Smoke Damage	Confined to structure of origin	.:.0
Area of Smoke Damage		1200
Extent of Water Damage	Confined to structure of origin	0.
Area of Water Damage		150
Extent of Fire Control Damage	No damage of this type	
Area of Fire Control Damage		0

Comments

9/4/2017 4:22:31 PM

Reporter Comments

Fire above ceiling and below upper floor on level 10 caused by electrical malfunction of air conditioning unit above apartment bathroom ceiling igniting timber framing.

Mark Griffin