SMS Incident Report

10/01/2018 08:47:58

Summary

CAD Number F2431984 Status Closed

Station Ashburton Volunteer Fire Brigade

Incident Started 04/12/2017 19:39:43 Incident Ended 06/12/2017 10:18:16

Incident Type 1101: Structure fire with damage

Common Name SEALES WINSLOW SOUTH ISLAND

Address / 605 Hinds Highway Winslow

Alarm Method 111 Telephone Alarm Level 3

PFA Number

Zone 346230

 Map Grid E
 1491734
 Map Grid N 5131890

First Caller


Incident Closed 06/12/2017 15:14:10

Report Completed 12:37, Wed 27 Dec 2017 by

Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
WILL9911	WT	19:43:23 04 Dec 2017	19:47:21 04 Dec 2017	19:52:31 04 Dec 2017	07:34:33 05 Dec 2017
ASHB621	P1	19:43:26 04 Dec 2017	19:46:54 04 Dec 2017	19:53:45 04 Dec 2017	00:15:26 05 Dec 2017
HIND9371	RP	19:41:14 04 Dec 2017	19:47:05 04 Dec 2017	19:55:16 04 Dec 2017	01:20:08 05 Dec 2017
ASHB622	P2	19:41:16 04 Dec 2017	19:48:44 04 Dec 2017	19:55:44 04 Dec 2017	10:18:41 06 Dec 2017
ASHB6211	WT	19:51:26 04 Dec 2017	19:51:26 04 Dec 2017	20:02:56 04 Dec 2017	09:52:03 05 Dec 2017
ASHB627	PR 🕜	19:55:07 04 Dec 2017	19:57:41 04 Dec 2017	20:05:20 04 Dec 2017	23:41:48 04 Dec 2017
ASHB9011	WT	19:53:48 04 Dec 2017	19:55:50 04 Dec 2017	20:05:24 04 Dec 2017	01:43:00 05 Dec 2017
ASHB6229	sv	20:03:46 04 Dec 2017	20:03:46 04 Dec 2017	20:12:16 04 Dec 2017	03:47:50 05 Dec 2017
RURALSCRF5	RFO	19:43:44 04 Dec 2017	20:06:16 04 Dec 2017	20:19:14 04 Dec 2017	01:59:54 05 Dec 2017
MAYF9411	WT	19:55:04 04 Dec 2017	19:59:14 04 Dec 2017	20:21:14 04 Dec 2017	22:48:45 04 Dec 2017
GERA841	P1	19:57:13 04 Dec 2017	20:00:36 04 Dec 2017	20:26:29 04 Dec 2017	01:09:32 05 Dec 2017
RAKA6411	WT	19:57:10 04 Dec 2017	20:02:44 04 Dec 2017	20:31:29 04 Dec 2017	02:06:26 05 Dec 2017
SOUTHCANT2	OF	19:59:16 04 Dec 2017	20:01:03 04 Dec 2017	20:37:09 04 Dec 2017	18:49:56 05 Dec 2017
TEMU861	P1	20:09:50 04 Dec 2017	20:13:34 04 Dec 2017	20:40:16 04 Dec 2017	22:29:37 05 Dec 2017
GERA847	PR	20:09:48 04 Dec 2017	20:13:08 04 Dec 2017	20:42:22 04 Dec 2017	00:09:15 05 Dec 2017
TIMA804	PM	19:58:36 04 Dec 2017	19:59:24 04 Dec 2017	20:43:21 04 Dec 2017	01:46:05 05 Dec 2017

First Caller Contact



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
WILL9911	00:03:40	00:09:08	00:12:48	11:54:50
ASHB621	00:03:43	00:10:19	00:14:02	04:35:43
HIND9371	00:01:31	00:14:02	00:15:33	05:40:25
ASHB622	00:01:33	00:14:28	00:16:01	38:38:58
ASHB6211	00:11:43	00:11:30	00:23:13	14:12:20
ASHB627	00:15:24	00:10:13	00:25:37	04:02:05
ASHB9011	00:14:05	00:11:36	00:25:41	06:03:17
ASHB6229	00:24:03	00:08:30	00:32:33	08:08:07
RURALSCRF5	00:04:01	00:35:30	00:39:31	06:20:11
MAYF9411	00:15:21	00:26:10	00:41:31	03:09:02
GERA841	00:17:30	00:29:16	00:46:46	05:29:49
RAKA6411	00:17:27	00:34:19	00:51:46	06:26:43

SMS Incident Report F2	431984	3/21		10/01/2018 08:47:58
SOUTHCANT2	00:19:33	00:37:53	00:57:26	23:10:13
TEMU861	00:30:07	00:30:26	01:00:33	26:49:54
GERA847	00:30:05	00:32:34	01:02:39	04:29:32
TIMA804	00:18:53	00:44:45	01:03:38	06:06:22
HIND9311	00:03:37	01:00:14	01:03:51	08:31:32
PEND8911	00:32:39	00:33:55	01:06:34	06:52:31
TIMA8029	00:36:10	00:43:59	01:20:09	06:41:36
TIMA8018	00:17:40	01:08:17	01:25:57	11:33:58
RANG5111	00:31:44	00:59:21	01:31:05	06:12:22
CANTERBRY1	00:53:30	00:49:18	01:42:48	04:36:24
TEMU8629	01:15:06	01:04:55	02:20:01	02:55:45
VSOSTHCAN2	03:04:53	00:09:46	03:14:39	08:09:33
TIMA802	02:20:31	00:59:53	03:20:24	38:21:36
CHRI2129	02:46:06	01:49:46	04:35:52	08:37:33
SOUTHCANT1	03:04:53	02:11:40	05:16:33	09:33:51
TIMA801	03:04:53	04:13:45	07:18:38	13:57:14
SPRE221	03:04:53	04:35:39	07:40:32	13:18:57
CANTERBRY2	03:04:53	05:52:01	08:56:54	14:14:31
FISTHCANT1	11:51:42	00:34:22	12:26:04	43:30:52
VSOSTHCAN1	12:27:54	02:41:13	15:09:07	17:35:31
EVENTSCC1		()		38:58:53
CHRISTCH4		01		12:37:23
WASH817				00:26:01

Notifications

Date	Time	Party Notified
04 Dec 2017	19:45:36	RFO SOUTH CANTY DON GEDDES ACK PAGE
04 Dec 2017	19:50:25	ELECTRICITY ASHBURTON
04 Dec 2017	19:51:25	ETA POWER 10-15 MINS @ 1950HRS
04 Dec 2017	19:54:39	PAGED CFO ASHBURTON/VSO STH CANTY RE K99
04 Dec 2017	19:55:47	PAGED AREA SOUTH CANTERBURY
04 Dec 2017	19:56:45	PAGED RFO SOUTH CANTY K99/2ND ALARM
04 Dec 2017	19:58:40	AAC JOHNS ACK PAGE - RESPONDING
04 Dec 2017	20:00:53	RFO STH CANTY DON GEDDES ACK PAGE RESPONDING
04 Dec 2017	20:02:17	MIKE JOHNS CALLS IN TO GET WASHDYKE CREW TO PICK UP COMMAND UNIT BEFORE
04 Dec 2017	20:02:30	PAGED TIMARU AVAILABILITY
04 Dec 2017	20:04:40	PAGED REGION 4
04 Dec 2017	20:06:55	REGION 4 PAUL HENDERSON ACK PAGE
04 Dec 2017	20:13:45	PAGED REGION 4 RE 4TH ALARM

SMS Incident Report	F2431984	4/21	10/01/2018 08:47:58
04 Dec 2017	20:15:15	PAGED NAT COMCEN MNGR MUNRO	
04 Dec 2017	20:15:23	PAGED CM SOUTHERN PATTERSON	
04 Dec 2017	20:16:16	PAGED NAT COMMANDER GROUP	
04 Dec 2017	20:16:50	REGION 4 PAUL HENDERSON ACK PAGE	
04 Dec 2017	20:17:33	AMB COMS RANG TO CHECK NOTIFICATION ONLY AT T	HIS STAGE -
04 Dec 2017	20:18:34	OPS MNGR MUNRO ACK PAGE	
04 Dec 2017	20:22:33	PHONED MIKE JOHNS - UPDATED	
04 Dec 2017	20:23:14	NCG TREVOR BROWN ACK PAGE	60
04 Dec 2017	20:24:21	AC GREENYER PHONED - FAIRLIE TO COVER GERALDI	NE
04 Dec 2017	20:26:54	REGION 4 PAUL HENDERSON REQUESTS TO SPEAK TO	O AREA CANTY ON CALL
04 Dec 2017	20:27:04	PAGED AREA CANTERBURY	O
04 Dec 2017	20:28:30	AAC STEVE KENNEDY ACK PAGE - TRANSFERRED THE HENDERSON	ROUGH TO FRC
04 Dec 2017	20:33:44	AC BERRY RESPONDING AS 2ND COMMANDER	
04 Dec 2017	20:34:04	PAGED VSO STH CANTY RE 4TH ALARM	
04 Dec 2017	20:40:16	MIKES JOHNS REQUEST TIMARU VAN TO BRING AS MA POSSIBLE - 2	ANY CYLINDERS AS
04 Dec 2017	20:40:42	TIMARU SALVATION ARMY CONTACT FIRST CONTACT	
04 Dec 2017	20:41:59	ADV MIKE JOHNS THAT TIMA8029 IS ENROUTE ALREAD CYLINDERS	OY, HE WILL SORT BA
04 Dec 2017	20:42:52	RUNG MURRAY CAIRNS RE NO CONTACT FROM ON CA	ALL VSO
04 Dec 2017	20:45:55	SALVATION ARMY ASHBURTON IS F	RESPONDING APPROX
04 Dec 2017	20:52:08	VSO STH CAN1 ACK PAGE	
04 Dec 2017	20:55:49	TIMARU STATION ADVISED TEMUKA VAN IS COMING TO	O UPLIFT MORE BA
04 Dec 2017	21:00:32	TEMUKA VAN IS RESPONDING TO TIMARU TO COLLEC' HEADING TO	T CYCLINDERS BEFORE
04 Dec 2017	21:58:32	AAC JOHNS REQUESTS A HEAVY DIGGER AT SCENE	
04 Dec 2017	22:03:06	PAGED RFO SOUTH CANTY TO PHON FIRECOM RE DIG	GER
04 Dec 2017	22:05:14	DPRFO DON GEDDES ACK PAGE - USE STUART TARBO	TTON CONTRACTORS
04 Dec 2017	22:06:27	AMBCOMS RUNG TO CONFIRM RESPONSE ASHB1 RESETA 9MINS	PONDING FROM STN
04 Dec 2017	22:09:32	PHONED STUART TARBOTTON CONTRACTORS - 20 TO TO RESPOND	N DIGGER WITH GRAB
04 Dec 2017	22:16:05	PAGED CFO WAIMATE ON REQUEST OF AC GREENYEF REQUIRED	R - LIGHTING PLANT
04 Dec 2017	22:23:03	CFO WAIMATE CALLS IN UPDATED	
04 Dec 2017	22:24:50	PAGED NATIONAL COMMANDERS GROUP RE INJURIES	3
04 Dec 2017	22:24:59	PAGED REGION 4 DUTY RE INJURIES	
04 Dec 2017	22:25:14	PAGED AREA SOUTH CANTERBURY RE INJURIES	
04 Dec 2017	22:25:33	PAGED NAT COMCEN MANAGER	
04 Dec 2017	22:27:12	PAGED CFO GERALDINE RE INJURY	
04 Dec 2017	22:28:44	DCFO CRAIG CHAMBERS GERALDINE PATCHED TO TIN	MA8018 RE INJURIES

SMS Incident Report	F2431984	5/21	10/01/2018 08:47:58
04 Dec 2017	22:29:26	PAGED HSO REGION 4 (DENIS FITZMAURICE) RE I	NJURIES
04 Dec 2017	22:30:43	TERVOR BROWN RE INJURIES ASKED IF THE FF A DOESNT WANT	RE BEING TRANSPORTED -
04 Dec 2017	22:31:27	FRC REGION 4 PAUL HENDERSON ACK PAGE	
04 Dec 2017	22:34:00	PAGED SPRE221 TO CONTACT FIRECOM	
04 Dec 2017	22:34:02	NAT COMCEN MANAGER ACK PAGED AND UPDAT	ED
04 Dec 2017	22:35:36	PAGED REGION 4 DUTY RE STATUS'S OF	
04 Dec 2017	22:43:12	REGION 4 RMR RICHARD MAC PHONED AND UPDA	ATED
04 Dec 2017	22:43:22	PAUL HENDERSON RANG IN FOR AN UPDATE OF ITHEY ARE BEING	FF - PASSED AND THAT
04 Dec 2017	22:47:36	FI CANTY (KERRI PRING) PAGED TO CONTACT FIR	RE COMS
04 Dec 2017	22:51:14	FI CANTY (KERRI PRING) ACK PAGE - PATCHED TH	HRU TO DAVE BERRY
04 Dec 2017	23:00:09	DCFO CRAIG CHAMBERS RANG BUT NO ANSWER FIRECOMS	MSG LEFT TO CONTACT
05 Dec 2017	00:10:34	PAGED NATIONAL COMMANDER GROUP RE INJUR	RIES
05 Dec 2017	00:10:42	PAGED REGION 4 RE INJURIES	
05 Dec 2017	00:10:50	PAGED AREA SOUTH CANTY RE INJURIES	
05 Dec 2017	00:11:03	PAGED NATIONAL COMCEN MANAGER RE INJURIE	ES
05 Dec 2017	00:12:11	AC STEVEN GEENYER ACK RE INJURIES	
05 Dec 2017	00:14:38	REGION 4 PAUL HENDERSON ACK PAGE	
05 Dec 2017	00:15:31	CHRIS MUNRO ACK PAGE	
05 Dec 2017	00:16:42	NATIONAL COMMANDER GP TREVOR BROWN ACK	(PAGE
05 Dec 2017	00:55:29	NO CONTACT WITH ANY OF THE A/H NUMBERS FO	OR ROONEY CONTRACTING
05 Dec 2017	01:15:47	JEFF FROM DOWNERS IS RESPONDING WITH DIESETA 1 HR	SEL TANKER - 1000 LTRS -
05 Dec 2017	01:28:29	NIWA RE WEATHER FORECAST	
05 Dec 2017	11:26:47	WORKSAFE NEW ZEALAND	
05 Dec 2017	12:12:47	CRAIG CHAMBERS PAGED TO RING FIRECOM RE	WORKSAFE

Message Log

06 Dec 2017

14:42:06

Time	Message
19:41:00	INC INFO: CRATES ON FIRE
19:41:07	** Recommended unit HIND9371 for requirement RPUMP (>7.1 km)
19:41:07	** Recommended unit ASHB622 for requirement PUMP (>10.9 km)
19:41:34	AL: PAGING ACK RECEIVED FROM STATION 3462 at 04/12/17 19:41:34
19:42:27	Duplicate Event:Location = HINDS HWY,WINSLOW,ASHBURTON DISTRICT, Type = STRU -
19:42:27	STRUCTURE FIRE, Caller Ph Number = Call Source = 111Inc InfoCREATES
19:42:27	ON FIRE CLOSE TO BUILDING, Event Source = Fire 111
19:42:28	INC INFO: CREATES ON FIRE CLOSE TO BUILDING
19:42:28	End of Duplicate Event data

FISTHCANT1 WILL BE ANOTHER 30MINS NO FURTHER WELFARE CHECKS REQ

19:43:01	INC INFO: 605 HINSDS HWYCRATES ON FIRE
19:43:01	Duplicate Event: HINDS HWY ASHBURTON DISTRICTCross Street 1WINSLOW WILLOWBY
19:43:01	** LOI search completed at 04/12/17 19:42:02
19:43:01	RDCross Street 2CHATMOS RD, Type = MIN MINOR, Subtype = default, Caller Name =
19:43:01	INC INFO: 605 HINDS HWYCRATES ON FIRE
19:43:01	Caller Ph Number = Caller Address =
19:43:01	Call Source = 111Alarm Level1Inc
19:43:01	Info605 HINDS HWYCRATES ON FIRE, Event Source = Fire 111
19:43:02	End of Duplicate Event data
19:43:02	** Cross Referenced to Event # F2431987 at: 04/12/17 19:43:02
19:43:02	** Event Type changed from MIN to STRU at: 04/12/17 19:43:02
19:43:03	** Event Priority changed from 2 to 1 at: 04/12/17 19:43:03
19:43:12	** Recommended unit HIND9311 for requirement TANKER (>7.1 km)
19:43:12	** Recommended unit WILL9911 for requirement TANKER (>3.9 km)
19:43:12	** Recommended unit ASHB621 for requirement PUMP (>10.9 km)
19:43:12	** Recommended unit RURALSCRF5 for requirement RFO (>10.3 km)
19:43:28	Duplicate Event:Location = HINDS HWY,WINSLOW,ASHBURTON DISTRICT, Type = STRU -
19:43:28	STRUCTURE FIRE, Call Source = 111Inc InfoCRATES ON FIRE
19:43:29	INC INFO: CRATES ON FIRE
19:43:29	End of Duplicate Event data
19:43:44	SEALES WINSLOW SOUTH ISLAND
19:43:47	
19:43:51	AL: PAGING ACK RECEIVED FROM STATION 3462 at 04/12/17 19:43:51
19:43:56	CALLER HADNT STOPPED CONTINUED DRIVING
19:43:58	** Event Location changed from "HINDS HWY,WINSLOW,ASHBURTON DISTRICT" to "605
19:43:58	HINDS HWY, WINSLOW, ASHBURTON DISTRICT: @SEALES WINSLOW SOUTH ISLAND" at: 04/12/17
19:43:58	19:43:58
19:44:51	Unit RURALSCRF5 [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
19:45:23	
19:45:36	T3 CALLER WORKING OUT LOCATION AFTER CARRYING ON
19:45:50	Unit HIND9311 [K1 : PROCEEDING TO INCIDENT]
19:46:50	Duplicate Event:Location = 605 HINDS HWY,WINSLOW,ASHBURTON DISTRICT: @SEALES
19:46:50	WINSLOW SOUTH ISLAND, Type = MIN - MINOR, Caller Ph Number =, Call
19:46:50	Source = 111Inc InfoCREATES ON FIRE, Event Source = Fire 111
19:46:51	INC INFO: CREATES ON FIRE
19:46:51	End of Duplicate Event data
19:46:52	** LOI search completed at 04/12/17 19:46:52
19:46:55	Unit ASHB621 [K1 : PROCEEDING TO INCIDENT]

SWS incident Rep	Ort F2431984	1121	10/01/2018 08:47:58
19:47:06	Unit HIND93	71 [K1 : PROCEEDING TO INCIDENT]	
19:47:15	//RED//		
19:47:22	Unit WILL99	11 [K1 : PROCEEDING TO INCIDENT]	
19:47:59	Unit ASHB62	21 [KC : UNIT CALLING]	
19:48:33	Unit ASHB62	21 [SITREP :] ANY FURTHER INFO	
19:48:43	Unit ASHB62	21 [COMCEN COM : MESSAGE] MULTIPLE CALLS	
19:48:44	Unit ASHB62	22 [K1 : PROCEEDING TO INCIDENT]	*
19:48:51	Unit ASHB62	22 [K1 : PROCEEDING TO INCIDENT]	
19:49:24	Duplicate Ev	ent:Location = HINDS HWY,WINSLOW,ASHBURTON	DISTRICT, Type = STRU -
19:49:24	STRUCTUR	E FIRE, Caller Name = Ca	aller Ph Number =
19:49:24		Caller Address =	
19:49:24	Call Source	= 111Inc InfoCRATES ON FIRE, Event Source = Fire 1	11
19:49:25	INC INFO: C	RATES ON FIRE	.0.
19:49:25	End of Dupli	cate Event data	
19:49:33	CALLER CO	NFIRMS BUILDING IS ON FIRE NOW	
19:49:54	Duplicate Ev	ent:Location = 605 HINDS HWY,WINSLOW,ASHBURT	ON DISTRICT: @SEALES
19:49:54	WINSLOW S	SOUTH ISLAND, Type = STRU - STRUCTURE FIRE, C	aller Name =
19:49:54		Caller Ph Number = Ca	aller Address =
19:49:54		Call	Source = 111Inc InfoFIRE
19:49:54	SEEN, Even	t Source = Fire 111	
19:49:55	INC INFO: F	IRE SEEN	
19:49:55	End of Dupli	cate Event data	
19:50:02	INC INFO: B	UILDING FIRE	
19:50:02	Duplicate Ev	ent:Location = 605 HINDS HWY,WINSLOW,ASHBURT	ON DISTRICT: @SEALES
19:50:02	WINSLOW S	SOUTH ISLAND, Type = STRU - STRUCTURE FIRE, C	aller Name =
19:50:02	, C	aller Ph Number = Caller Address =	
19:50:02		Call Source = 111Inc Int	foBUILDING FIRE , Event
19:50:02	Source = Fir	e 111	
19:50:02	End of Dupli	cate Event data	
19:51:15	5		
19:51:26	Unit ASHB62	211 [K1 : PROCEEDING TO INCIDENT]	
19:52:31	Unit WILL99	11 [K2 : IN ATTENDANCE AT INCIDENT]	
19:52:47	Unit ASHB62	21 [KP : PRIORITY MESSAGE]	
19:52:57	-		
19:53:10	Unit ASHB62	21 [KP : PRIORITY MESSAGE] MAKE TANKER 4 K99	PROCEEDING
19:53:14	FIR2POL - V	VELL INVOLVED BUILDING FIRE ON THE SIDE OF T	HE STATE HWY
19:53:21	** Requireme	ent TORT added for alarm level 1	
19:53:22	Unit HIND93	11 [KP : PRIORITY MESSAGE]	
19:53:29	** Requireme	ent TORT added for alarm level 1	
19:53:34	** Recomme	nded unit ASHB9011 for requirement ADHOC TORT (>	9.2 km)

SMS Incident Report	F2431984	8/21	10/01/2018 08:47:58
19:53:41	Unit HIND9311 [k	(P : PRIORITY MESSAGE]	
19:53:46	Unit ASHB621 [K	99 : PROPERTY FIRE WELL INV]	
19:54:11	-		
19:54:13	Unit HIND9311 [k	(P : PRIORITY MESSAGE] MAKE MORE TANKER	RS AND ANOTHER APPLIANCE
19:54:49	Unit ASHB621 [S	ITREP :] MAKE 2ND ALARM	
19:54:58	** Alarm level upd	ated to 2	
19:54:58	** Recommended	unit MAYF9411 for requirement TANKER (>24.0 k	xm)
19:54:58	** Recommended	unit ASHB627 for requirement PUMP (>9.8 km)	
19:55:17	Unit HIND9371 [k	(2 : IN ATTENDANCE AT INCIDENT]	
19:55:33	AL: PAGING ACK	RECEIVED FROM STATION 3462 at 04/12/17 19	9:55:33
19:55:43			.:.0
19:55:45	Unit ASHB622 [K	2 : IN ATTENDANCE AT INCIDENT]	
19:55:51	Unit ASHB9011 [I	K1 : PROCEEDING TO INCIDENT]	.0.
19:56:06	INC INFO: BUILD	ING FIRE 2ND ALARM	
19:56:33	Unit ASHB621 [K	P : PRIORITY MESSAGE]	
19:56:52	Unit ASHB621 [K	P : PRIORITY MESSAGE] MAKE 3 RD ALARM AI	ND AERIALS 1
19:56:53	Unit ASHB621 [K	99 : PROPERTY FIRE WELL INV]	
19:57:01	** Alarm level upd	ated to 3	
19:57:01	** Recommended	unit RAKA6411 for requirement TANKER (>37.3 k	m)
19:57:01	** Recommended	unit TIMA8018 for requirement COMU (>58.4 km)	
19:57:01	** Recommended	unit GERA841 for requirement PUMP (>36.1 km)	
19:57:07	Unit MAYF9411 [KP : PRIORITY MESSAGE]	
19:57:41	Unit ASHB627 [K	1 : PROCEEDING TO INCIDENT]	
19:58:13	Unit ASHB627 [K	1 : PROCEEDING TO INCIDENT]	
19:58:25	AL: PAGING ACK	RECEIVED FROM STATION 3464 at 04/12/17 19	9:58:25
19:59:15	Unit MAYF9411 [K1 : PROCEEDING TO INCIDENT]	
19:59:17	AL: PAGING ACK	RECEIVED FROM STATION 3580 at 04/12/17 19	9:59:17
19:59:20	INC INFO: BUILD	ING FIRE 3RD ALARM	
19:59:25	Unit TIMA804 [K1	: PROCEEDING TO INCIDENT]	
20:00:28	Unit TIMA804 [KO	C : UNIT CALLING]	
20:00:37	Unit GERA841 [K	1 : PROCEEDING TO INCIDENT]	
20:01:03	Unit SOUTHCANT	T2 [K1 : PROCEEDING TO INCIDENT]	
20:01:24			
20:01:56	AL: PAGING ACK	TIMED OUT FOR STATION: 3580 at 04/12/17 20	:01:56
20:02:17	AVAILABILITY CF	RREW	
20:02:24			
20:02:45	Unit RAKA6411 [I	K1 : PROCEEDING TO INCIDENT]	
20:02:53	Unit RAKA6411 [I	K1 : PROCEEDING TO INCIDENT]	
20:02:57	Unit ASHB6211 [I	K2 : IN ATTENDANCE AT INCIDENT]	
20:03:01	Unit RAKA6411 [I	K1 : PROCEEDING TO INCIDENT]	

SMS Incident Report	F2431984 9/21 10/01/2018 08:47:5
20:03:29	
20:03:45	WASHDYKE STATION PHONED TO UPLIFT COMMAND UNIT
20:03:46	Unit ASHB6229 [K1 : PROCEEDING TO INCIDENT]
20:05:20	Unit ASHB627 [K2 : IN ATTENDANCE AT INCIDENT]
20:05:25	Unit ASHB9011 [K2 : IN ATTENDANCE AT INCIDENT]
20:05:34	COVERING UNIT METH631 DISPATCHED TO STATION ASHBURTON
20:05:34	D0730062
20:05:46	Unit WASH817 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
20:06:16	Unit RURALSCRF5 [K1 : PROCEEDING TO INCIDENT]
20:07:21	Unit RAKA6411 [K1 : PROCEEDING TO INCIDENT]
20:07:35	Unit RAKA6411 [K1 : PROCEEDING TO INCIDENT]
20:08:03	Unit ASHB621 [KP : PRIORITY MESSAGE]
20:08:36	TIMA801 FULLY MANNED
20:08:50	Unit ASHB621 [KP : PRIORITY MESSAGE] TRANSMIT 4TH ALARM MAKE TANKERS 8
20:09:24	** Requirement PUMP added for alarm level 3
20:09:29	** Requirement PUMP added for alarm level 3
20:09:33	** Requirement PUMP added for alarm level 3
20:09:41	** Recommended unit GERA847 for requirement ADHOC PUMP (>36.1 km)
20:09:41	** Recommended unit TEMU861 for requirement ADHOC PUMP (>44.1 km)
20:10:17	Unit TEMU861 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
20:12:09	INC INFO: BUILDING FIRE 4TH ALARM
20:12:17	Unit ASHB6229 [K2 : IN ATTENDANCE AT INCIDENT]
20:12:27	-
20:12:32	AMBO EVENT -FIR LINKED AT 04/12/2017 20:12:32
20:12:35	FIR2AMB - 4TH ALARM BUILDING FIRE FYI
20:13:09	Unit GERA847 [K1 : PROCEEDING TO INCIDENT]
20:13:24	
20:13:35	Unit TEMU861 [K1 : PROCEEDING TO INCIDENT]
20:13:39	
20:13:42	Unit TEMU861 [K1 : PROCEEDING TO INCIDENT]
20:15:21	WASH817 FULLY MANNED
20:15:53	Unit TIMA8029 [K1 : PROCEEDING TO INCIDENT]
20:15:58	Unit TIMA8018 [K1 : PROCEEDING TO INCIDENT]
20:16:06	
20:17:34	
20:19:15	Unit RURALSCRF5 [K2 : IN ATTENDANCE AT INCIDENT]
20:21:15	Unit MAYF9411 [K2 : IN ATTENDANCE AT INCIDENT]
20:21:56	Unit PEND8911 [K1 : PROCEEDING TO INCIDENT]
20:23:15	··
20:23:57	COVERING UNIT FAIR821 DISPATCHED TO STATION GERALDINE

SWS incident Report	F2431984 10/21 10/01/2018 08:47:58
20:23:57	D0730062
20:25:18	EMAILED SOUTHCOM STAFF AND COMMAND UNIT APPLIANCES IN ATTENDANCE
20:26:30	Unit GERA841 [K2 : IN ATTENDANCE AT INCIDENT]
20:26:39	Unit TIMA8018 [KC : UNIT CALLING]
20:26:58	Unit ASHB6229 [KC : UNIT CALLING]
20:27:36	
20:27:40	INC INFO: PILOT SEEN BUILDING FIRE
20:27:40	Duplicate Event:Location = HINDS HWY,WINSLOW,ASHBURTON DISTRICT, Type = STRU -
20:27:40	STRUCTURE FIRE, Caller Name = Caller Ph
20:27:40	Number = Caller Address =
20:27:40	Call Source = 111Inc InfoPILOT SEEN BUILDING FIRE, Event
20:27:40	Source = Fire 111
20:27:40	End of Duplicate Event data
20:28:14	
20:28:35	Unit ASHB6229 [SITREP :] SO 1 LARGE SHED 100 BY 50 BY 20 SINGLE SEED
20:28:35	PROCESSING PLANT 50% IN FIRE DEFENSIVE MODE MULT DEL WATER SHORTAGE IS HAMPERING
20:28:35	EFFORTS K45 CFO
20:28:41	Unit RANG5111 [KC : UNIT CALLING]
20:28:49	Unit RANG5111 [KC : UNIT CALLING]
20:28:49	Unit ASHB6229 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] CFO
20:30:01	Unit SOUTHCANT2 [KC : UNIT CALLING]
20:30:09	
20:30:44	FAIR821 RESPONDING TO GERALDINE
20:30:53	Unit SOUTHCANT2 [SITREP :] DO YOU HAVE A SITREP
20:31:30	Unit RAKA6411 [K2 : IN ATTENDANCE AT INCIDENT]
20:31:51	Unit RANG5111 [K1 : PROCEEDING TO INCIDENT]
20:32:03	
20:34:26	Unit TIMA804 [K1 : PROCEEDING TO INCIDENT]
20:34:40	Unit ASHB6229 [KC : UNIT CALLING]
20:35:31	Unit TEMU861 [KC : UNIT CALLING]
20:35:42	Unit TEMU861 [KC : UNIT CALLING]
20:35:44	Unit ASHB6229 [SITREP :] WE HAVE AT LEASE 39 PEOPLE ON SITE CAN WE HAVE
20:35:44	CONTACT ASHB SALVATION ARMY AND ASK THEM TO BRING TEA AND COFFEE
20:36:03	Unit CANTERBRY1 [K1 : PROCEEDING TO INCIDENT]
20:36:42	Unit RANG5111 [K1 : PROCEEDING TO INCIDENT]
20:36:58	Unit ASHB6229 [SITREP :] SFP JUST INSIDE GATE
20:37:10	Unit SOUTHCANT2 [K2 : IN ATTENDANCE AT INCIDENT]
20:38:06	ANNOUNCEMENT MADE TO FURTHER ARRIVING APPLIANCES PASSED SFP - JUST INSIDE THE
20:38:06	GATE

SWS incident Report	FZ431904	11/21	10/01/2018 08:47:58
20:39:25	-		
20:39:44			
20:40:16	GUYS ONLY TO	COME	
20:40:17	Unit TEMU861 [R	(2 : IN ATTENDANCE AT INCIDENT]	
20:40:42	SUGGESTED RII	NGING SALVATION ARMY ASHBURTON NUMBER [DIRECT
20:40:43			
20:42:23	Unit GERA847 [k	(2 : IN ATTENDANCE AT INCIDENT]	×
20:43:21	Unit TIMA804 [K	2 : IN ATTENDANCE AT INCIDENT]	~ C)
20:43:35	Unit HIND9311 [I	K2 : IN ATTENDANCE AT INCIDENT]	
20:45:11			
20:45:41	Unit TIMA8018 [F	K1 : PROCEEDING TO INCIDENT]	.:.0
20:45:55	CONTACT		
20:45:56		~	C.
20:46:18	Unit PEND8911 [K2 : IN ATTENDANCE AT INCIDENT]	
20:48:21	Unit ASHB6229 [KC : UNIT CALLING]	
20:48:37	Unit TIMA8018 [F	K1 : PROCEEDING TO INCIDENT]	
20:48:44	Unit TIMA8018 [F	K1 : PROCEEDING TO INCIDENT]	
20:49:27	Unit ASHB6229 [SITREP:] CAN WE HAVE A LIST OF ALL APPLIANCE	CES AT SITE
20:49:38	Unit ASHB6229 [COMCEN COM : MESSAGE] CAN WE PASS BY PHO	DNE
20:49:47	Unit ASHB6229 [SITREP:] STAND BY	
20:50:10	Unit TIMA8018 [F	K1 : PROCEEDING TO INCIDENT]	
20:51:00	Unit TEMU861 [k	(C : UNIT CALLING]	
20:52:19	Unit TEMU861 [S	SITREP:] HAVE FOUND AN APPLIANCE WITH A CE	ELLPHONE - CAN YOU
20:52:19	RING WITH THE	LIST OF APPLIANCES	
20:52:51	PHONED THRU	APPLIANCES TO TEMU861	
20:54:44	AL: PAGING ACK	RECEIVED FROM STATION 3586 at 04/12/17 20:54	:43
20:55:30	Unit ASHB6229 [KC : UNIT CALLING]	
20:55:56	. 70.		
20:56:43	Unit ASHB6229 [SITREP:] FIRE IS CONTAINED WORKING TO PRO	TECT EXPOSURES WATER
20:56:43	SUPPLY IS A PR	OBLEM K45 AAM JOHNS CFO	ANAGER
20:56:56	Unit ASHB6229 [K45: COMMAND RESPONSIBILITY CHANGED TO	- NAME] AAM JOHNS
20:59:37	Unit TEMU8629 [K1 : PROCEEDING TO INCIDENT]	
20:59:40			
20:59:52	Unit TIMA8029 [F	K2 : IN ATTENDANCE AT INCIDENT]	
21:00:32	ASHBURTON SC	THERE ARE EXTRA 4 CREW WITH FULL PPE RES	SPONDING IF NEEDED
21:00:33			
21:04:32	ASHB6229 TO C	ONTACT AT ASHBURTON STATION	
21:04:53	Unit ASHB6229 [KC : UNIT CALLING]	
21:05:21	Unit ASHB6229 [COMCEN COM : MESSAGE] CAN YOU CONTACT	AT YOUR STATION
21:05:40	Unit TIMA8018 [K2 : IN ATTENDANCE AT INCIDENT]	

SMS Incident Report	F2431984	12/21	10/01/2018 08:47:5
21:10:48	Unit RANG5111	[K2 : IN ATTENDANCE AT INCIDENT]	
21:22:32	Unit CANTERB	RY1 [K2 : IN ATTENDANCE AT INCIDENT]	
21:22:48	Unit CANTERB	RY1 [K2 : IN ATTENDANCE AT INCIDENT]	
21:30:22	Unit TIMA8018	KC : UNIT CALLING]	
21:32:47	Unit TIMA8018	K44 : COMMAND OR CONTROL POINT ESTAB	LISHED - OIC AND LOCATION]
21:32:47	WINSLOW COM	MAND	
21:33:27	Unit TIMA8018	KC : UNIT CALLING]	×
21:35:30	Unit TIMA8018	SITREP:] AM JOHNS BUILDING IRREGULAR	SIZE 100 BY 50M SEED
21:35:30	STORAGE AND POLIE	PROCESSING BLDG 1 CREW INTERNAL FF PI	ROTECTING HAZSUB STOCK
21:35:30	WATER SUPPL	Y FROM IRRIGATION	
21:55:55			XIO .
21:56:14	**		
21:56:58	A RELIEF CRE	V FROM CHCH WILL BE AT SCENE FOR 2330 -	THEY WILL BE RELIEVED AT
21:56:58	0330 BY A ANC	THER CREW FROM CHCH	
21:57:28	A RELIEF CRE	V FROM TIMARU WILL BE AT INCIDENT FROM	2300 - THEY WILL BE RELIEVED
21:57:28	BY ANOTHER 1	TIMARU CREW AT 0300	
21:57:51	AC GREENYER	WILL BE EXECUTIVE RELIEF AT 0100	
21:58:00	AAC BUTLE WI	LL RELIEVE AC GREENYER AT 0500	
21:58:01			
21:58:51	DIGGER TO BE	AT LEAST 30 TONS FOR IRON REMOVAL	
21:59:45	Unit TEMU8629	[K2 : IN ATTENDANCE AT INCIDENT]	
22:00:15	Unit TIMA802 [K1 : PROCEEDING TO INCIDENT]	
22:01:43	Unit TIMA8018	KP : PRIORITY MESSAGE]	
22:02:16	Unit TIMA8018	KP : PRIORITY MESSAGE] K11A	
22:02:26		76.	
22:02:31	FIR2AMB	0.	
22:02:41	1 FF INJURED		
22:02:50	INFO ON INJUR	RIES TO FOLLOW	
22:02:56	-0		
22:03:11	AMBO EVENT	FIR LINKED AT 04/12/2017 22	2:03:11
22:03:40	Unit TIMA8018	K11A : AMBULANCE REQUIRED]	
22:03:57	Unit TIMA8018	SITREP :] AMB REQ FOR FF WITH	
22:03:57	BELIEVED TO E	BE A VOLLIE	
22:05:04	Unit TIMA8018	K11A : AMBULANCE REQUIRED]	
22:05:06			
22:05:58	FM AMB VIA PH	IONE - CALLING TO ASK IF THEY ARE REQUIR	RED TO ATTEND: ADVISED THEM
22:05:58	AFFIRMATIVE '		
22:06:30			
22:08:38			

SMS Incident Report	F2431984	13/21	10/01/2018 08:47:58
22:14:41	ETA DIGGER	90 MINS	
22:15:50			
22:17:16			
22:17:30	STUART TAR	RBOTTON CONTRACTORS CONTACT NO.	
22:20:53	SSO	IS ARRANGING THE WAIMATE LIGHTING UNIT	
22:21:06			
22:24:33			×
22:25:34			~ 6
22:25:50	Unit CHRI212	9 [K1 : PROCEEDING TO INCIDENT]	
22:26:12	2X FIREFIGH ASHBURTON	TERS INJURED - I	FROM
22:26:12	BRIGADE AN	FROM GERALDINE BRIGADE	
22:26:18	AMBULANCE	IN ATTENDANCE	3 -
22:26:21			
22:27:33			
22:28:24	CHRI2129 IS	HEADING DOWN AS RELIEF - CHRI214 IS OFF THE RU	N UNTIL MANNED AGAIN
22:29:45	SPRE221 WII	LL GO AT 0200 FOR 0300 ARRIVAL	
22:30:43	UPDATE AS I	HE WILL TALK TO DAVE BERRY IN THE MORNING	
22:31:12			
22:32:01			
22:33:28	CHRI214 NO	N K7	
22:34:43	Unit TIMA801	8 [SITREP :] BOTH FF STAT 4 1% AND 4% B	OTH ARE BEING
22:34:43	TRANSPORT	ED	
22:35:29		29 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
22:35:34		N ENROUTE SSO - CONTACT NUMBER I	F NEEDED
22:37:50	SPRE221 WII	LL HEAD DOWN AT 0200	
22:40:06	-		
22:43:22	TRANSPORT	ED TO ASHBURTON HOSPITAL	
22:43:46	. 0		
22:44:37	Unit VSOSTH	CAN2 [K1 : PROCEEDING TO INCIDENT]	
22:44:59	Unit TIMA801	8 [KC : UNIT CALLING]	
22:45:42	Unit TIMA801	8 [SITREP :] FROM AAM JOHN K11F	
22:45:52	Unit TIMA801	8 [K11F : FIRE SAFETY REQUIRED]	
22:47:16			
22:47:37	Unit TIMA802	[K1 : PROCEEDING TO INCIDENT]	
22:47:39			
22:48:46	Unit MAYF94	11 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
22:50:25	-		
22:54:23	Unit VSOSTH	CAN2 [K2 : IN ATTENDANCE AT INCIDENT]	
23:00:07	Unit TIMA802	[K2 : IN ATTENDANCE AT INCIDENT]	

SMS incluent Keport	12431904	10/01/2010 00.47.30
23:00:11		
23:07:06	CRAIG CHAMBERS UPDATED RE INJURIES	
23:07:53	Unit TIMA8018 [SITREP :] VIA PHONE, WANTING TO KNOW ABOUT HOW	V THE RESPONDING
23:07:53	DIGGER CAME ABOUT - (UPDATED THIS REQUEST CAME FROM AAC JO	OHNS)
23:12:59	Unit CHRI2129 [K1 : PROCEEDING TO INCIDENT]	
23:41:50	Unit ASHB627 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
23:42:51	ļ.	×
23:43:00	FIRE WILL BE ON SCENE ALL NIGHT	~ ()
23:43:08	AMB CREW HAVE ATTENDED	
00:00:03	Unit TIMA8018 [KC : UNIT CALLING]	
00:01:14	Unit TIMA8018 [SITREP :] DIGGER IN OPERATOIN BURNS TO FF AND BE	EING TRANSPORTED
00:01:14	TO A & E BY VAN WE REQUIRE DIESEL AND PETROL TO FIREGROUND	
00:02:39	Unit TIMA8018 [SITREP :]	VILLOBY STN
00:02:39		
00:03:59	%O	
00:09:16	Unit GERA847 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
00:11:05		
00:13:31	Unit TEMU861 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
00:14:51	Unit ASHB621 [KC : UNIT CALLING]	
00:15:18	Unit ASHB621 [SITREP :] WE WILL BE K10	
00:15:27	Unit ASHB621 [K10 : RECOMMISSIONING]	
00:15:36	Unit CHRI2129 [K2 : IN ATTENDANCE AT INCIDENT] ENTERED BY COMS	,
00:16:08	Unit CANTERBRY1 [K6 : ON TELEPAGER]	
00:19:30	Unit SOUTHCANT1 [K1 : PROCEEDING TO INCIDENT] ENTERED BY COM	IS - WAS ENROUTE
00:19:30	WHEN HE RUNG IN	
00:27:36	NO CONTACT WITH ROONEY EARTHMOVING FOR FUEL	
00:42:29	FIREGROUND MAKING ENQUIRIES VIA MURRAY CAIRNS RE FUEL	
00:48:44	Unit TIMA8018 [SITREP :] PLSE MAKE CONTACT WITH PAUL SMITH CON	NTRACTING FOR
00:48:44	FUEL	
00:55:05		
00:56:17	Unit SOUTHCANT1 [K2 : IN ATTENDANCE AT INCIDENT]	
00:59:39	HAVE TRIED PHONING ALL THE MAIN EARTHMOVING COMPANIES IN THE STH	HE RURAL FIRE PLAN
00:59:39	CANTY - NO ANSWER -LEFT MESSAGES WITH ROONEYS, PAUL SMITH	AND FULTON HOGAN
01:05:21		
01:05:41	TOC ADVISE THEIR CONTRACTORS ARE DOWNERS IN THE AREA	
01:08:26	DOWNERS MAY HAVE A DIESEL TANKER THAT COULD RESPOND - WIL	L CONFRIM SHORTLY
01:09:34	Unit GERA841 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
01:09:39	Unit TIMA8018 [KC : UNIT CALLING]	
01:10:36	Unit TIMA8018 [SITREP :] REQUEST FROM THE CFO GERALDINE GET H	OLD OF THE

SWS incident Report	F2431984 15/21 10/01/2018 08:47:58
01:10:36	AND CONTACT 841 DIRECTLY
01:10:53	Unit TIMA8018 [KC : UNIT CALLING]
01:11:45	Unit TIMA8018 [SITREP :] COULD WE ALSO HAVE THE INFO FOR THE INCIDENT
01:11:45	CONTROLLER
01:11:57	-
01:12:30	FROM ASHBURTON STATION CRAIG CHAMBERS IS IN HOSPITAL WITH THE HES
01:12:30	THE BEST CONTACT IF WE NEED UPDATES
01:12:32	
01:13:59	
01:14:53	
01:14:53	
01:16:34	Unit TIMA8018 [COMCEN COM : MESSAGE] FF CONDITION UPDATE PASSED TO WINSLOW
01:16:34	COMMAND
01:17:56	Unit TIMA8018 [COMCEN COM : MESSAGE] DOWNERS IS RESPONDING WITH DIESEL TANKER -
01:17:56	1000 LTRS - ETA 1 HR
01:20:09	Unit HIND9371 [K7 : AT NORMAL STATION]
01:24:40	Unit TIMA8018 [KC : UNIT CALLING]
01:25:49	Unit TIMA8018 [SITREP :] AAM JOHNS REQUEST FOR 24HR WEATHER FORCAST EMAILED
01:25:49	THROUGH TO THE COMMAND UNIT
01:28:16	-
01:32:50	NIWA WILL EMAIL WEATHER REPORT THROUGH WITH IN 20 MINS AND CALL BACK TO ENSURE
01:32:50	WE RECEIVED IT
01:40:46	Unit TIMA8018 [KC : UNIT CALLING]
01:41:31	Unit TIMA8018 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] K45 AM GREENYER
01:43:01	Unit ASHB9011 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
01:46:07	Unit TIMA804 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
01:52:06	Unit RANG5111 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
01:59:44	Unit TIMA8018 [COMCEN COM : MESSAGE] WE HAVE EMAILED YOU THROUGH THE WEATHER
01:59:44	REPORT
01:59:55	Unit RURALSCRF5 [K6 : ON TELEPAGER]
02:01:45	Unit TIMA801 [K1 : PROCEEDING TO INCIDENT]
02:04:34	Unit TIMA8018 [KC : UNIT CALLING]
02:04:54	Unit SPRE221 [K1 : PROCEEDING TO INCIDENT]
02:06:24	Unit TIMA8018 [SITREP :] IC GREENYER OPERATIONS FERGUSON SAFETY BAKER EXTERNAL
02:06:24	DEFENSIVE MODE 2 SECOTRS ONLY
02:06:27	Unit RAKA6411 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
02:11:37	Unit SPRE221 [KC : UNIT CALLING]
02:13:02	Unit SPRE221 [SITREP :] WHAT CHANNEL ARE THEY OPERATING ON AND WHERE DO WE

SWS incident Report	F2431984 10/21 10/01/2018 08:47:5
02:13:02	CHANGE OVER
02:21:20	Unit TIMA8029 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
02:28:59	Unit SPRE221 [K1 : PROCEEDING TO INCIDENT]
02:32:15	Unit PEND8911 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
02:40:46	Unit SOUTHCANT2 [K6 : ON TELEPAGER]
02:44:46	Unit TIMA801 [K1 : PROCEEDING TO INCIDENT]
02:58:22	Unit TIMA801 [K2 : IN ATTENDANCE AT INCIDENT]
03:20:16	Unit SPRE221 [K2 : IN ATTENDANCE AT INCIDENT]
03:21:52	Unit WILL9911 [K7 : AT NORMAL STATION]
03:32:55	Unit CHRI2129 [K2 : IN ATTENDANCE AT INCIDENT]
03:46:38	Unit CANTERBRY2 [K1 : PROCEEDING TO INCIDENT]
03:47:40	Unit ASHB622 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
03:47:51	Unit ASHB6229 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
03:49:17	Unit VSOSTHCAN2 [K6 : ON TELEPAGER]
03:49:54	Unit TIMA8018 [KC : UNIT CALLING]
03:50:51	Unit TIMA801 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
03:51:11	Unit TIMA8018 [SITREP :] AM GREENYER ASHB622 HAS BEEN RELEASED AT WRK WITH 2
03:51:11	TANKERS AND 1 PUMP CREW SAFETY OFFICER IS NOW
04:10:35	Unit TIMA8018 [KC : UNIT CALLING]
04:11:11	Unit ASHB6211 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
04:11:16	Unit HIND9311 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
04:11:23	Unit CHRI2129 [K2 : IN ATTENDANCE AT INCIDENT]
04:11:38	Unit TIMA8018 [SITREP :] AM GREENYER ASHB6211 AND HIND9311 ARE BEING RELEASED
04:11:38	PUMP WORKING FROM IRRIGATION SUPPLY
04:17:17	Unit CHRI2129 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
04:30:33	Unit CANTERBRY2 [K1 : PROCEEDING TO INCIDENT]
04:35:02	
04:35:50	Unit SOUTHCANT1 [SITREP :] AM STEVE GREENYER - ANY MEDIA CALLS CAN BE PUT
04:35:50	THROUGH TO MY CELL
04:36:37	Unit CANTERBRY2 [K2 : IN ATTENDANCE AT INCIDENT]
05:02:07	Unit TIMA8018 [KC : UNIT CALLING]
05:02:38	Unit TIMA8018 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] AAC BUTLER
05:10:37	Unit CANTERBRY2 [SITREP :] ALL MEDIA NOW THROUGH AAC STEPHEN BUTLER -
05:10:37	
05:13:36	Unit SOUTHCANT1 [K6 : ON TELEPAGER]
05:17:34	Unit TIMA8018 [KC : UNIT CALLING]
05:18:22	Unit TIMA8018 [SITREP :] AAC BUTLER NO CHANGE TO FF OPS PLAN IN PLACE TO
05:18:22	REPLACE CREWS UNDERWAY
06:32:15	Unit TIMA8018 [KC : UNIT CALLING]
06:33:15	Unit TIMA8018 [SITREP :] AAC BUTLER AWAITING ARRIVAL OF MACHINERY CREWS TO

SWS incident Report	F2431984 17/21 10/01/2018 08:47:58
06:33:15	DEMOLISH STRUCTURE FF OPERATIONS HAVE CEASED FOR THE MOMENT
06:52:37	Unit TIMA8018 [KC : UNIT CALLING]
06:53:37	Unit TIMA8018 [SITREP :] COMMAND UNIT SHUT DOWN NOW WINSLOW COMMAND WILL BE
06:53:37	OPERATING OUT OF AAC BUTLERS CAR FROM HERE ON
07:13:42	Unit TIMA8018 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
07:31:35	Unit FISTHCANT1 [K1 : PROCEEDING TO INCIDENT]
07:34:34	Unit WILL9911 [K7 : AT NORMAL STATION]
07:42:19	Unit ASHB622 [K1 : PROCEEDING TO INCIDENT]
07:48:58	Unit ASHB622 [K2 : IN ATTENDANCE AT INCIDENT]
07:57:20	Unit TIMA801 [K1 : PROCEEDING TO INCIDENT]
08:03:14	Unit SPRE221 [K2 : IN ATTENDANCE AT INCIDENT]
08:05:47	Unit FISTHCANT1 [K2 : IN ATTENDANCE AT INCIDENT]
08:10:11	Unit CANTERBRY2 [SITREP :] ASHBURTON CREWS BACK ON SCENE. DIGGER STRATEGICALLY
08:10:11	DISMANTLING SHED. DAMPENING DOWN HOTSPOTS.
08:10:18	Unit ASHB6211 [K2 : IN ATTENDANCE AT INCIDENT]
08:10:50	Unit CANTERBRY2 [SITREP :] ONCE THE CREW FROM TIMARU GETS HERE WE WILL RELEASE
08:10:50	THE CHRISTCHURCH CREW
08:15:02	Unit SOUTHCANT2 [K1 : PROCEEDING TO INCIDENT]
08:15:29	Unit SOUTHCANT2 [K1 : PROCEEDING TO INCIDENT]
08:17:06	Unit CHRISTCH4 [K6 : ON TELEPAGER]
08:18:16	AL: PAGING ACK TIMED OUT FOR STATION: 3580 at 05/12/17 08:18:16
08:19:24	Unit VSOSTHCAN1 [K1 : PROCEEDING TO INCIDENT]
08:55:55	Unit TIMA801 [K2 : IN ATTENDANCE AT INCIDENT]
08:58:42	Unit SPRE221 [K7 : AT NORMAL STATION]
09:36:23	Unit TIMA801 [KC : UNIT CALLING]
09:36:58	Unit TIMA801 [K10 : RECOMMISSIONING]
09:37:18	Unit CANTERBRY2 [SITREP :] VIA PHONE WORKING WITH DIGGERS AND LOADERS GAINING
09:37:18	ACCESS TO HOTSPOTS 2 DELIVIERIES, MOP UP MODE K45 AAC JOHNS CFO
09:37:18	OPERATIONS COMMANDER
09:37:34	Unit CANTERBRY2 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] AAC JOHNS
09:50:34	Unit ASHB6211 [KC : UNIT CALLING]
09:52:04	Unit ASHB6211 [K7 : AT NORMAL STATION]
09:54:15	Unit CANTERBRY2 [K6 : ON TELEPAGER]
10:48:50	Unit VSOSTHCAN1 [K2 : IN ATTENDANCE AT INCIDENT]
10:49:47	**
10:50:49	Unit SOUTHCANT2 [SITREP :] CAN WORKSAFE BE ORGANISED TO TAKE SAMPLES OF THE
10:50:49	IN THEY NEED FURTHER
10:50:49	INFORMATION PUT THEM THROUGH TO FI CRAIG CHAMBERS
10:50:49	**
10.01.00	

SWS incident Report	F2431964 10/21 10/01/2016 06:47:5
11:02:32	Unit ASHB622 [KC : UNIT CALLING]
11:04:51	Unit SOUTHCANT2 [K2 : IN ATTENDANCE AT INCIDENT] ENTERED BY FIRECOM
11:05:19	Unit ASHB622 [COMCEN COM : MESSAGE] CAN YOU PHONE YOUR STATION (ACK)
11:26:43	****
11:26:48	***
11:27:43	WORKSAFE IS MAKING A JOB FILE NOW AND WILL CALL BACK SHORTLY AND NEEDS TO BE PUT
11:27:43	THROUGH TO THE OIC
11:28:05	THEY HAVE BASIC DETIALS SO FAR (WHAT WHERE HOW ETC) BUT WILL NEED MORE DETAILED
11:28:05	INFO SHORTLY
11:28:07	***
11:32:15	WORKSAFE TO BE PUT THROUGH TO CRAIG CHAMBERS
11:32:16	***
12:23:34	Unit SOUTHCANT2 [SITREP :] VIA PHONE ALL FF DISCHARGED FROM HOSPITAL
13:15:15	Unit VSOSTHCAN1 [K6 : ON TELEPAGER]
17:21:20	Unit TEMU861 [K1 : PROCEEDING TO INCIDENT]
17:38:15	Unit FISTHCANT1 [K6 : ON TELEPAGER]
17:40:10	Unit TEMU861 [KC : UNIT CALLING]
17:40:51	Unit TEMU861 [K1 : PROCEEDING TO INCIDENT]
17:41:16	Unit TEMU861 [SITREP :] SHOULD I CHANGE ONTO THE CENTRAL CANTERBURY CHANNELL
18:03:56	Unit TEMU861 [K2 : IN ATTENDANCE AT INCIDENT]
18:06:28	Unit TEMU861 [KC : UNIT CALLING]
18:07:37	Unit TEMU861 [SITREP :] WE ARE RELEAVING THE ASHB622 CREW THEY ARE LEAVING
18:07:37	THEIR APPLIANCE HERE BUT ARE TAKING A CAR HOME
18:07:46	Unit TEMU861 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SSO
18:49:57	Unit SOUTHCANT2 [K6 : ON TELEPAGER]
21:52:17	
21:52:49	HARE261 CREW ARE HEADING DOWN IN THE VAN TO RELIEVE TEMUKA. HAREWOODS CREV
21:52:49	BE RELIEVED AT 0230 BY WAINONIS CREW
22:29:05	Unit TEMU861 [KC : UNIT CALLING]
22:29:24	Unit TEMU861 [SITREP :] WE HAVE BEEN RELEVIED
22:29:35	Unit TEMU861 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SSO
22:29:38	Unit TEMU861 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
07:32:44	Unit FISTHCANT1 [K1 : PROCEEDING TO INCIDENT]
08:02:42	Unit FISTHCANT1 [K2 : IN ATTENDANCE AT INCIDENT]
10:00:53	Unit TIMA802 [K2 : IN ATTENDANCE AT INCIDENT]
10:01:21	Unit TIMA802 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
10:18:16	Unit ASHB622 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE]
10:18:42	Unit ASHB622 [K0 : NOT AVAILABLE] UNTIL 1930HRS 06/12/17

SMS incident Report	F2431984 19/21	10/01/2018 08:47:58
10:38:36	Unit EVENTSCC1 [K7 : AT NORMAL STATION]	
11:34:00	Unit FISTHCANT1 [SITREP :] VIA PHONE - REQUEST FOR LOCA	AL POLICE OFFICER TO
11:34:00	CONTACT VIA CELL PHONE (HANDED TO POLICE COMMS TO A	RRANGE)
15:10:36	Unit FISTHCANT1 [K6 : ON TELEPAGER]	
15:14:04	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifie	er 1: Q1,
15:14:04	UNIT ASHB6211 ALERT TIME [NULL] ADJUSTED TO	
15:14:04	Qualifier 2:	×
15:14:05	UNIT CANTERBRY2 ALERT TIME [NULL] ADJUSTED TO	
15:14:05	UNIT ASHB6229 ALERT TIME [NULL] ADJUSTED TO	
15:14:05	UNIT CANTERBRY2 ALERT TIME [NULL] ADJUSTED TO	
15:14:06	UNIT CHRI2129 ALERT TIME [NULL] ADJUSTED TO	.:.0
15:14:06	UNIT CHRI2129 ALERT TIME [NULL] ADJUSTED TO	
15:14:06	UNIT SOUTHCANT1 ALERT TIME [NULL] ADJUSTED TO	C.O.
15:14:07	UNIT SPRE221 ALERT TIME [NULL] ADJUSTED TO	
15:14:07	UNIT TIMA801 ALERT TIME [NULL] ADJUSTED TO	
15:14:07	UNIT TIMA801 ALERT TIME [NULL] ADJUSTED TO	
15:14:07	UNIT SPRE221 ALERT TIME [NULL] ADJUSTED TO	
15:14:08	UNIT TIMA802 ALERT TIME [NULL] ADJUSTED TO	
15:14:08	UNIT TIMA802 ALERT TIME [NULL] ADJUSTED TO	
15:14:08	UNIT TIMA801 ALERT TIME [NULL] ADJUSTED TO	
15:14:09	UNIT VSOSTHCAN2 ALERT TIME [NULL] ADJUSTED TO	
15:14:09	UNIT TIMA8029 ALERT TIME [NULL] ADJUSTED TO	

Incident

CAD Number F2431984
Incident Reporter

Distance Travelled (km)
Delay In Receiving Call

Property Details

Incident Controller

Occupant Seales Ltd

Building Owner Owner occupied

General Property Use Industrial, Manufacturing

Special Property Use Storage open: Barn, Silo, Bin, Bulk/loose

Purpose Group

Actions

Persons Reported Trapped

Evacuation Status

Not occupied at time of incident

Action Prior 1

Action Prior 2

Action Taken

Extinguishment only: Includes isolating fuel/power

Civilians

Civilians Rescued	×	0
Civilians Extricated	~ G.	0
Civilians Assisted		0
Civilians Evacuated		0

Origin

Location Outside area, multiple area - not classified above

Level Ground level

Equipment Used

Quantity	Equipment
1	Hose reel, high pressure delivery
8	Low pressure delivery
3	Monitor

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition Large fire

Heat Source Refuse burning

Termination Stage

First Object Ignited

First Object Material

Second Object Ignited

Second Object Material

Indicated Cause Heat source too close to combustibles

Certainty of Cause Low

Age of PersonUnknownEthnicityUnknown

Gender

FAIP Service Offered FAIP Service Accepted No No

Comments

12/27/2017 12:37:22 PM

Reporter Comments

zeleased under the Official Information 2. no files from Ashburton brigade. See fire investigation report. FENZ injuries noted in kiosk