

Date of Notification	Date of Commencement	Days between notification and commencement	Active Days	Type of Asbestos	Is Immediate Removal?	Was Notice of Immediate Removal Given to WorkSafe?	Immediate Removal Flag	Worksite Address	Worksite Address cont.	Worksite Suburb	Location of Asbestos	Asbestos Removal Licence Holder	Removal Licence/Certificate Number	Removal Licence Holder Contact Number	Removal Licence Holder Email	Expired licence flag	Supervisor	Supervisor Contact Number	Supervisor Email	Supervisor Certificate Number	Supervisor on multiple sites on commencement date	Assessor
25/09/2017 2:00:28 p.m.	3/10/2017	8	4	Non-friable	No	No		Otamatea High School	581 Bickerstaffe Rd	Maungaturoto 0581	Remove and dispose the asbestos cladding from block P3. Remove and dispose greenery to access the asbestos cladding.	Harcourt Insulation (2006) Ltd	RA16080080 RB16080081	9(2)(a)	office@insulation.co.nz		Sub Contractor - RA17020027. As on worksafe licence holder register	Sub Contractor - RA17020027: 9(2)(a)	Sub Contractor - RA17020027: 9(2)(a)	Sub Contractor - RA17020027: Class A	Sub Contractor - RA17020027: COC number on multiple sites	Intertek Intertek
8/12/2017 3:26:23 p.m.	13/12/2017	5	2	Non-friable	No	No		Otamatea High School	581 Bickerstaffe Rd	Maungaturoto 0581	Remove the exterior flat sheet cladding containing asbestos	Harcourt Insulation (2006) Ltd	RA16080080 RB16080081	9(2)(a)	office@insulation.co.nz		Our Staff Sub Contractor - RA17020027. As on worksafe licence holder register	Sub Contractor - RA17020027: 9(2)(a)	Sub Contractor - RA17020027: 9(2)(a)	Sub Contractor - RA17020027: Class A	Sub Contractor - RA17020027: COC number on multiple sites	Intertek Testing Services (NZ) Intertek Testing Services (NZ)
1/01/2018 5:02:49 p.m.	16/01/2018	15	4	Non-friable	No	No		581 BICKERSTAFFE RD		MAUNGATAROTO	BOILER HOUSE	AS BEST AS US ASBESTOS REMOVALISTS AND DEMOLITION LIMITED	RA 17060001	9(2)(a)	9(2)(a)		MR ASHTON EUGENE TAIRUA	9(2)(a)	9(2)(a)	ASHTON: RA 17060001		HEALTHSAFE ROBERT MUMFORD
2/02/2018 2:25:15 p.m.	10/02/2018	8	2	Non-friable	No	No		Otamatea High School	581 Bickerstaffe Rd	Maungaturoto 0581	Removal of external cladding.	Harcourt Insulation (2006) Ltd	RA16080080 RB16080081	9(2)(a)	office@insulation.co.nz		Our Staff Sub Contractor - RA17020027 As on worksafe licence holder register	Sub Contractor - RA17020027: 9(2)(a)	Sub Contractor - RA17020027: 9(2)(a)	Sub Contractor - RA17020027: Class A		Intertek Testing Services (NZ) Intertek Testing Services (NZ)

RELEASED UNDER THE OFFICIAL INFORMATION ACT 1982

Assessor Licence Number	Assessor Licence Expiry Date	Friable Licence Flag	Friable Enclosure Details	Quantity Removed	Transportation/ Disposal Method	Description of Worksite	Number of Workers	Workers	Worker Has Relevant Training Certificate?	Summary of Training	Manager or Controller of Worksite	Manager or Controller Trading Name	Manager or Controller NZBN	Property or Site Owner	Property or Site Trading Name	Property or Site NZBN	Property or Site Owner Contact Number	Property or Site Owner Email	Property or Site Contact	Declarer Name	Declarer Email	Date of Declaration	Reference Number
				Approx 60m2	Covered company vehicle used to transport asbestos materials to an approved disposal site.	High School	1	[REDACTED] 9(2)(a)	No 9(2)(a)	9(2)(a); Working under the supervision of a Class A holder. External provider safety training and internal process skill training.	Harcourt Insulation (2006) Ltd			Arco Group Ltd			[REDACTED] 9(2)(a)	[REDACTED] 9(2)(a)	Harcourt Insulation (2006) Ltd	office@insulation.co.nz	25/09/2017	0015789	
				Approx 25m2	Covered company vehicle used to transport asbestos materials to an approved disposal site.	School	1	[REDACTED] 9(2)(a)	No 9(2)(a)	9(2)(a); Working under the supervision of a Class A holder. External provider safety training and internal process skill training.	Harcourt Insulation (2006) Ltd			Arco Group Ltd			[REDACTED] 9(2)(a)	[REDACTED] 9(2)(a)	Harcourt Insulation (2006) Ltd	office@insulation.co.nz	8/12/2017	0019031	
				1/2 TONNE	TRUCK TO PUWERA DUMP	HIGH SCHOOL	6	[REDACTED] 9(2)(a)	Yes; Yes; Yes; No 9(2)(a)	9(2)(a); ASBESTOS AWARENESS CERTIFICATE HEIGHTS CERTIFICATE / ASBESTOS AWARENESS CERTIFICATE 9(2)(a) ASBESTOS AWARENESS CERTIFICATE / ASBESTOS AWARENESS CERTIFICATE 9(2)(a) ASBESTOS AWARENESS CERTIFICATE / ASBESTOS AWARENESS CERTIFICATE 9(2)(a) UNDER DIRECT SUPERVISION TO ME 9(2)(a)	AS BEST AS US ASBESTOS REMOVALISTS AND DEMOLITION LIMITED	AS BEST AS US	942904223 0151	KERR CONSTRUCTION	KERR CONSTRUCTION LIMITED		[REDACTED] 9(2)(a)	[REDACTED] 9(2)(a)	[REDACTED] 9(2)(a)	ASHTON TAIRUA	[REDACTED] 9(2)(a)	1/01/2018	0019386
				Approx 27m2	Covered company vehicle used to transport asbestos materials to an approved disposal site.	School	1	[REDACTED] 9(2)(a)	No 9(2)(a)	9(2)(a); Working under the supervision of a Class A holder. External provider safety training and internal process skill training.	Harcourt Insulation (2006) Ltd			Arco Group Ltd			[REDACTED] 9(2)(a)	[REDACTED] 9(2)(a)	Harcourt Insulation (2006) Ltd	office@insulation.co.nz	2/02/2018	0020211	

RELEASED UNDER THE OFFICIAL INFORMATION ACT 1982