## SUMMIT SYSTEMS LTD

## FIRE SAFETY ANNUAL AUDIT

To identify
important issues
and to improve
RISK RATING FOR BEST
INSURANCE PREMIUMS

Client name
Rise VI Tust

Address

22 Nosella Go, Magar Lat

Contact person

Green Lafea.

NB you can issue one free Fire Action Emergency sign for doing this audit, you can issue another for sign up of warden training and yet another if they sign for a formal evacuation scheme

> Summit Systems Ltd for Compliance Solutions

	External Annual Audit for	Repor	t & Certification - P1	
	You may show this pag	e to cl	ient - but not issue	
100 days	Fire Safety and Evacuation of Buildings Regulations 2006 Fire & Emergency NZ Evacuation Procedures and Evacuation Schemes 2018	No/Yes or N/A	Recommendations on action Say okay or not okay Yes or no; tba to be actioned; ny not yet; missing; faulty etc	Score 0-5
	There is a formal written procedure or audit log of say 6-12 pages – not just a sign	YES	If the answer is probably, or subject to conditions, then the correct answer is NO.	5
Umlay	2. There is an alarm system in place and it actually operates correctly – it can be voice or whistle, gong, bell - it must be written down	182	80 questions of the 5 mark variety to be attempted	5
	,	YES	making a maximum of 400.  You may ignore or delete	5
	4. There is an assistance register for persons requiring evacuation assistance and 2 staff	n/a	12 of the first 90 questions.	0
	are trained in methods to provide assistance  5. There is a proper register for visitors /	YES	Then do the 6 compulsory ones worth 20 each for 120.	5
	contractors and they are advised of fire safety rules to be observed		Then divide total scored by 5 See notes at end.	ノ
	6. There is a register for all staff with their address, phone numbers & mobile number	YES	When scoring the minimum is zero NOT 1	5
	7. Personal protective equipment is available at reception for visitors e.g. Hi vis vests	YES	Legal requirement	5
	There are evacuation procedure notices in every department or fire cell (4+ per site)	YES	Legal requirement	5
	There are emergency information signs in every department or fire cell (4+ per site)	1/2	Reception, Office, Warehouse, Factory, Cafe	5
	10. There are at least two escape routes and exit signs are in place and visible	Ve	Legal requirement	5
	11. There are sufficient extinguishers around the building e.g. 1 x 2kg for every 200M2 and they have an annual survey to check good condition and able to operate	Yes	Site plan to be made up  Oune 8 Extinguisher  on site.	5
٧	12. Staff have been trained in how to use extinguishers in a safe manner	udA	Legal requirement for all permanent staff	2
	13. Extinguishers are of the right type and are easily accessible and have blazons	YES	4 types current extinguishers FFF, CO2, ABE, Water	ク
	14. Call points / alarms are maintained in good working order at all times, they have signs telling people how to make alarm	YES	The BCF now outlawed  Legal requirement	5
	15. Where there is a basic system of raising the alarm (e.g. gong or whistle) it can be heard throughout the building/s.	YE		5
			Maximum this page 75	± <i>67</i>

External Annual Audit for Report & Certification - P2 You may show this page to client - but not issue

Fire Safety and Evacuation Regs 2006	No/Yes	Recommendations on any	Score
Fire & Emergency NZ Evacuation Procedures and Evacuation Schemes 2018	or N/A	Action to be taken	0-5
16. There are signs near the lifts (if any) to warn people not to use lifts to escape in the event of a fire or an earthquake	NA	Some sites don't have lifts but they have routes blocked	0
17. All fire cells have a Warden and Deputy warden and the Wardens carry out monthly fire safety checks in a proper manner	1 4/a	Bonus points (2) may be issued for monthly or quarterly (minimum) checks	2
18. All buildings have a Head Warden and Deputy Head Warden	Ma	Legal requirement	O
19. All buildings have Emergency Enforcer to ensure that evacuation systems work	ula	All sites need an Enforcer	2
20. Large sites have security warden plus a rescue warden that are properly trained	N/a	All large sites need these	0
21. All Wardens have an arm band or vest plus a tag placed at the end of their patrol area	-,VEŞ	Hi - Vest Must be identifiable	5
22. All Head Wardens have peaked hat or hard hat for evacuation	XES	Must be identifiable	5
23. All permanent staff are given fire safety training every two years at the minimum	- Ula	Legal requirement	2
24. All new staff are inducted into the regulatory requirements and procedures when they start work	YES	Bonus points (2) may be issued for formal training all staff in all safety procedures	5
25. All Wardens and Head/Deputy Wardens are given training every two years and have certificates to prove it	ula	Legal requirement	2
26. Smoke & Fire stop /solid doors are maintained in accordance with the Bldg Code & Regs	VES	There are 10 checks for IQP	5
27. First aid cabinets and kits are adequate and have signs and are checked monthly and replenished as needed	YES	Large vehicles have kit	5
28. Staff are trained in methods to avoid dust explosion or particulate explosion	N/o	Dust explosions happen in joinery shops, panel beaters, bakeries with flour or paint	0
29. Large Gas cylinders are chained up and no gas bottles are stored near escape routes	NA	Some sites do not have gas bottles	0
		Maximum this page 70 + 4	31

External Annual Audit for Report & Certification - P3
You may show this page to client - but not issue

You may show this pag	ge to ci	ient - but not issue	
Fire Safety and Evacuation Regs 2006 Fire & Emergency NZ Evacuation Procedures and Evacuation Schemes 2018	No/Yes or N/A	Recommendations on any Action to be taken	Score 0-5
30. Decanting of all dangerous goods complies with the regulations - labels and data sheets on hand.	YES	Each type kept separate, no diesoline near animal pellets it can create huge explosion.	5
31. Waste bins are not placed near any grinders or welding bays where sparks could enter them	YES	Some sites have no grinders or no welding	5
32. The air extraction system or windows allow for dangerous vapours to be released quickly and effectively	YES	Dangerous fumes must be evacuated quickly every day	5
33. Extinguishers (hose reels if any) are checked periodically and have proper signs and are easily accessible at all times	Yes	Quarterly check is minimum for all Warden checking, monthly = Health Safety Act	5
34. Instructions are issued to staff to ensure that no flammable goods are being stored under stairways or in cupboards	VES	Itall area Ask for instructions / check	5
35. There is an evacuation checklist tally board or similar means of tally check	YES	Tallies to be made of a) disabled, b) staff, c) visitors, d) contractors	5
36. Hazardous goods signs are placed in all appropriate places or near any highly flammable or volatiles	YES	Check for signs	5
37. There are no smoking signs in areas where goods are packed and or unpacked	YES	No smoking signs needed	5
38. There is an assembly area at least 70 metres away with a sign that clearly indicates it to staff	. , _	Sparks travel 80 metres	2
39. Staff are instructed never to park cars on top of a local fire hydrant	N/a	Some sites do not have hydrants but they have water tanks/pools to be reached	0
40. Passageways are kept clear of obstructions or things or rubbish so that all occupants can evacuate without delay	1 4 2 1	Major fines apply for failure to keep egress routes clear	5
41. Several key staff have been trained in how to do the fireman's lift or the drag	ua	Can save lives	2
42. There is AED for resuscitation available on site or <u>nearby</u> also trained operators.	Wla	Not all sites have AED defibrillators available/nearby	0
43. There are sufficient safety officers with current certificates – 1 per 5 staff	TBA	Safety Officers are to find hazards, risks and dangers	· ·
		Maximum this page 70	149

External Annual Audit for Report & Certification - P4
You may show this page to client - but not issue

You may show this pa	ige to	client - but not issue	
Fire Safety and Evacuation Regs 2006 Fire & Emergency NZ Evacuation Procedures and Evacuation Schemes 2018	No/Yes or N/A	Recommendations on any Action to be taken	Score 0-5
44. All building tenants or lessees (if any) are informed of legal requirements and they have people trained every 2 years	Ma	Some sites have no tenants	0
45. There is an external audit by a trained and qualified person who is able to produce a report for our insurer yearly	Ves	Report can be for underwriter	5
46. All heat and smoke detectors are checked quarterly to ensure that they will work to warn staff on time	YES	Detectors to be tested monthly HSE Act, quarterly Fire Regs	5
47. Our Insurer allows us a major discount as we have high quality systems in place and a professional audit annually	TBA	Underwriters do actuarial analysis	/
48. Our electrical switchboards are checked annually by a qualified electrician with tagging of all electrical tools plus electrical machinery and cables	VÉS	Some fuses are not adequate, & will cause fires. You may issue another 2 bonus points For proper annual checks	5
49. Waste bins or big skips are kept away from buildings by 3-5 metres.	YES	Some sites have no big skips	5
50. There is steel bin with steel lid for oily rags disposal or things that can ignite	YES	Bucket of water 4 oily rags ok	5
51. Volatiles / flammables are not stored in direct sunlight even if in small amounts	YES	Can make fires	5
52. Office equipment is switched off daily	YES	Can make fires	5
53. Sprinklers (if any) or automatic systems are maintained in good operating status & checked periodically	NO	Some sites have none	0
54. Our main escape route or exit has door/s that open outwards not inwards	YES	Legal requirement Bldg Act	,5
55. Procedures are in place to identify generation of static and to control it	YES	Anti static spray for clothes and or carpets	5
56. Staff instructed never to place things on top of a convection/space heater	YES	Keep away from curtains also	5
57. Staff instructed to ensure that gas heaters are properly switched off and also to ensure that they are not leaking	NA	Some sites have no gas heaters, & no barbecues Inside or outside	0
		Maximum this page 70 + 2	57

External Annual Audit fo You may show this pa	ige to c	lient - but not issue	
Fire Safety and Evacuation Regs 2006 Fire & Emergency NZ Evacuation Procedures and Evacuation Schemes 2018	No/Yes or N/A	Recommendations on any Action to be taken	Score 0-5
58. Staff instructed to switch off welders, vats, grinders, cutters and all sources of flames when evacuating	Ma	Some sites have none of these	0
59. Staff instructed never to place boxes on the top shelf of a store room near the lighting system/s	VES	Same applies re insul / bats	5
60. There are timing devices on cookers to minimise the risk of fire and staff are instructed to use the timing devices	h/a,	Timers can switch off circuits.	Ō
61. Staff instructed to shut windows and doors if possible in the event of a real evacuation other than a drill	VES	FENZ don't agree but the Insurance Company will.	5
62. Welding, gas cutting or flames or smoking is not allowed near any storage area for chemicals	N/ca	Control of flames/smoking.	b
63. Wardens are trained in how to check a free standing burner or a patio heater		Wardens still must be trained even if no such risks and for checking all items listed	5
64. Wardens are trained in how to check switchboards and to look for signs of overheating or potential fire (black marks)	Ma.	Black marks mean fire soon.	D
65. Staff trained to not have glass bottles parked on a window sill in direct sun	YES	Could be mobile phone or could be vase or vause	5
66. All permanent staff are given bi-annua training in fire prevention methods	TBA	All Perm Staff not just Wardens	1
67. Flammable packing material correctly stored after hours to eliminate fire risk	YES	Combustibles to be controlled.	5
68. Long grass is removed from around the building at regular intervals and hedges - if any, are trimmed	ÆS	Long grass is major risk.	3
69. We have two qualified first aiders / ČPR responders for every 20 staff	XES /	This is required by law.	5
70. Staff instructed to uncoil long electrica cables prior to use to avoid heating / fire	" VEJ	Big cables must not be left on for hours at a time (fire risk)	5
71. Staff instructed to keep machinery in good order and not to let motors overheat	YES	Lubricated machinery	5
72. Saw blades or cutters kept sharp to minimise sparks. No flying sparks from electrical sockets when disconnect plugs.	WA	Sharp blades prevent sparks	0
0.000.000.000.000		Maximum this page 75	14

Maximum this page 75

External Annual Audit for Report & Certification	- P6
You may show this page to client - but not issu	ıe

You may show this pa	ge to c	lient - but not issue	
Fire Safety and Evacuation Regs 2006 Fire & Emergency NZ Evacuation Procedures and Evacuation Schemes 2018	No/Yes or N/A	Recommendations on any Action to be taken	Score 0-5
73. Staff instructed not to put large light bulbs into shades designed for small bulbs	VES	Will grossly overheat	5
74. Recessed ceiling lights not to be in contact with the insulation materials. Wall lights have no drapes or curtains nearby	YES	Can catch fire / create fire	5
75. Buildings are properly secured at the end of day to reduce risk of entry and arson or burglary	YES	Roller doors have pins	5
76. Rubbish fires only when no fire ban and in proper incinerator or drum and a hose is handy	Ma	Fire permits now needed	0
77. Staff instructed not to impede access of Ambulance or FENZ or Police in the event of evacuation.	XES	Keep access free all times	5
78. Staff instructed not to return to building for keys or valuables and not to try and remove their car	XES	Cars not to be moved	5
79. Escape route doors must be openable from the interior at all times, padlocks are never to be used when persons present	XES	Legal requirements	5
80. Staff instructed never to park car in front of emergency escape doors	VES	Don't obstruct swimming pool or water tank/reservoir	)
81. Aerosol containers & similar are never stored near a source of heat or cooker	nla	Can easily explode	0
82. There are no shrubs close to the building that would allow concealment for arsonists	VES	Minimise risk of burglary	5
83. Where cooker with elements at work fire blanket should be available. Toasters must be kept away from other items.	N/a	Blankets can stop fires	0
84. Building separations should be right to the top of the roof not just the ceiling	Na	Building code applies	U
85. Security lighting is provided or small light left on where it will deter burglars	VES	Frightens all burglars	5
86. What is maximum fine under the new FENZ Act and Regulations 2018? It was \$200 previously under old Regulations	YES	New fines \$150k have teeth & can be linked to Building Act Max fine FENZ Act \$600k	5
		Maximum this page 70	50

External Annual Audit fo	and the first term	· 新· 大· 大· 大· 大· 大· 大· 大· · · · · · · ·	
You may show this pa	ge to c	lient - but not issue	
Fire Safety and Evacuation of Buildings Regulations 2006 Fire & Emergency NZ Evacuation Procedures and Evacuation Schemes 2018	No/Yes or N/A	Recommendations on any Action to be taken	Score 0-5
87. Security fencing is provided to keep out thieves and vandals.	-TBA	Underwriters want security	1
88. All visitors are escorted at our site. Hi vis vests and PPE are made available to them.	· Hon	Legal requirement	5
89 We have formal policies to prevent smoking in the workplace.	w/a	Policies on noticeboards for no drugs and no smoking	2
90. We have drug and alcohol policies and also anger management policies to reduce risk of severe damage or arson.	wa	No drugs signs present	2
Bonus question – For sites that send in a formal report to FENZ every 6 months after they have a trial evacuation award 5 marks.	nla	Legal requirement	D
Bonus question – all large waste bins have locked lid to prevent arson and or all chemical areas are locked up - 5 marks	Ma	Underwriters require this	D
	Max	imum this part 20 plus 10 bonus	10
COMPULSORY QUESTIONS 0-20 each 91. There is a certificate at reception to state there is an operative scheme approved by FENZ Fire Service	YES	If no certificate then score 0 If letter coming 10 Certificate at reception 20	20
92. Wardens have completed proper training course for <u>all regulations</u> not just evacuation or fire extinguisher use.	ula	Extinguisher or Evac only 5 Extinguishers & Evac 10 Formal course 60 pages 20	10
93. If Deputy Wardens have also completed training all regulations - score as for Q92.	ttla	Extinguisher or Evac only 5 Extinguishers & Evac 10 Formal course 60 pages 20	10
94. Compartments in all buildings are constructed to allow for at least one hour of fire rating. E.g. solid doors and double GIB cladding or concrete dividing walls	VES	Ordinary walls score 0 Solid doors between areas 10 Solid doors & concrete wall 15	20
95. Do you have both types of smoke detectors installed or do you have the dual ones available (First Alert or Kidde) for both Photo-electric & Ionization/smoke	YES Type Comp Max 100	Real fire wall/doors score 20  No detectors score 0  One type only score 10  Both types or dual score 20	25
96. All managers and Wardens and Permanent Occupiers trained in all of the Fire Safety and Evac Regulations	Ma	No formal training yet 0 Only Wardens trained 10 All Wardens/Permanents 20	6
Identify all GENUINELY NOT APPLICABLE e.	a no lifte	Maximum this page 150	toves

Identify all <u>GENUINELY</u> NOT APPLICABLE e.g. no lifts, no call points, no free standing sto no saw blades, no stairways, no welding, no decanting, no gas bottles. To qualify for well managed risk or considerably reduced insurance premium it is necessary to score 80% of the presently required plus all potentially possible items. Instructed means instructed in writing.

## Client Review/Audit Work Sheet

To be completed by Manager Auditor during the audit process & send to Summit. If client on service contract, delete this page.

COMPANY/CLIENT NAME RUSE Up Trust	
CLIENT ADDRESS 29 Rosella, Road Mangere E	ast
CONTACT PERSON TWEN haufalle TELEPHONE (69)2	768 127
CLIENTEMAIL ADDRESS adminarise uptrustiona. 12 REF NO 115	-
MANAGER AUDITOR NAME Nevina House Date 7/12/18	
PART A MANAGER AUDITOR FEES 100%	30.00
SET UP VISIT FEE LOCAL TRAVEL UPTO 30K EACH WAY range \$29 to \$49	\$
LONG DISTANCE TRAVEL AT \$69 PER HOUR FOR HOURS.	\$
POSTPONED APPOINTMENT SITE VISITED (CLIENT OR DEPUTY UNAVAILABLE) \$79 SIGNAGE SURVEY free or \$33	\$
PART B CONSULTANT 33% AND HEAD OFFICE 66%	
Formal Scheme medium/large site. This would be for sites with hazardous goods under 10	
staff, plus all sites of 10+ staff or where 100 people can gather - shop or building. Set fee of \$299 + online help or Head Office assist (3-5 hours) at \$ 119 + or p.h.	\$
SELF AUDIT Consultant to encourage self audit by Head Warden at process fee \$99	\$
PART C AUDITS AND TRAINING 50/50 OR 55/45 IF PAID ON THE DAY	
BROKER OR AGENT FIRE SAFETY ANNUAL AUDIT systems and site then report (2 hours	\$
approx) \$269 + or This is for a Broker / Agent attending, doing a tour of the site and	\$
formal audit for FENZ levy & insurance purposes. Extra hours x \$	\$ <u></u>
WARDEN MANAGER ROLES HOURLY RATES \$27 - \$40	
EVACUATION DRILLS 6 monthly attendances and FENZ report \$99 or plus travel BI-ANNUAL Fire Warden Training 2 wardens plus 2 perm staff trained per dept, floor or	\$
small site. \$99 or \$ per person. Plus Head Warden & Deputy HW also Emergency	\$
Manager \$ Minimum 5. One site copy of training course per 2 Wardens to be provided.	\$
PART D HEAD OFFICE FEES 100%	
HEAD OFFICE TO PROCESS A PROFESSIONAL AUDIT REPORT	\$119.00
COURIER FEES FOR DESPATCH TO CLIENT (IF APPLICABLE) N.I. \$17 S.I. \$19	\$ \$25.00
UNFRAMED NEW CERTIFICATE FOR CLIENT WARDEN CERTIFICATES AT \$25 EACH, STATE NUMBER	\$
TOTAL EXCLUSIVE GST	\$
ADD GST	\$
TOTAL INCLUSIVE GST	\$
THE MANAGER/AUDITOR WILL INCLUDE PERSONAL INVOICE TO SUMMIT SYSTEMS LTD	).
THIS FORM SIGNED BY THE AGENT/AUDITOR/CLIENT - TO AUTHORISE BILLING (SIGNATURE) M FLANCE DATE 17.12.18	
MANAGERIAUDITOR MAY COPY THIS PAGE OR TEAR OFF THIS PART FOR VALI	IED CLIENT
INTERIM RECEIPT FOR CLIENT SSL GST No. 62.044.879 DIRECT CREDIT 03 0830 C	
This is not a tax invoice until payment is made in full. RECEIVED \$	,
Signed by MANAGER/AUDITOR A Company Date Date Date Date Date Date Date Date	e / /

Fire Safety Regulations - Site Audit
Copyright © Summit Systems Ltd 1993-2018. All rights reserved. Licence No GPC7000FR Version 2018

Der Invoice sent to like Up That

## THE CONSULTANT OR AUDITOR SHOULD ISSUE A COPY OF THIS PAGE TO CLIENT

ISSUE A COPY OF THIS PAGE TO CLIENT
NAME OF CLIENT/COMPANY
CLIENT ADDRESS
TOTAL ITEMS FOR THIS AUDIT WORTH 586 OF THESE 16 ARE BONUS AND 60 MARKS MAYBE NOT APPLICABLE YOU MAY IGNORE OR DISCARD OR N/A (12 QUESTIONS) ALL OTHER ITEMS ARE TO BE COUNTED
PAGE 1 TOTAL PAGE 2 TOTAL PAGE 3 TOTAL PAGE 3 TOTAL PAGE 5 TOTAL PAGE 6 TOTAL PAGE 6 TOTAL PAGE 7 TOTAL Bonus max 16
TOTAL POTENTIAL SCORE 586 (includes 60 n/a 16 bonus) TOTAL ACTUAL 3 / 1
RATING SYSTEM IN RELATIONSHIP TO SCORE  E GRADE 0 - 25% VERY POOR AND MOST UNSATISFACTORY  D GRADE 26 - 49% INADEQUATE AND UNSATISFACTORY  C GRADE 50 - 60% ONLY FAIR TO AVERAGE STANDARD  B GRADE 61 - 69% QUITE GOOD AND SATISFACTORY STANDARD  B + GRADE 70 - 75% VERY GOOD STANDARD IS ACHIEVED  A - TO A GRADE 76 - 89% VERY GOOD TO EXCELLENT STANDARD  A + 90% PLUS FIRST CLASS STANDARD AND SHIELD AWARDED  THE GRADING FOR THIS AUDIT WAS
Policies have already been actional. Reviews are been dure on a repulse been
The training of Fire Wordens are goy to be done in Term 1 2019.
SIGNATURE OF CONSULTANT M Howe DATE 20/12/13/ Address DATE
COMPLETION OF WORK IS SUBJECT TO AGREED TERMS IN THE LICENCE AGREEMENT, BUT IF NO LICENCE Quotations not accepted at the point of offer, expire after 30 days. Uptake of a quotation after expiry will incur additional costs. Appointments cancelled less than 48 hours prior to agreed time may be charged for. Any debt recovery charges will be charged to the Client on all overdue accounts including interest at the rate of 2% per month cumulative and 2% per month also applies for term payment. The full price is still payable on time - even if training is delayed by the Client. Summit and the Broker or Agent are not responsible for accuracy and completeness of this audit log. The Client will be responsible for the obtaining of legal advice from its legal advisors as may be required. The Client shall not enter into a private consultancy arrangement for Fire or Safety Regulations & must advise Summit immediately of any attempt to do so.
THE AGENT OR CONSULTANT IS TO PLEASE FORWARD THIS DOCUMENT TO SUMMIT SYSTEMS LTD (WHEN COMPLETED), WITH AUDIT WORK SHEET PLUS COPY OF CLIENT DISK FOR UPDATING. A copy of this report may be released to FENZ and/or Insurance Company for information and records,
SIGNED BY CLIENT /OR BY CONSULTANT / Comments (if any) for Summit Systems Ltd. Client or Consultant may phone 09 438 7555 or 7550.