

# SMS Incident Report

21/02/2022 07:28:50

## Summary

**CAD Number** F3407790 **Status** Closed

**Station** Milton Volunteer Fire Brigade

**Incident Started** 25/01/2022 13:13:47 **Incident Ended** 25/01/2022 13:33:38

**Incident Type** 7101: False Alarm: Malicious K-46-4

**Common Name** OTAGO CORRECTIONS FACILITY BUILDING 35 HIGH SECURITY WINGS KL

**Address** MA34 / 62 Narrowdale Road Milburn

**Alarm Method** Sprinkler PFA Call **Alarm Level** 1

**PFA Number** 611445

**Zone** 36538200

**Map Grid E** 1368996 **Map Grid N** 4891938


**First Caller** **First Caller Contact**

**Incident Closed** 25/01/2022 14:31:12

**Report Completed** 8:14, Thur 27 Jan 2022 by [REDACTED]

## Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
MILT531	P1	13:14:03 25 Jan 2022	13:18:29 25 Jan 2022	13:25:03 25 Jan 2022	13:37:55 25 Jan 2022
MILT537	PR	13:14:04 25 Jan 2022			13:35:39 25 Jan 2022
MOSG311	P1	13:24:34 25 Jan 2022	13:26:04 25 Jan 2022		13:34:03 25 Jan 2022



## Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
MILT531	00:00:16	00:11:00	00:11:16	00:24:08
MILT537	00:00:17			00:21:52

MOSG311	00:10:47		00:20:16
---------	----------	--	----------

### Message Log

Time	Message
13:13:47	AL: 611445 13:13:47 INITIAL - ALARM
13:13:47	PANEL: PLANT ROOM
13:13:47	** LOI search completed at 25/01/22 13:13:47
13:13:56	** Recommended unit MILT531 for requirement PUMP (>5.6 km)
13:13:56	** Recommended unit MILT537 for requirement PUMP (>5.5 km)
13:13:58	Station Selcal used to Initiate Alerting. (MILT531 at 3653 MILTON 195531)
13:13:59	Station Selcal used to Initiate Alerting. (MILT537 at 3653 MILTON 195531)
13:14:01	** PFA/CPN search completed
13:14:04	ALERTING_COMPLETED MILT531
13:14:04	ALERTING_COMPLETED MILT537
13:14:08	ACCESS NO CURRENT: [REDACTED]
13:14:17	AL: PAGING ACK RECEIVED FROM STATION 3653 at 01-25-22 13:14:17
13:18:29	Unit MILT531 [ K1 : PROCEEDING TO INCIDENT]
13:23:19	Unit MILT531 [ KC : UNIT CALLING]
13:24:08	Unit MILT531 [ SITREP : ] WE DONT HAVE ENOUGH TO MAN MILT537 TURN OUT A SECOND
13:24:08	APPLIANCE
13:24:21	** Requirement PUMP added for alarm level 1
13:24:27	** Recommended unit MOSG311 for requirement PUMP (>35.3 km)
13:24:31	PA Selcal used to Initiate Alerting. (MOSG311 at 3631 MOSGIEL 195311)
13:24:34	ALERTING_COMPLETED MOSG311
13:25:03	Unit MILT531 [ K77 : NOTHING SHOWING]
13:26:04	Unit MOSG311 [ K1 : PROCEEDING TO INCIDENT]
13:32:40	Unit MILT531 [ KC : UNIT CALLING]
13:33:38	Unit MILT531 [ K46-4 : STOP MESSAGE: FALSE ALARM MALICIOUS] [REDACTED] SPRINKLE
13:33:38	R ACT BY [REDACTED]
13:34:03	Unit MOSG311 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
13:34:11	Unit MOSG311 [ K28 : RESPONSE NO LONGER REQUIRED]
13:35:39	Unit MILT537 [ K7 : AT NORMAL STATION]
13:37:55	Unit MILT531 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
14:31:12	** Assigned Result Code: SPRNKLR, Detailed Event Type: 7100

---

**Incident**

CAD Number F3407790  
Incident Reporter [REDACTED]  
Incident Controller  
Distance Travelled (km)  
Delay In Receiving Call

---

**False Alarm**

False Alarm Type Sprinkler  
Good Intent Type Human Intervention | Malicious activation (detector tampered with)  
Additional comment [REDACTED] tampered with sprinkler head

---

**Property Details**

Occupant  
Building Owner  
General Property Use Prison, Correctional institution  
Special Property Use Prison [REDACTED]  
Purpose Group

---

**Actions**

Persons Reported Trapped  
Evacuation Status  
Action Prior 1  
Action Prior 2  
Action Taken Investigation Only (Non-Fire related)

---

**Civilians**

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	0

---

**Comments**

1/28/2022 6:40:05 AM

Reporter Comments

[REDACTED] tampered with SPK head

Released under the Official Information Act