

National Headquarters Fire and Emergency New Zealand National Headquarters Spark Central, Level 7 42-52 Willis Street Wellington Central Wellington 6011

Phone +64 4 496 3600

1 August 2023

Frank By email: fyi-request-23157-0cfed6e2@requests.fyi.org.nz

Tēnā koe

Information Request – Seismic assessment priorities

I refer to your official information request dated 19 June 2023 asking for the following information.

please provide a response/any information that outlines the timeframe -within which all stations will obtain a DSA (acknowledging some may not need a DSA due to their size/construction) and how those DSAs are being prioritised - within which all stations identified as below your identified threshold of 67%NBS IL4 will be strengthened/replaced and how this work is being prioritised.

Could you also confirm whether there is a process to pro-actively notify the local TA where a station is identified as less than 34%NBS?

When a Territorial Authority approaches us to undertake a detailed seismic assessment of a property, due to a preliminary earthquake prone building assessment we will meet the required timeframe. There is not a formal requirement or a programme to undertake DSAs on all of our buildings. However, we are proactively undertaking assessments of our own properties, which include seismic assessments, as part of our asset management practice. These assessments are undertaken to an IL4 standard.

Where a Territorial Authority approaches us to complete a detailed seismic assessment, we provide them with a copy of the completed assessment if it already exists.

You have the right to seek an investigation and review by the Ombudsman of this decision. Information about how to make a complaint is available at <u>www.ombudsman.parliament.nz</u> or freephone 0800 802 602.

Nāku noa nā

Sarah Sinclair Deputy Chief Executive, Organisational Strategy and Capability Development

