



RE: Melanesia Rd - Test Pits results

From [redacted]@downer.co.nz>  
Date Wed 3/11/2026 1:02 PM  
To Jesmina Yunus Patel (AT) <JesminaYunus.Patel@at.govt.nz>; Alex Schultz (AT) <Alex.Schultz@at.govt.nz>; Michael Deadman (AT) <Michael.Deadman@at.govt.nz>; [redacted]@downer.co.nz  
Cc [redacted]@downer.co.nz>; [redacted]@downer.co.nz>; [redacted]@downer.co.nz>; [redacted]@downer.co.nz>; [redacted]@downer.co.nz>

1 attachment (3 MB)  
20260305\_130342.jpg;

**This Message Is From an External Sender**

Report Suspicious

Looks suspicious? Please click the 'Report Suspicious' button for automatic analysis.

Hi Jesmina,

As discussed over the phone, we will proceed with the digout that was marked onsite at the TP1 location.

For the two locations where TP2 and TP3 were undertaken, [redacted] could you please arrange to carry out the required pre-seal repairs.

Please let me know if you require any further information.

Regards

[redacted]  
**Contract Engineer - CAPEX**  
Transport and Infrastructure



M | [redacted]  
E | [redacted]@downer.co.nz  
645 Great South Rd, Penrose  
Auckland Auckland (AUK) 1061  
[www.downergroup.co.nz](http://www.downergroup.co.nz)



From: [redacted]  
Sent: Wednesday, 11 March 2026 8:47 am  
To: Jesmina Yunus Patel (AT) <JesminaYunus.Patel@at.govt.nz>; Michael Deadman (AT) <michael.deadman@at.govt.nz>

**Subject:** Melanesia Rd - Test Pits results

Morning Jesmina,

Please find the attached test pit results for Melanesia Rd.

Could you please confirm whether we can proceed with the digout at the TP1 location as marked, and advise if any additional digouts are required at the TP2 and TP3 locations?

Please let me know if you have any questions.

Regards

**Contract Engineer - CAPEX**  
Transport and Infrastructure



M | [REDACTED]  
E | [REDACTED]@downer.co.nz

645 Great South Rd, Penrose  
Auckland Auckland (AUK) 1061

[www.downergroup.co.nz](http://www.downergroup.co.nz)

