

# SMS Incident Report

28/05/2017 20:18:02


## Summary

**CAD Number** F2291990 **Status** Closed  
**Station** Avondale Station  
**Incident Started** 20/04/2017 03:48:31 **Incident Ended** 20/04/2017 08:58:16  
**Incident Type** 1101: Structure fire with damage  
**Common Name**  
**Address** 10 COPSEY PLACE AVONDALE  
**Alarm Method** 111 Telephone **Alarm Level** 3  
**PFA Number**  
**Zone** 146001  
**Map Grid E** 1749821 **Map Grid N** 5916881  
**First Caller** [REDACTED] **First Caller Contact** [REDACTED]  
**Incident Closed** 20/04/2017 11:07:16  
**Report Completed** 8:58, Wed 10 May 2017 by Chris Todd

## Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
AVON607	PR	03:49:28 20 Apr 2017	03:51:08 20 Apr 2017	03:55:10 20 Apr 2017	09:05:34 20 Apr 2017
TEAT664	PM	03:49:32 20 Apr 2017	03:51:33 20 Apr 2017	03:56:31 20 Apr 2017	08:43:48 20 Apr 2017
GLEN641	P1	03:49:35 20 Apr 2017	03:51:13 20 Apr 2017	03:59:02 20 Apr 2017	08:53:46 20 Apr 2017
AUCK205	HPNP	03:58:08 20 Apr 2017	04:00:07 20 Apr 2017	04:09:12 20 Apr 2017	06:02:29 20 Apr 2017
AUCK2018	CUHU	03:58:09 20 Apr 2017	04:00:33 20 Apr 2017	04:10:22 20 Apr 2017	07:01:17 20 Apr 2017
TEAT662	P2	03:58:12 20 Apr 2017	04:05:00 20 Apr 2017	04:11:01 20 Apr 2017	06:44:32 20 Apr 2017
WEST671	P1	03:58:15 20 Apr 2017	04:00:01 20 Apr 2017	04:12:25 20 Apr 2017	06:33:15 20 Apr 2017
AUCKOSU2	SV	04:00:30 20 Apr 2017	04:00:45 20 Apr 2017	04:12:37 20 Apr 2017	06:57:43 20 Apr 2017
AUCK207	PR	04:09:00 20 Apr 2017	04:10:56 20 Apr 2017	04:19:08 20 Apr 2017	05:42:11 20 Apr 2017
AUCKCITY4	OF	04:01:31 20 Apr 2017	04:06:27 20 Apr 2017	04:21:12 20 Apr 2017	07:03:19 20 Apr 2017
HEND657	PR	04:09:21 20 Apr 2017	04:12:09 20 Apr 2017	04:21:20 20 Apr 2017	05:56:23 20 Apr 2017
AUCKCITY2	OF	03:59:02 20 Apr 2017	04:01:57 20 Apr 2017	04:21:26 20 Apr 2017	06:19:02 20 Apr 2017
PARN255	HPNP	04:08:50 20 Apr 2017	04:11:05 20 Apr 2017	04:22:16 20 Apr 2017	09:28:11 20 Apr 2017
ELLE274	PM	04:08:53 20 Apr 2017	04:10:34 20 Apr 2017	04:24:24 20 Apr 2017	05:45:55 20 Apr 2017
AVON6015	BA	04:08:56 20 Apr 2017	04:18:00 20 Apr 2017	04:24:39 20 Apr 2017	09:05:45 20 Apr 2017
WEST672	P2	04:09:03 20 Apr 2017	04:14:11 20 Apr 2017	04:27:30 20 Apr 2017	06:00:12 20 Apr 2017

MTRO621	P1	04:11:15 20 Apr 2017	04:11:58 20 Apr 2017	04:30:32 20 Apr 2017	08:16:13 20 Apr 2017
WAITEMATA3	OF	04:11:43 20 Apr 2017	04:14:22 20 Apr 2017	04:42:45 20 Apr 2017	06:13:39 20 Apr 2017
FIACITY4	FSO	04:07:52 20 Apr 2017	04:44:07 20 Apr 2017	04:44:09 20 Apr 2017	10:55:22 20 Apr 2017
AUCKOSU4	CV	04:08:53 20 Apr 2017	04:38:38 20 Apr 2017	04:58:35 20 Apr 2017	07:02:39 20 Apr 2017
AUCKOSU1	SV	04:17:21 20 Apr 2017	06:21:28 20 Apr 2017	06:42:27 20 Apr 2017	08:08:38 20 Apr 2017
COUNTIES1	OF	04:17:21 20 Apr 2017	04:17:23 20 Apr 2017		04:22:22 20 Apr 2017



**Elapsed Times**

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
AVON607	00:00:57	00:05:42	00:06:39	05:17:03
TEAT664	00:01:01	00:06:59	00:08:00	04:55:17
GLEN641	00:01:04	00:09:27	00:10:31	05:05:15
AUCK205	00:09:37	00:11:04	00:20:41	02:13:58
AUCK2018	00:09:38	00:12:13	00:21:51	03:12:46
TEAT662	00:09:41	00:12:49	00:22:30	02:56:01
WEST671	00:09:44	00:14:10	00:23:54	02:44:44
AUCKOSU2	00:11:59	00:12:07	00:24:06	03:09:12
AUCK207	00:20:29	00:10:08	00:30:37	01:53:40
AUCKCITY4	00:13:00	00:19:41	00:32:41	03:14:48
HEND657	00:20:50	00:11:59	00:32:49	02:07:52
AUCKCITY2	00:10:31	00:22:24	00:32:55	02:30:31
PARN255	00:20:19	00:13:26	00:33:45	05:39:40
ELLE274	00:20:22	00:15:31	00:35:53	01:57:24
AVON6015	00:20:25	00:15:43	00:36:08	05:17:14
WEST672	00:20:32	00:18:27	00:38:59	02:11:41
MTRO621	00:22:44	00:19:17	00:42:01	04:27:42
WAITEMATA3	00:23:12	00:31:02	00:54:14	02:25:08
FIACITY4	00:19:21	00:36:17	00:55:38	07:06:51
AUCKOSU4	00:20:22	00:49:42	01:10:04	03:14:08
AUCKOSU1	00:28:50	02:25:06	02:53:56	04:20:07
COUNTIES1	00:28:50			00:33:51

**Notifications**

Date	Time	Party Notified
20 Apr 2017	03:55:22	VECTOR
20 Apr 2017	03:56:17	VECTOR ADVISE THEY WILL CALL BACK WITH AN ETA ONCE THEY HAVE SOMEONE ON THE
20 Apr 2017	03:56:35	OSU AUCKLAND BY ADHOC PAGE
20 Apr 2017	03:56:39	AAC AUCKLAND CITY / AAC MACKERETH RE-K99 ARRIVAL..
20 Apr 2017	03:57:29	OSU AUCKLAND PER PAGER RE 2ND ALARM BLDG FIRE
20 Apr 2017	03:57:41	VECTOR RE: 2ND ALARM
20 Apr 2017	03:58:42	AAC AUCKLAND CITY / AAC MACKERETH RE-2ND ALARM..
20 Apr 2017	03:58:52	AAC WOON ACK PAGER - RESPONDING..
20 Apr 2017	04:00:09	AAC MACKERETH ACK PAGER - UPDATED..
20 Apr 2017	04:01:50	AAC CALLISTER ACK PAGER - RESPONDING..
20 Apr 2017	04:03:13	ICU.AUCKLAND GREATER ALARM ATTENDANCE VIA E-MAIL (.DOC AND .PDF)
20 Apr 2017	04:08:03	VECTOR RE: 3RD ALARM
20 Apr 2017	04:08:14	FIACKCITY4 (RUSSELL DICKSON) TURNED OUT AS PER 3RD ALARM
20 Apr 2017	04:08:35	VECTOR OF THIRD ALARM
20 Apr 2017	04:09:20	VECTOR ETA 20-25MINS
20 Apr 2017	04:09:50	AUCKLAND CITY AREA 3RD ALARM RE-3RD ALARM..
20 Apr 2017	04:10:11	AC MONRAD / AAC MACKERETH RE-3RD ALARM..
20 Apr 2017	04:11:59	AAC MACKERETH ACK PAGER - RESPONDING..
20 Apr 2017	04:12:44	COUNTIES1 AC MONRAD ACK 3RD ALARM PAGE - WILL RESPOND
20 Apr 2017	04:13:31	FIAC CITY4 WILL BE RESONDING BY WAY OF HARBOUR BRIDGE DUE TO MWAY CLOSURE
20 Apr 2017	04:14:29	ICU.AUCKLAND GREATER ALARM ATTENDANCE (3RD ALARM) VIA E-MAIL (.DOC AND .PDF)
20 Apr 2017	04:14:51	HENDERSON VOLUNTEER OFFICER ██████████ REQUESTS HEND651 K25'D TO STATION FOR
20 Apr 2017	04:15:48	CM STEVENSON ACK PAGER..
20 Apr 2017	04:17:15	AUCKCITY1 (AC RICHARD TWOMEY) ACK'D PAGE
20 Apr 2017	04:26:15	HENDERSON FIRE ADVISE HEND651 MANNED ON STATION @ 0426
20 Apr 2017	05:58:00	HENDERSON FIRE - HEND651 RELEASED FROM COVER MOVE..WILL WAIT FOR HEND657 GET
20 Apr 2017	06:35:46	ALB851 221 AND 311 ADV TO HEAD HOME

**Message Log**

Time	Message
03:49:14	INC INFO: BUILDING FIRE
03:49:15	** LOI search completed at 20/04/17 03:49:15
03:49:20	** Recommended unit AVON607 for requirement PUMP (>2.4 km)
03:49:20	** Recommended unit TEAT664 for requirement PUMP (>3.6 km)
03:49:20	** Recommended unit GLEN641 for requirement PUMP (>4.0 km)

03:49:29 @MADISON QUALITEX LAUNDRY

03:50:08 ARRIVED AT WORK AND CAN SEE FLAMES FROM THE ROOF

03:51:09 Unit AVON607 [ K1 : PROCEEDING TO INCIDENT]

03:51:14 Unit GLEN641 [ K1 : PROCEEDING TO INCIDENT]

03:51:33 Unit TEAT664 [ K1 : PROCEEDING TO INCIDENT]

03:52:46 AL: PAGING ACK TIMED OUT FOR STATION: 1466 at 20/04/17 03:52:46

03:55:10 Unit AVON607 [ K99 : PROPERTY FIRE WELL INV]

03:55:21 --+

03:56:17 WAY

03:56:31 Unit TEAT664 [ K2 : IN ATTENDANCE AT INCIDENT]

03:57:12 Unit AVON607 [ KP : PRIORITY MESSAGE]

03:57:26 AMBO EVENT 0060-1-2017/04/20-FIR LINKED AT 20/04/2017 03:57:26

03:57:30 FIR2POL: NOTIFICATION OF 2ND ALARM BUILDING FIRE

03:57:32 FIR2AMB: NOTIFICATION OF 2ND ALARM BUILDING FIRE

03:57:32 Unit AVON607 [ KP : PRIORITY MESSAGE] TRANSMIT 2ND ALARM

03:57:52 INC INFO: BUILDING FIRE - 2ND ALARM TX

03:58:00 \*\* Alarm level updated to 2

03:58:00 \*\* Recommended unit AUCK205 for requirement AERIAL (>7.5 km)

03:58:00 \*\* Recommended unit AUCK2018 for requirement COMU (>7.5 km)

03:58:00 \*\* Recommended unit TEAT662 for requirement PUMP (>3.6 km)

03:58:00 \*\* Recommended unit WEST671 for requirement PUMP (>9.2 km)

03:59:03 Unit GLEN641 [ K2 : IN ATTENDANCE AT INCIDENT]

03:59:58 FIR2POL: NEGATIVE

04:00:01 Unit WEST671 [ K1 : PROCEEDING TO INCIDENT]

04:00:08 Unit AUCK205 [ K1 : PROCEEDING TO INCIDENT]

04:00:33 Unit AUCK2018 [ K1 : PROCEEDING TO INCIDENT]

04:00:40 Unit AUCKOSU2 [ K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]

04:00:45 Unit AUCKOSU2 [ K39 : RE-TRANSMIT YOUR CURRENT STATUS]

04:00:46 Unit AUCKOSU2 [ K1 : PROCEEDING TO INCIDENT]

04:01:04 Unit WEST671 [ KC : UNIT CALLING]

04:01:27 AL: PAGING ACK TIMED OUT FOR STATION: 1466 at 20/04/17 04:01:27

04:01:33 Unit WEST671 [ SITREP : ] WE ARE DELAYED DUE TO THE MOTORWAY CLOSURE

04:01:58 Unit AUCKCITY2 [ K1 : PROCEEDING TO INCIDENT]

04:02:58 COVERING UNIT MTRO621 DISPATCHED TO STATION AVONDALE

04:02:58 D0710063

04:05:01 Unit TEAT662 [ K1 : PROCEEDING TO INCIDENT]

04:05:12 Unit AVON607 [ KC : UNIT CALLING]

04:06:10 Unit AVON607 [ SITREP : ] SSO TODD - BUILDING OF 2 LEVELS - 20M BY 50M - USED AS

04:06:10 A COMMERCIAL LAUNDRY - FIRE LOCATED IN REAR OF BUILDING - 2 LPDS - 1 AERIAL IN

04:06:10 USE - INTERNAL CUT OFF FIRE ATTACK

04:06:26	Unit AUCKCITY2 [ SITREP : ] COPIED
04:06:27	Unit AUCKCITY4 [ K1 : PROCEEDING TO INCIDENT]
04:07:04	Unit AUCKCITY4 [COMCEN COM : MESSAGE] DID YOU COPY SITREP
04:07:06	Unit AVON607 [ KP : PRIORITY MESSAGE]
04:08:01	Unit AVON607 [ KP : PRIORITY MESSAGE] ASSEMBLY AREA FOR APPLIANCES CORNER OF
04:08:01	COPSEY PLACE AND ROSEBANK - TRANSMIT 3RD ALARM
04:08:09	INC INFO: BUILDING FIRE - 3RD ALARM TX
04:08:19	FIR2AMB: NOTIFICATION OF 3RD ALARM TRANSMITTED
04:08:28	FIR2POL: NOTIFICATION OF 3RD ALARM TRANSMITTED
04:08:36	** Alarm level updated to 3
04:08:36	** Recommended unit PARN255 for requirement AERIAL (>9.9 km)
04:08:36	** Recommended unit ELLE274 for requirement AERIAL (>11.2 km)
04:08:36	** Recommended unit AVON6015 for requirement BAT (>2.5 km)
04:08:36	** Recommended unit AUCKOSU4 for requirement CANT (>15.6 km)
04:08:36	** Recommended unit AUCK207 for requirement PUMP (>7.5 km)
04:08:36	** Recommended unit WEST672 for requirement PUMP (>9.2 km)
04:08:36	** Recommended unit HEND657 for requirement PUMP (>4.4 km)
04:09:01	FIR2POL: 3RD ALARM TRANSMITTED - RESPONSE REQUIRED
04:09:03	FIR2AMB: 3RD ALARM TRANSMITTED - RESPONSE REQUIRED
04:09:13	Unit AUCK205 [ K2 : IN ATTENDANCE AT INCIDENT]
04:09:17	Unit AUCK205 [ K2 : IN ATTENDANCE AT INCIDENT]
04:09:24	Unit AUCK205 [ K2 : IN ATTENDANCE AT INCIDENT]
04:10:23	Unit AUCK2018 [ K2 : IN ATTENDANCE AT INCIDENT]
04:10:30	Unit AUCK2018 [ K2 : IN ATTENDANCE AT INCIDENT]
04:10:34	Unit ELLE274 [ K1 : PROCEEDING TO INCIDENT]
04:10:56	Unit AUCK207 [ K1 : PROCEEDING TO INCIDENT]
04:11:02	Unit TEAT662 [ K2 : IN ATTENDANCE AT INCIDENT]
04:11:06	Unit PARN255 [ K1 : PROCEEDING TO INCIDENT]
04:11:08	Unit TEAT662 [ K2 : IN ATTENDANCE AT INCIDENT]
04:11:11	Unit PARN255 [ K1 : PROCEEDING TO INCIDENT]
04:11:13	Unit TEAT662 [ K2 : IN ATTENDANCE AT INCIDENT]
04:11:18	Unit PARN255 [ K1 : PROCEEDING TO INCIDENT]
04:11:58	Unit MTRO621 [ K1 : PROCEEDING TO INCIDENT]
04:12:09	Unit HEND657 [ K1 : PROCEEDING TO INCIDENT]
04:12:26	Unit WEST671 [ K2 : IN ATTENDANCE AT INCIDENT]
04:12:38	Unit AUCKOSU2 [ K2 : IN ATTENDANCE AT INCIDENT]
04:14:11	Unit WEST672 [ K1 : PROCEEDING TO INCIDENT]
04:14:22	Unit WAITEMATA3 [ K1 : PROCEEDING TO INCIDENT]
04:14:51	COVER
04:15:54	Unit MTRO621 [ KC : UNIT CALLING]

04:16:40	Unit MTRO621 [ SITREP : ] CAN YOU ACTIVATE AVONDALE STATION ALARMS
04:17:24	Unit COUNTIES1 [ K1 : PROCEEDING TO INCIDENT]
04:18:01	Unit AVON6015 [ K1 : PROCEEDING TO INCIDENT]
04:18:04	COVERING UNIT HEND651 DISPATCHED TO STATION HENDERSON
04:18:04	D0710067
04:18:05	Unit WEST672 [ KC : UNIT CALLING]
04:19:09	Unit AUUCK207 [ K2 : IN ATTENDANCE AT INCIDENT]
04:19:52	Unit WEST672 [ KC : UNIT CALLING]
04:20:30	COVERING UNIT ALBA851 DISPATCHED TO STATION WEST
04:20:30	TERMINAL: D0710063
04:21:12	COVERING UNIT ONEH221 DISPATCHED TO STATION AVONDALE
04:21:12	D0710063
04:21:13	Unit AUUCKCITY4 [ K2 : IN ATTENDANCE AT INCIDENT]
04:21:21	Unit HEND657 [ K2 : IN ATTENDANCE AT INCIDENT]
04:21:26	Unit AUUCKCITY2 [ K2 : IN ATTENDANCE AT INCIDENT]
04:22:11	COVERING UNIT OTAH311 DISPATCHED TO STATION ONEHUNGA
04:22:11	D0710063
04:22:17	Unit PARN255 [ K2 : IN ATTENDANCE AT INCIDENT]
04:22:23	Unit COUNTIES1 [ K6 : ON TELEPAGER]
04:24:19	Unit WEST672 [ KC : UNIT CALLING]
04:24:24	Unit ELLE274 [ K2 : IN ATTENDANCE AT INCIDENT]
04:24:39	Unit AVON6015 [ K2 : IN ATTENDANCE AT INCIDENT]
04:25:26	Unit WEST672 [ SITREP : ] DELAYED RESPONSE DUE TO MOTORWAY CLOSURE - SHORT
04:25:26	CREWED - OFFICER AND 2
04:27:31	Unit WEST672 [ K2 : IN ATTENDANCE AT INCIDENT]
04:30:33	Unit MTRO621 [ K2 : IN ATTENDANCE AT INCIDENT]
04:38:39	Unit AUUCKOSU4 [ K1 : PROCEEDING TO INCIDENT]
04:42:46	Unit WAITEMATA3 [ K2 : IN ATTENDANCE AT INCIDENT]
04:44:10	Unit FIAKCITY4 [ K2 : IN ATTENDANCE AT INCIDENT]
04:45:49	Unit AUUCK2018 [ KC : UNIT CALLING]
04:46:36	Unit AUUCK2018 [ K44 : COMMAND OR CONTROL POINT ESTABLISHED - OIC AND LOCATION]
04:46:36	COPSEY COMMAND - AAC CALLISTER
04:48:45	Unit AUUCK2018 [ KC : UNIT CALLING]
04:51:30	Unit AUUCK2018 [ SITREP : ] MAIN FIRE - REAR OF BUILDING - 2 LPDS - FIRE
04:51:30	CONTROLLED - STILL FIRE EXTENSION ROOF RIDGE LINE SECTOR 1 - ROOF REMOVAL IN
04:51:30	PROCESS
04:54:08	Unit AUUCK2018 [ KC : UNIT CALLING]
04:54:36	Unit AUUCK2018 [ K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] AAC CALLISTER
04:57:28	Unit AUUCK2018 [ KC : UNIT CALLING]
04:58:36	Unit AUUCKOSU4 [ K2 : IN ATTENDANCE AT INCIDENT]

04:58:40	Unit AUCK2018 [ SITREP : ] FIRE CONTAINED - RIDGELINE FIRE CONTAINED ALSO -
04:58:40	COMMENCING POSITIVE PRESSURE VETILATION
05:32:59	Unit AUCK2018 [ KC : UNIT CALLING]
05:33:37	Unit AUCK2018 [ K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]
05:33:37	BREAKING DOWN THIRD ALARM APPLIANCES
05:34:05	Unit AUCK207 [ K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
05:34:19	Unit AUCK207 [ K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
05:42:12	Unit AUCK207 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
05:45:56	Unit ELLE274 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
05:55:30	Unit FIAKCITY4 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
05:55:32	Unit AUCK2018 [ KC : UNIT CALLING]
05:56:24	Unit HEND657 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
05:56:59	Unit AUCK2018 [ SITREP : ] FIRE RISK MANAGER DICKSON - DEPARTING SCENE -
05:56:59	RETURNING 0800 - REQUESTS PLATFORM AERIAL FOR AERIAL PHOTOGRAPHS AT 0830
05:58:00	BACK
06:00:13	Unit WEST672 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
06:02:30	Unit AUCK205 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
06:12:55	Unit PARN255 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
06:13:41	Unit WAITEMATA3 [ K6 : ON TELEPAGER]
06:19:03	Unit AUCKCITY2 [ K6 : ON TELEPAGER]
06:20:37	Unit AUCK2018 [ KC : UNIT CALLING]
06:21:02	Unit AUCK2018 [ K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]
06:21:29	Unit AUCKOSU1 [ K1 : PROCEEDING TO INCIDENT]
06:26:58	Unit MTRO621 [ K2 : IN ATTENDANCE AT INCIDENT]
06:27:06	Unit GLEN641 [ SITREP : ] HEADING BACK TO STATION TO GET CLEANED UP - GLEN AT
06:27:06	0800 WILL HEAD BACK TO COPSEY TO PROVIDE COVER
06:33:16	Unit WEST671 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
06:37:10	Unit AUCK2018 [ KC : UNIT CALLING]
06:37:37	Unit AUCK2018 [ K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO GARDNER ON
06:37:37	664
06:42:27	Unit AUCKOSU1 [ K2 : IN ATTENDANCE AT INCIDENT]
06:44:34	Unit TEAT662 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
06:57:45	Unit AUCKOSU2 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
07:01:19	Unit AUCK2018 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
07:02:41	Unit AUCKOSU4 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
07:03:20	Unit AUCKCITY4 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
07:12:07	Unit GLEN641 [ K7 : AT NORMAL STATION]
07:13:39	Unit FIAKCITY4 [ KC : UNIT CALLING]
07:13:46	Unit FIAKCITY4 [ KC : UNIT CALLING]
07:18:05	Unit FIAKCITY4 [ K1 : PROCEEDING TO INCIDENT]

07:34:37	Unit FIAKCITY4 [ K2 : IN ATTENDANCE AT INCIDENT]
07:46:38	Unit AVON607 [ KC : UNIT CALLING]
07:47:09	Unit AVON607 [ K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SSO WOOD
08:08:40	Unit AUCKOSU1 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
08:16:15	Unit MTRO621 [ K7 : AT NORMAL STATION]
08:25:37	Unit GLEN641 [ K1 : PROCEEDING TO INCIDENT]
08:25:44	Unit GLEN641 [ K1 : PROCEEDING TO INCIDENT]
08:34:13	Unit PARN255 [ K2 : IN ATTENDANCE AT INCIDENT]
08:36:49	Unit GLEN641 [ K2 : IN ATTENDANCE AT INCIDENT]
08:43:50	Unit TEAT664 [ K7 : AT NORMAL STATION]
08:53:47	Unit GLEN641 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
08:57:33	Unit AVON607 [ KC : UNIT CALLING]
08:57:44	Unit AVON607 [ KC : UNIT CALLING]
08:57:46	Unit AVON607 [ KC : UNIT CALLING]
08:58:16	Unit AVON607 [ K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] NO
08:58:16	FURHTER STANDBYS RQD INCIDENT LEFT WITH FI DICKSON
09:05:36	Unit AVON607 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
09:05:47	Unit AVON6015 [ K7 : AT NORMAL STATION]
09:28:13	Unit PARN255 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
10:55:09	Unit FIAKCITY4 [ STOP : MESSAGE] LEAVING THE SCENE NOW BUT WILL RETURN AGAIN
10:55:09	TOMORROW WITH AN ELECTRICAL INSPECTOR
10:55:24	Unit FIAKCITY4 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:07:08	UNIT FIAKCITY4 RESPONSE TIME [NULL] ADJUSTED TO
11:07:16	UNIT COUNTIES1 ALERT TIME [NULL] ADJUSTED TO
11:07:16	UNIT AUCKOSU1 ALERT TIME [NULL] ADJUSTED TO
11:07:16	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
11:07:16	Qualifier 2:

**Incident**

<b>CAD Number</b>	F2291990
<b>Incident Reporter</b>	Chris Todd
<b>Incident Controller</b>	Chris todd
<b>Distance Travelled (km)</b>	3
<b>Delay In Receiving Call</b>	

**Property Details**

<b>Occupant</b>	Madison Qualitex Laundry
<b>Building Owner</b>	Owner occupied
<b>General Property Use</b>	Service/Repair use, Dry cleaner, Laundromat, Mechanical workshop



Special Property Use      Laundromat  
Purpose Group

**Actions**

Persons Reported Trapped    No  
Evacuation Status      Not occupied at time of incident  
Action Prior 1  
Action Prior 2  
Action Taken      Extinguishment, salvage and ventilation

**Civilians**

Civilians Rescued      0  
Civilians Extricated      0  
Civilians Assisted      1  
Civilians Evacuated

**Origin**

Location      Supply room/area, Tool room, Maintenance supply room  
Level      Ground level

**Equipment Used**

Quantity	Equipment
3	Low pressure delivery
3	Hydraulic elevating platform (HEP), Snorkel, other Aerial
2	Thermal Imaging Camera

**Equipment Involved**

Equipment Involved  
Year  
Make  
Model

**Fire**

Arrival Condition      Large fire  
Heat Source      Heat from electrical equipment: Defective or faulty  
Termination Stage      Flame  
First Object Ignited      Electrical wire, Wiring insulation  
First Object Material      PVC eg. Floor Tiles, Guttering/Pipes, Plastic Bags, Elec. Insulation

**Second Object Ignited**

**Second Object Material**

**Indicated Cause** Short circuit, earth fault

**Certainty of Cause** Medium

**Age of Person** Unknown

**Ethnicity** Unknown

**Gender**

**FAIP Service Offered** No **FAIP Service Accepted** No

**Structure**

<b>Area of One Floor</b>		770
<b>Age of Building</b>	1970 - 1991	
<b>Structural Frame Type</b>	Metal frame unprotected	
<b>Number of Floors</b>		2
<b>Number of Basements</b>		0
<b>Internal Wall Lining</b>	Combination of materials	
<b>Ceiling Lining</b>	Metal: Aluminium, Steel, Metallic alloy	
<b>Material Generating Most Flame</b>	Cotton, Canvas, Rayon	
<b>Material Generating Most Smoke</b>	Cotton, Canvas, Rayon	
<b>Avenue of Flame Travel</b>	Stored material	
<b>Avenue of Smoke Travel</b>	Furniture, fixtures	
<b>Extent of Flame Damage</b>	Confined to structure of origin	
<b>Area of Flame Damage</b>		600
<b>Extent of Smoke Damage</b>	Confined to structure of origin	
<b>Area of Smoke Damage</b>		770
<b>Extent of Water Damage</b>	Confined to structure of origin	
<b>Area of Water Damage</b>		100
<b>Extent of Fire Control Damage</b>	Confined to structure of origin	
<b>Area of Fire Control Damage</b>		100

Released under the Official Information Act