

SMS Incident Report


02/06/2017 11:57:27

Summary

CAD Number F2307762 **Status** Closed
Station Papatoetoe Station
Incident Started 16/05/2017 01:24:35 **Incident Ended** 16/05/2017 02:35:52
Incident Type 1511: Outside fire: Material burnt has definable value
Common Name ANZ HOUSE
Address 3 OSTERLEY WAY MANUKAU
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 143403
Map Grid E 1767279 **Map Grid N** 5904373
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 16/05/2017 02:35:52
Report Completed 7:12, Tue 16 May 2017 by Alex Betteridge

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
PAPA347	PR	01:26:08 16 May 2017	01:27:25 16 May 2017	01:29:58 16 May 2017	01:46:36 16 May 2017
PAPA344	PM	01:26:08 16 May 2017	01:28:42 16 May 2017	01:30:34 16 May 2017	01:36:59 16 May 2017
MANU301	P1	01:26:13 16 May 2017	01:27:52 16 May 2017	01:33:19 16 May 2017	01:34:05 16 May 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
PAPA347	00:01:33	00:03:50	00:05:23	00:22:01
PAPA344	00:01:33	00:04:26	00:05:59	00:12:24
MANU301	00:01:38	00:07:06	00:08:44	00:09:30

Notifications

Date	Time	Party Notified
16 May 2017	01:50:51	VIA PHONE FROM SSO BETTERIDGE, THERE WERE VANDALS AT THIS CALL, THEY HAVE
16 May 2017	01:55:52	ADT ADVISED OF BROKEN GLASS THAT NEEDS REPLACING

Message Log

Time	Message
01:25:52	WIRES ATB MAIN SOURCE OF BURNING
01:25:52	INC INFO: FIRE PRESUMMED OUT
01:25:53	** ELOI search completed at 16/05/17 01:25:53 - 5 results
01:25:54	** LOI search completed at 16/05/17 01:25:54
01:26:00	** Recommended unit PAPA344 for requirement AERIAL (>0.9 km)
01:26:00	** Recommended unit PAPA347 for requirement PUMP (>0.9 km)
01:26:00	** Recommended unit MANU301 for requirement PUMP (>4.0 km)
01:26:22	WARWICK WORTH - MAUKAU POLICE - CRIME SQUAD
01:26:32	0211910715
01:26:59	WARWICK -WILL BE WAITING FOR FIRE OUTSIDE BUILDING
01:27:25	Unit PAPA347 [K1 : PROCEEDING TO INCIDENT]
01:27:52	Unit MANU301 [K1 : PROCEEDING TO INCIDENT]
01:28:21	ATB TO BE DAMAGE TO BULDING EITHER CAUSED BY FIRE OR WILFUL DAMAGER
01:28:24	DAMAGE
01:28:38	Unit PAPA347 [COMCEN COM : MESSAGE] DETAILS PASSED
01:28:43	Unit PAPA344 [K1 : PROCEEDING TO INCIDENT]
01:29:58	Unit PAPA347 [K77 : NOTHING SHOWING]
01:30:34	Unit PAPA344 [K2 : IN ATTENDANCE AT INCIDENT]
01:33:19	Unit MANU301 [K2 : IN ATTENDANCE AT INCIDENT]
01:33:59	Unit PAPA347 [KC : UNIT CALLING]
01:34:06	Unit MANU301 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
01:34:53	Unit PAPA347 [SITREP :] SSO BETTERIDGE. MANUKAU LIBRARY. OSTERLEY WAY,
01:34:53	MANUKAU. ATB SOME WILLFUL DAMAGE AND A SMALL, WHAT ATB A SMALL ELECTRICAL FIRE,
01:34:53	EXTINGUISHED BY POL, BRIGADE INVESTIGATING.
01:37:00	Unit PAPA344 [K7 : AT NORMAL STATION]
01:43:29	Unit PAPA347 [KC : UNIT CALLING]
01:45:16	Unit PAPA347 [KC : UNIT CALLING]
01:45:47	Unit PAPA347 [STOP : MESSAGE] SMALL EXTERNAL FIRE OUT ON ARRIVAL. EXTINGUISHED
01:45:47	BY POL. NO FURTHER ACTION REQUIRED.
01:46:38	Unit PAPA347 [K7 : AT NORMAL STATION]
01:50:51	SMASHED THE GLASS AT THE RISER INLET, THE SPRINKLER INLET AND ANOTHER PANEL BY

01:50:51	THE PANEL, GLASS WILL NEED REPLACING
02:35:52	** Assigned Result Code: STRU, Detailed Event Type: 3100, Qualifier 1: Q1,
02:35:52	Qualifier 2:

Incident

CAD Number F2307762
Incident Reporter Alex Betteridge
Incident Controller SSO Betteridge
Distance Travelled (km) 2
Delay In Receiving Call

Property Details

Occupant
Building Owner
General Property Use Office, Bank, Embassy, Fire/Ambulance/Police station
Special Property Use Office: General business
Purpose Group

Actions

Persons Reported Trapped
Evacuation Status
Action Prior 1
Action Prior 2
Action Taken Investigation only (Fire related)

Origin

Location
Level

Equipment Used

Quantity	Equipment
0	Portable extinguisher - by Occupant/Passerby

Equipment Involved

Equipment Involved
Year
Make
Model

Fire

Arrival Condition

Heat Source

Termination Stage

First Object Ignited

First Object Material

Second Object Ignited

Second Object Material

Indicated Cause Unlawful

Certainty of Cause High

Age of Person Unknown

Ethnicity Unknown

Gender

FAIP Service Offered No FAIP Service Accepted No

Comments

5/16/2017 7:12:36 AM

Reporter Comments

Glass doors on Brigade Inlets ((High Rise and Sprinkler inlets) smashed by vandals.
Exterior power cable attached to wall set on fire. Also tagging etc.

Alex Betteridge

Released under the Official Information Act