

# SMS Incident Report


10/07/2017 12:40:41

## Summary

**CAD Number** F2338065 **Status** Closed  
**Station** Mount Wellington Station  
**Incident Started** 06/07/2017 15:34:09 **Incident Ended** 06/07/2017 15:51:54  
**Incident Type** 7105: False alarm: Excess Smoke, Heat  
**Common Name** THE TERRACES HOWICK  
**Address** 24 WELLINGTON STREET HOWICK  
**Alarm Method** Manual PFA Call **Alarm Level** 1  
**PFA Number** 119178  
**Zone** 143207  
**Map Grid E** 1771998 **Map Grid N** 5915122  
**First Caller** **First Caller Contact**  
**Incident Closed** 06/07/2017 16:33:49  
**Report Completed** 17:50, Fri 07 Jul 2017 by Frank Walsh

## Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
MTWE237	PR	15:35:04 06 Jul 2017	15:35:51 06 Jul 2017	15:45:41 06 Jul 2017	15:59:19 06 Jul 2017
OTAR331	P1	15:35:16 06 Jul 2017	15:36:09 06 Jul 2017	15:47:27 06 Jul 2017	15:51:15 06 Jul 2017



## Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
MTWE237	00:00:55	00:10:37	00:11:32	00:25:10
OTAR331	00:01:07	00:12:11	00:13:18	00:17:06

**Message Log**

Time	Message
15:34:09	AL: 119178 15:34:09 INITIAL - AL
15:34:10	** LOI search completed at 06/07/17 15:34:10
15:34:10	PANEL: SPRINKLER VALVE ROOM
15:34:34	** Recommended unit OTAR331 for requirement PUMP (>7.5 km)
15:34:34	** Recommended unit MTWE237 for requirement PUMP (>5.9 km)
15:35:51	Unit MTWE237 [ K1 : PROCEEDING TO INCIDENT]
15:36:09	Unit OTAR331 [ K1 : PROCEEDING TO INCIDENT]
15:39:09	Duplicate Event:Location = 24 WELLINGTON ST,HOWICK,AUCKLAND: @THE TERRACES
15:39:09	INC INFO: ALARM SOUNDING
15:39:09	HOWICK, Type = STRU - STRUCTURE FIRE, Caller Ph Number = [REDACTED], Call Source
15:39:09	= 111Inc InfoALARM SOUNDING, Event Source = Fire 111
15:39:09	End of Duplicate Event data
15:40:37	Duplicate Event:Location = FENCIBLE DR,HOWICK,AUCKLAND, Type = STRU - STRUCTURE
15:40:37	INC INFO: ALARM ACTIVATION - COMMERCIAL
15:40:37	FIRE, Caller Ph Number = [REDACTED], Call Source = 111Inc InfoALARM ACTIVATION
15:40:37	- COMMERCIAL, Event Source = Fire 111
15:40:38	End of Duplicate Event data
15:45:41	Unit MTWE237 [ K77 : NOTHING SHOWING]
15:45:50	Unit MTWE237 [ K77 : NOTHING SHOWING]
15:47:27	Unit OTAR331 [ K2 : IN ATTENDANCE AT INCIDENT]
15:48:07	Unit OTAR331 [ K2 : IN ATTENDANCE AT INCIDENT]
15:50:13	Unit MTWE237 [ KC : UNIT CALLING]
15:50:38	Unit MTWE237 [ SITREP : ] SSO WALSH IPS ZONE 1 REAR RIGHT INV
15:51:24	Unit OTAR331 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
15:51:29	Unit MTWE237 [ KC : UNIT CALLING]
15:51:55	Unit MTWE237 [ K46-2 : STOP MESSAGE: FALSE ALARM ACCIDENTAL] SMOKE FROM POPCORN
15:51:55	MACHINE
15:59:21	Unit MTWE237 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
16:33:49	** Assigned Result Code: SPRNKLR, Detailed Event Type: 7100, Qualifier 1: Q1,
16:33:49	Qualifier 2:

**Incident**

<b>CAD Number</b>	F2338065
<b>Incident Reporter</b>	Frank Walsh
<b>Incident Controller</b>	SSO Frank Walsh
<b>Distance Travelled (km)</b>	
<b>Delay In Receiving Call</b>	

---

**False Alarm**

**Detector Type** Smoke detector  
**False Alarm Cause** Building Usage | Fumes from food processing (excl. from toasters)  
**Other Cause**

---

**Property Details**

**Occupant**  
**Building Owner**  
**General Property Use** Recreational use, Theatre, Indoor sports, Pool, Park, Zoo, Aquarium  
**Special Property Use** Cinema, Picture theatre  
**Purpose Group** IA - Intermittent Light Fire Hazard

**Comments**

7/7/2017 5:49:58 PM

Reporter Comments

---

fumes from popcorn machine in cinema foyer activated smoke detector

Frank Walsh

Released under the Official Information Act