# **SMS Incident Report**

10/07/2017 11:54:04

## **Summary**

CAD Number F2338070 Status Closed

**Station** Papakura Station

Incident Started 06/07/2017 15:44:13 Incident Ended 06/07/2017 16:03:33

Incident Type7104: False alarm: Accidental operationCommon NameEAST TAMAKI HEALTHCARE TAKANINIAddressMA2 / 30 WALTERS ROAD TAKANINI

Alarm Method Manual PFA Call Alarm Level 1

**PFA Number** 119921 **Zone** 143807

**Map Grid E** 1771871 **Map Grid N** 5897987


First Caller Contact

**Incident Closed** 06/07/2017 16:34:22

Report Completed 20:14, Fri 07 Jul 2017 by Bob O'Flaherty

### Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
PAPA387	PR	15:50:48 06 Jul 2017	15:50:49 06 Jul 2017	15:52:18 06 Jul 2017	16:03:49 06 Jul 2017
PAPA347	PR	15:44:45 06 Jul 2017	15:46:08 06 Jul 2017		15:52:48 06 Jul 2017
PAPA344	PM	15:44:46 06 Jul 2017	15:47:10 06 Jul 2017		15:56:14 06 Jul 2017



## **Elapsed Times**

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
PAPA387	00:06:35	00:01:30	00:08:05	00:19:36
PAPA347	00:00:32			00:08:35
PAPA344	00:00:33			00:12:01

## Message Log

Time	Message	
15:44:14	** LOI search completed at 06/07/17 15:44:14	
15:44:14	** ELOI search completed at 06/07/17 15:44:14 - 1 result	
15:44:14	AL: 119921 15:44:13 INITIAL - AL	
15:44:14	PANEL: SPRINKLER VALVE ROOM	
15:44:34	ACCESS NO: -S	
15:44:36	** Recommended unit PAPA347 for requirement PUMP (>8.8 km)	
15:44:36	** Recommended unit PAPA344 for requirement PUMP (>8.7 km)	
15:46:07	COVERING UNIT OTAH311 DISPATCHED TO STATION MANUREWA	
15:46:07	D0710063	
15:46:09	Unit PAPA347 [ K1 : PROCEEDING TO INCIDENT]	
15:46:34	ОТАН	
15:46:51	Unit PAPA347 [ KC : UNIT CALLING]	
15:47:11	Unit PAPA344 [ K1 : PROCEEDING TO INCIDENT]	
15:47:15	Unit PAPA347 [ SITREP : ] RESPONDING NORM TRAFFIC LACK OF BEACONS	
15:47:24	Unit PAPA347 [ KC : UNIT CALLING]	
15:48:32	Unit PAPA344 [ K1 : PROCEEDING TO INCIDENT]	
15:50:45	Unit PAPA387 [ K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]	
15:50:49	Unit PAPA387 [ K1 : PROCEEDING TO INCIDENT]	
15:52:16	Unit PAPA347 [ K28 : UNIT IS TO RETURN TO STATION]	
15:52:19	Unit PAPA387 [ K77 : NOTHING SHOWING]	
15:52:29	Unit PAPA347 [ SITREP : ] K0 US AS PAPA 387 IS RESPONDING (PH)	
15:52:49	Unit PAPA347 [ K0 : NOT AVAILABLE] NO ERD CAPABILITY	
15:55:31	Unit PAPA387 [ KC : UNIT CALLING]	
15:56:09	Unit PAPA387 [ SITREP : ] SO OFLAHERTY AREA INDICATED GROUND FLOOR K28	
15:56:15	Unit PAPA344 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
15:56:16	Unit PAPA387 [ K28 : UNIT IS TO RETURN TO STATION]	
16:03:16	Unit PAPA387 [ KC : UNIT CALLING]	
16:03:33	Unit PAPA387 [ K46-2 : STOP MESSAGE: FALSE ALARM ACCIDENTAL] COOKING	
16:03:50	Unit PAPA387 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
16:34:22	** Assigned Result Code: SPRNKLR, Detailed Event Type: 7100, Qualifier 1: Q1,	
16:34:22	UNIT PAPA387 ALERT TIME [NULL] ADJUSTED TO	
16:34:22	Qualifier 2:	

### Incident

CAD Number	F2338070
Incident Reporter	Bob O'Flaherty

**Incident Controller** 

Bob O'Flaherty

**Distance Travelled (km) Delay In Receiving Call** 

3

**False Alarm** 

**Detector Type** Smoke detector

**False Alarm Cause** 

Human Intervention | Accidential alarm activation by (c) other person

**Other Cause** 

**Property Details** 

**Occupant** 

**Building Owner** 

**General Property Use** Construction, Renovation, Demolition site

**Special Property Use** Building under construction

**Purpose Group** WM - Working, Business or Storage Moderate Fire Hazard

#### **Comments**

7/7/2017 8:13:21 PM **Reporter Comments** 

Alarm activated by cooking toast in Pharmacy office

Only partial evacuation from health care facility

**Bob O'Flaherty** 

**Reporter Comments** 

7/7/2017 8:14:22 PM

**Bob O'Flaherty**