# **SMS Incident Report**

11/09/2017 09:28:36

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
Responses			2		
Report Completed	22:4	14, Sat 09 Sep 2017 by Rus	sell Wilkinson		
Incident Closed	08/0	9/2017 15:38:23			
First Caller		NCORP NEW ZEALAND RVICES LIMITED	First C	aller Contact	
Map Grid E	175 <sup>-</sup>	1272		Map Grid N 592695	56
Zone	1482	251			
PFA Number				XU	
Alarm Method	111	Telephone		Alarm Level 1	
Address	44 L	ANCASTER ROAD BEACH	HAVEN		
Common Name				2	
Incident Type	110 <sup>-</sup>	1: Structure fire with damag	e	x	Q.
Incident Started	08/0	09/2017 10:56:16	In	cident Ended 08/09/2	2017 15:38:23
Station	Birk	enhead Station			
CAD Number	F23	75856		Status Closed	2
Summary					X

### Responses

(esponses					
Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
BIRK821	P1	10:57:03 08 Sep 2017	10:58:28 08 Sep 2017	11:06:02 08 Sep 2017	15:04:11 08 Sep 2017
TAKA807	PR	10:57:00 08 Sep 2017	10:57:45 08 Sep 2017	11:06:40 08 Sep 2017	14:06:51 08 Sep 2017
ALBA851	P1	10:59:48 08 Sep 2017	11:00:55 08 Sep 2017	11:09:00 08 Sep 2017	12:25:53 08 Sep 2017
AUCKOSU1	SV	11:20:57 08 Sep 2017	11:21:54 08 Sep 2017	11:45:34 08 Sep 2017	12:05:11 08 Sep 2017
FIWAITEM2	FSO	13:26:32 08 Sep 2017	13:26:51 08 Sep 2017	13:41:00 08 Sep 2017	15:36:53 08 Sep 2017
WHAN1218	СИНИ				14:47:38 08 Sep 2017
Start->Alert	7 min	10 min			
8					
			15 min		3 mir
1	Δlert->1st Δ	rrival	11111		1111

Alert->1st Arrival

# **Elapsed Times**

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
BIRK821	00:00:47	00:08:59	00:09:46	04:07:55

#### SMS Incident Report F2375856

2/10

11/09/2017 09:28:36

X

TAKA807	00:00:44	00:09:40	00:10:24	03:10:35
ALBA851	00:03:32	00:09:12	00:12:44	01:29:37
AUCKOSU1	00:24:41	00:24:37	00:49:18	01:08:55
FIWAITEM2	02:30:16	00:14:28	02:44:44	04:40:37
WHAN1218				03:51:22

## **Notifications**

Date	Time	Party Notified
08 Sep 2017	11:01:19	AAC WAITEMATA PER PAGER - MULTIPLE CALLS
08 Sep 2017	11:06:55	VECTOR
08 Sep 2017	11:08:22	VECTOR WILL CALL BACK ETA
08 Sep 2017	11:12:14	VECTOR CALL BACK - ETA 30 MINUTES
08 Sep 2017	11:23:49	POL VIA INTERCAD
08 Sep 2017	11:29:19	FIWAITM2 (CHRIS LEWIS) BY ADHOC PAGE AS ALREADY COMMITTED TO F2372095
08 Sep 2017	11:33:21	AAC WAITEMATA PER PAGER - AC ODONOGHUE CONTACT FIRECOM
08 Sep 2017	11:37:17	AC ODONOGHUE ACK PAGER - DISCUSSED SITUATION - CONTACT FRMO MCGINTY TO GO
08 Sep 2017	11:38:12	FI WAITEMATA3 (CHRISTINE MCGINTY) PAGED TO CALL FIRECOM
08 Sep 2017	11:46:12	HOUSING NZ
08 Sep 2017	11:48:51	FRMO MCGINTY PER PHONE - UNAVAILABLE ON LEAVE TODAY
08 Sep 2017	11:49:18	FI AUCKLAND CITY 3 (JASON GOFFIN) PAGED TO CALL FIRECOM
08 Sep 2017	11:55:03	FRMO GOFFIN ACK PAGER - UNAVAILABLE
08 Sep 2017	11:56:13	AAC WAITEMATA PER PAGER - AC ODONOGHUE CONTACT FIRECOM
08 Sep 2017	12:06:52	AC ODONOGHUE ACK PAGER - UPDATED RE-MCGINTYGOFFIN - HE WILL RIN FRMO LEWIS
08 Sep 2017	12:30:50	TAKA807 PER CELLPHONE - UPDATED RE- FIRE INVESTIGATOR
08 Sep 2017	12:32:28	AAC MACKERETH PER PHONE - CAN YOU PAGE FI LEWIS TO CONTACT ME
08 Sep 2017	12:33:06	FI LEWIS PER PAGER
08 Sep 2017	12:35:39	AAC MACKERETH PER PHONE - ETA FI 1HOUR
08 Sep 2017	14:21:20	HOUSING NZ THAT THERE IS ASBESTOS ON SITE
08 Sep 2017	14:22:42	AUCKLAND COUNCIL ADV ASBESTOS ON SCENE

# Message Log

Time	Message
10:56:41	INC INFO: HOUSE FIRE
10:56:42	** LOI search completed at 08/09/17 10:56:42
10:56:48	** Recommended unit BIRK821 for requirement PUMP (>2.9 km)
10:56:48	** Recommended unit TAKA807 for requirement PUMP (>5.9 km)
10:56:57	CAR IN GARAGE AS WELL BUT NOT SURE OIF THEY ARE HOME

SMS Incident Report	F2375856	3/10	11/09/2017 09:28:36
10:57:17	LOUNG FIRE		
10:57:21	WHOLE HOUSE IS	S ON FIRE	
10:57:29	LOUNGE FIRE **		
10:57:46	Unit TAKA807 [ K1	: PROCEEDING TO INCIDENT]	
10:57:52	INC INFO: SMOKE	E IN VICINITY	
10:57:52	Duplicate Event:Lo	ocation = LANCASTER RD,BEACH HAVEN,AU	JCKLAND, Type = MIN -
10:57:52	MINOR, Caller Ph	Number = Call Source = 111Inc	c InfoSMOKE IN
10:57:52	VICINITY, Event S	Source = Fire 111	
10:57:52	End of Duplicate E	vent data	
10:58:01			í n
10:58:23	INC INFO: SMOKE	E IN AREA	
10:58:23	Duplicate Event:Lo	ocation = LANCASTER RD,BEACH HAVEN,AU	JCKLAND, Type = MIN -
10:58:23	MINOR, Caller Nar	me = Caller Ph Numbe	er = <b>Caller</b> , Caller
10:58:23	Address = LA	NCASTER ROAD, BEACH HAVEN, AUCKLAN	ND CITY, Call Source = 111Inc
10:58:23	InfoSMOKE IN AR	EA, Event Source = Fire 111	
10:58:23	End of Duplicate E	vent data	
10:58:28	INC INFO:		
10:58:28	Duplicate Event:Lo	ocation = LANCASTER RD,BEACH HAVEN,AU	JCKLAND, Type = STRU -
10:58:28	STRUCTURE FIRE	E, Caller Ph Number =	rce = 111, Event Source
10:58:28	= Fire 111	- PII-	
10:58:28	End of Duplicate E	vent data	
10:58:29	Unit BIRK821 [ K1	: PROCEEDING TO INCIDENT]	
10:58:59	Unit TAKA807 [ KC	C : UNIT CALLING]	
10:59:01	Unit BIRK821 [COI	MCEN COM : MESSAGE] MULTIPLE CALLS	AND HYDANRNT INFO
10:59:02	Duplicate Event:Lo	ocation = LANCASTER RD,BEACH HAVEN,AU	JCKLAND, Type = STRU -
10:59:02	STRUCTURE FIRE	E, Caller Ph Number =	rce = 111Inc InfoHOUSE
10:59:02	FIRE, Event Sourc	e = Fire 111	
10:59:03	INC INFO: HOUSE	EFIRE	
10:59:03	End of Duplicate E	vent data	
10:59:05	INC INFO: HOUSE	EFIRE	
10:59:05	Duplicate Event:Lo	ocation = 44 LANCASTER RD,BEACH HAVEN	,AUCKLAND, Type = STRU -
10:59:05	STRUCTURE FIRE	E, Caller Ph Number =	rce = 111Inc InfoHOUSE
10:59:05	FIRE, Event Sourc	e = Fire 111	
10:59:05	End of Duplicate E	vent data	
10:59:12	Unit BIRK821 [ SIT	[REP : ] MAKE PUMPS THREE	
10:59:16	Duplicate Event:Lo	cation = LANCASTER RD,BEACH HAVEN,AL	JCKLAND, Type = MIN -
10:59:16	INC INFO: BLACK	SMOKE IN THE VICINITY	
10:59:16	MINOR, Caller Nar	me =, Caller Ph Number =	, Caller Address
10:59:16	= FAIRCLOUGI	H ROAD, BEACH HAVEN, AUCKLAND CITY,	Call Source = 111Inc InfoBLACK
10:59:16	SMOKE IN THE VI	ICINITY , Event Source = Fire 111	

IS Incident Report	F2375856	4/10	11/09/2017 09:28:
10:59:16	End of Duplicate Event da	ata	
10:59:17	Duplicate Event:Location	= LANCASTER RD,BEACH HAVEN,	AUCKLAND, Type = STRU -
10:59:17	INC INFO: HOUSE FIRE		
10:59:17	STRUCTURE FIRE, Calle	er Ph Number =, Call S	ource = 111Inc InfoHOUSE
10:59:17	FIRE, Event Source = Fire	e 111	
10:59:17	End of Duplicate Event da	ata	
10:59:20	INC INFO: HOUSE FIRE		×
10:59:20	Duplicate Event:Location	= 44 LANCASTER RD,BEACH HAVE	EN,AUCKLAND, Type = STRU -
10:59:20	STRUCTURE FIRE, Calle	er Name = FIRST COMMERCIALS LI	MITED, Caller Ph Number =
10:59:20	Caller Add	ress = TELECOM CELLULAR 027, K	ERIKERI, FAR NORTH
10:59:20	DISTRICT, Call Source =	111Inc InfoHOUSE FIRE, Event Sou	rce = Central Admin
10:59:20	End of Duplicate Event da	ata	
10:59:25	Unit TAKA807 [ SITREP :	] ADVISE BIRK821 12 MINS	
10:59:28	Duplicate Event:Location	= 44 LANCASTER RD,BEACH HAVE	EN,AUCKLAND, Type = STRU -
10:59:28	STRUCTURE FIRE, Call	Source = 111Inc InfoHOUSE FIRE	0
10:59:29	** Requirement PUMP ad	ded for alarm level 1	
10:59:29	INC INFO: HOUSE FIRE		
10:59:29	End of Duplicate Event da	ata	
10:59:33	** Recommended unit AL	BA851 for requirement ADHOC PUM	P (>4.4 km)
10:59:36	Duplicate Event:Location	= LANCASTER RD,BEACH HAVEN,	AUCKLAND, Type = STRU -
10:59:36	INC INFO: HOUSE FIRE		
10:59:36	STRUCTURE FIRE, Calle	er Ph Number =	ource = 111Inc InfoHOUSE
10:59:36	FIRE, Event Source = Fire	ə 111	
10:59:36	End of Duplicate Event da	ata	
10:59:41	INC INFO: HOUSE FIRE	MAKES PUMPS THREE	
11:00:04	INC INFO: SMOKE IN VIO	CNITY	
11:00:04	Duplicate Event:Location	= LANCASTER RD,BEACH HAVEN,	AUCKLAND, Type = MIN -
11:00:04	MINOR, Caller Ph Numbe	er = , Call Source = 111Ir	nc InfoSMOKE IN VICNITY,
11:00:04	Event Source = Fire 111		
11:00:04	End of Duplicate Event da	ata	
11:00:19		= LANCASTER RD,BEACH HAVEN,	AUCKLAND, Type = STRU -
11:00:19		er Ph Number =, Call So	
11:00:19	Event Source = Fire 111	, · · · · ·	,
11:00:20	INC INFO: HOUSE		
11:00:20	End of Duplicate Event da	ata	
11:00:28		= LANCASTER RD,BEACH HAVEN,	AUCKLAND, Type = STRU -
11:00:28	INC INFO: HOUSE FIRE	,	
11:00:28		er Name =, Caller	r Ph Number =
11:00:28		DM CELLULAR 027,, Call Source = 1	
11:00:28	Event Source = Fire 111		

SMS Incident Report	F2375856	5/10	11/09/2017 09:28:3
11:00:28	End of Duplicate Eve	ent data	
11:00:47	Duplicate Event:Loca	ation = LANCASTER RD,BEACH HAVEN,AUC	(LAND, Type = STRU -
11:00:47	INC INFO: THINKS	THERE IS A HOUSE FIRE	
11:00:47	STRUCTURE FIRE,	Caller Ph Number = , Call Source	e = 111Inc InfoTHINKS
11:00:47	THERE IS A HOUSE	EFIRE, Event Source = Fire 111	
11:00:47	End of Duplicate Eve	ent data	
11:00:56	Unit ALBA851 [ K1 :	PROCEEDING TO INCIDENT]	×
11:01:16	Duplicate Event:Loca	ation = LANCASTER RD,BEACH HAVEN,AUCH	(LAND, Type = STRU -
11:01:16	STRUCTURE FIRE,	Caller Name =, Ca	ller Ph Number =
11:01:16	, Caller	Address = HELLYERS STREET, BIRKDALE	, AUCKLAND CITY, Call
11:01:16	Source = 111Inc Info	HOUSE FIRE, Event Source = Fire 111	ON
11:01:17	INC INFO: HOUSE F	FIRE	
11:01:17	End of Duplicate Eve	ent data	~O.
11:02:17	Duplicate Event:Loca	ation = LANCASTER RD,BEACH HAVEN,AUCH	KLAND, Type = STRU -
11:02:17	STRUCTURE FIRE,	Caller Ph Number = , Call Source	= 111Inc InfoHOUSE,
11:02:17	Event Source = Fire	111	
11:02:18	INC INFO: HOUSE		
11:02:18	End of Duplicate Eve	ent data	
11:02:30	INC INFO: SMOKE I	N VICINITY	
11:02:30	Duplicate Event:Loca	ation = LANCASTER RD,BEACH HAVEN,AUCH	KLAND, Type = MIN -
11:02:30	MINOR, Caller Ph N	umber =, Call Source = 111Inc In	foSMOKE IN
11:02:30	VICINITY, Event Sou	urce = Fire 111	
11:02:30	End of Duplicate Eve	ent data	
11:05:01	INC INFO: HOUSE F		
11:05:01	Duplicate Event:Loca	ation = LANCASTER RD,BEACH HAVEN,AUCH	(LAND, Type = STRU -
11:05:01	STRUCTURE FIRE,	Caller Ph Number = , Call Source	e = 111Inc InfoHOUSE
11:05:01	FIRE, Event Source	= Fire 111	
11:05:01	End of Duplicate Eve	ent data	
11:05:21	Duplicate Event:Loca	ation = LANCASTER RD,BEACH HAVEN,AUCH	KLAND, Type = MIN -
11:05:21	INC INFO: SMOKE I	N THE VICINITY	
11:05:21		RIBERS FOR CALLER NUMBER	SA LOOKUP RECOMMENDED.
11:05:21	MINOR, Caller Name	e = BEACH HAVEN PRIMARY SCHOOL, Caller	Ph Number =
11:05:21	Caller Address =	ROAD, BEACH HAVEN, AUCKLAN	ID CITY, Call Source =
11:05:21	111Inc InfoSMOKE I	N THE VICINITY , Event Source = Fire 111	
11:05:21	End of Duplicate Eve	ent data	
11:05:36	COVERING UNIT D	EVO811 DISPATCHED TO STATION TAKAPU	NA
11:05:36	D0710063		
11:06:03	Unit BIRK821 [ K88 :	PROPERTY SMALL]	
11:06:09	Unit BIRK821 [ KC :	-	
11:06:41	_	IN ATTENDANCE AT INCIDENT]	

SMS Incident Report	F2375856	6/10	11/09/2017 09:28:36
11:07:01	Unit BIRK821 [ SI	TREP : ] SO WILKSONSON RESIDENTIAL DWELLI	NG HALF OF HOUSE WELL
11:07:01	INVOLVED IN FIR	RE POWER COMPANY REQUIRED	
11:07:07	Unit BIRK821 [ K1	1E : ELECTRICAL AUTHORITY REQUIRED]	
11:07:41	COVERING UNIT	WEST671 DISPATCHED TO STATION ALBANY AT	-
11:07:41	D0710063		
11:09:00	Unit ALBA851 [ K2	2 : IN ATTENDANCE AT INCIDENT]	
11:13:28	Unit BIRK821 [ KC	C : UNIT CALLING]	×
11:13:55	Unit BIRK821 [ SI <sup>-</sup>	TREP : ] 1LPD 1HPD AND PPV IN USE	
11:14:06	Unit BIRK821 [CO	MCEN COM : MESSAGE] VECTOR ETA 30 MINS	
11:14:16	Unit BIRK821 [ SI <sup>-</sup>	TREP : ] 2X BA TEAMS OPERATING	0
11:17:33	Duplicate Event:Lo	ocation = 44 LANCASTER RD,BEACH HAVEN,AUCH	KLAND, Type = STRU -
11:17:33	CALLER ADVISES	S "HOME OWNER" ENROUTE	
11:17:33	INC INFO: HOUSI	E FIRE	0.
11:17:33	STRUCTURE FIR	E, Caller Ph Number =, Call Source =	111Inc InfoHOUSE
11:17:33	FIRE, Event Source	ce = Fire 111	
11:17:33	End of Duplicate E	Event data	
11:21:50	Unit AUCKOSU1 [	K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT	ADDRESS]
11:21:54	Unit AUCKOSU1 [	[K1 : PROCEEDING TO INCIDENT]	
11:21:55	Unit AUCKOSU1 [	[K39 : RE-TRANSMIT YOUR CURRENT STATUS]	
11:22:20	Unit BIRK821 [ KC	C: UNIT CALLING]	
11:22:56	Unit BIRK821 [ K1	1P : POLICE REQUIRED] SUSPICOUS	
11:23:01	Unit BIRK821 [ K1	2 : SUSPICIOUS FIRE]	
11:23:11	Unit BIRK821 [ SI	TREP : ] ALL PERSONS ACCOUNTED FOR	
11:23:37	FIR2POL: FIRE O	N SCENE AT A SUSPICIOUS HOUSE FIRE - REQU	JEST POLICE ATTENDANCE
11:26:30	Unit BIRK821 [ KC	C : UNIT CALLING]	
11:27:00	Unit BIRK821 [ SI	TREP : ] REQUEST FIRE SAFETY	
11:27:05	Unit BIRK821 [ K1	1F : FIRE SAFETY REQUIRED]	
11:27:48	INC INFO: HOUSI	E FIRE TOC: 1056 TOA: 1106	
11:31:39	Unit FIWAITEM2 [	SITREP : ] (VIA PHONE) CAN YOU HAVE THE OIC	PUT A PROHIBITION
11:31:39	ORDER ON THE UNTIL	PROPERTY, CALL THE POLICE AND HAVE THEM	PUT A SCENE GUARD ON
11:31:39	I CAN ATTEND - I	I WON"T BE FREE FROM SQUADRON DRIVE UNT	IL 1600
11:35:11	Unit BIRK821 [ KC	C : UNIT CALLING]	
11:35:37	Unit BIRK821 [ SI	TREP : ] DO WE HAVE AN ETA ON POLICE?	
11:35:55	Unit BIRK821 [CO	MCEN COM : MESSAGE] POLICE HAVE BEEN NO	TIFIED - WE WILL ATTEMPT
11:35:55	TO GET AN ETA I	FOR YOU	
11:36:15			
11:36:16	FIR2POL: FROM	THE APPLICANCE ON SCENE - DO YOU HAVE AN	I ETA?
11:36:17			
11:37:17	AND DO THE PRI	ELIM	

MS Incident Report	F2375856	7/10	11/09/2017 09:28:36
11:37:25	Unit BIRK821 [ K	C : UNIT CALLING]	
11:37:47	Unit BIRK821 [ S	TREP : ] POLICE NOW IN ATTENDANCE	
11:43:35	Unit BIRK821 [ K	C : UNIT CALLING]	
11:44:07	Unit BIRK821 [ S	TREP : ] HOUSING NZ PROPERTY WHICH IS	S NOW UNIHABITABLE
11:44:27	Unit BIRK821 [CC	DMCEN COM : MESSAGE] WOULD YOU LIKE	HOUSING NZ NOTIFIED?
11:44:36	Unit BIRK821 [ S	TREP : ] AFFIRMATIVE	
11:45:35	Unit AUCKOSU1	[ K2 : IN ATTENDANCE AT INCIDENT]	
11:51:56	Unit BIRK821 [ S	TREP : ] VIA PHONE: CAN WE HAVE TOC AN	ND TOA
11:52:05	Unit BIRK821 [CC	DMCEN COM : MESSAGE] VIA PHONE TOC A	ND TOA PASSED
12:05:12	Unit AUCKOSU1	[ K4 : ON RT INSIDE NORMAL TURNOUT AR	EA]
12:06:52	AND GET HIM TO	D RESPOND??	
12:25:54	Unit ALBA851 [ K	3 : ON RT OUTSIDE NORMAL TURNOUT ARI	EA]
12:26:07	Unit BIRK821 [ K	C : UNIT CALLING]	.0.
12:26:21	Unit BIRK821 [ K	10 : RECOMMISSIONING]	
12:38:27	Unit TAKA807 [ K	C : UNIT CALLING]	
12:38:57	Unit TAKA807 [ K	45 : COMMAND RESPONSIBILITY CHANGED	TO - NAME] SSO WEBSTER
12:57:03	Unit TAKA807 [C	OMCEN COM : MESSAGE] ETA FOR FIRE IN	VESTIGATOR IS UNDER ONE HOUR
13:21:04	Unit TAKA807 [ K	C : UNIT CALLING]	
13:21:20	Unit TAKA807 [ K	26-1 : APPLIANCE STILL ENGAGED, NO ADE	DITIONAL DEVELOPMENTS]
13:26:47	Unit FIWAITEM2	[ K38 : ASSOCIATE THIS UNIT TO EVENT - E	VENT ADDRESS] (VIA PHONE)
13:26:51	Unit FIWAITEM2	[ K1 : PROCEEDING TO INCIDENT]	
13:41:00	Unit FIWAITEM2	[ K2 : IN ATTENDANCE AT INCIDENT]	
13:56:40	Unit BIRK821 [ K	1 : PROCEEDING TO INCIDENT] FC	
13:58:48	Unit TAKA807 [ K	C : UNIT CALLING]	
13:59:32	Unit TAKA807 [C	OMCEN COM : MESSAGE] NO RESPONSE T	O RADIO X 2
13:59:45	Unit TAKA807 [ K	C : UNIT CALLING]	
14:00:06	Unit TAKA807 [ K	26-1 : APPLIANCE STILL ENGAGED, NO ADD	DITIONAL DEVELOPMENTS]
14:00:48	Unit BIRK821 [ K	C : UNIT CALLING]	
14:01:26		2 : IN ATTENDANCE AT INCIDENT]	
14:01:30	Unit BIRK821 [ K	31 : REQUEST PERMISSION TO GO OFF RT]	
14:01:44	Unit BIRK821 [CC	- DMCEN COM : MESSAGE] AFFIRM	
14:06:52	Unit TAKA807 [ K	3 : ON RT OUTSIDE NORMAL TURNOUT ARI	EA]
14:07:56		C : UNIT CALLING]	-
14:08:30	_	TREP : ] SO DEVONPORT: K45 SO WILKINS	ON
14:08:43	_	45 : COMMAND RESPONSIBILITY CHANGED	
14:13:59	Unit FIWAITEM2	[ SITREP : ] THERE IS ASPESTOS ON SITE F	- IERE
14:17:27	*ASBESTOS		
14:17:52		[ SITREP : ] BIRK821 ARE CURRENTLY TAKI	NG DOIWN SOME ROOFING
14:17:52		WEARING THEIR APR	
14:47:39		K4 : ON RT INSIDE NORMAL TURNOUT ARE	EA]

MS Incident Report F2375	856 8/10	11/09/2017 09:28:3			
15:01:59	Unit BIRK821 [ KC : UNIT CALLING]				
15:02:44	Unit BIRK821 [ STOP : MESSAGE] NO FURTHER STANDBYS REQUIRE	D			
15:04:12	Unit BIRK821 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]				
15:36:39	Unit FIWAITEM2 [ SITREP : ] (VIA PHONE) LEAVING HERE NOW, RETU	RNING 0800 HRS			
15:36:39	TOMORROW - POLICE HAVE A SCENE GUARD IN PLACE				
15:36:54	Unit FIWAITEM2 [ K6 : ON TELEPAGER]				
15:38:23	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q	1, 💊			
15:38:23	Qualifier 2:	NC2			
Incident		-Cr			
CAD Number	F2375856	:(0)			
Incident Reporter	Russell Wilkinson				
Incident Controller	Russell Wilkinson	<i>y</i>			
Distance Travelled (km)	2				
Delay In Receiving Call	SO S				
Property Details					
Occupant	Unknown				
-					
Building Owner	Housing NZ				
General Property Use	Single house				
Special Property Use	Single house				
Purpose Group					
Actions					
Persons Reported Trapped	No				
Evacuation Status	Not occupied at time of incident				
Action Prior 1	No action taken by Civilian/Occupant/Passerby				
Action Prior 2	6				
Action Taken	Extinguishment and ventilation				
0	5				
Civilians					
Civilians Rescued					
Civilians Extricated					
Civilians Assisted					
Civilians Evacuated					
Origin					
-	ounge, Common room, TV room, Sitting room, Music room				

# SMS Incident Report

Level

Ground level

**Equipment Used** 

Quantity	Equipment		
1	Hose reel, high pressure delivery		
1	Low pressure delivery		
1	Thermal Imaging Camera		
2	Hand tools - Crowbar, Saw, Hammer, Mop, Broom, Misc small gear		
10	Scene protection equipment (eg. signs, tarps, lighting, safety wands etc		
Equipment Involved			
Equipment Involved			
Year			
Make			
Model			
Fire			
Arrival Condition	Small fire		
Heat Source	Matches		
Termination Stage	Flame		
First Object Ignited	Unknown		
First Object Material	Unknown		
Second Object Ignited			
Second Object Material			
Indicated Cause	Suspicious		
Certainty of Cause	High		
Age of Person	Unknown		
Ethnicity	Unknown		
Gender			
FAIP Service Offered	No FAIP Service Accepted No		
~			
Alarms			

Type of Alarm Initiating Call **Domestic Smoke Alarms** 

Performance of System

Failure/Ineffectiveness of system Number of sprinkler heads operated

Detector Not in Room operated AND was EFFECTIVE

F2375856

11/09/2017 09:28:36

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside NZ Fire and Emergency without prior approval

9/10

Structure		
Area of One Floor		150
Age of Building	1970 - 1991	
Structural Frame Type	Timber frame unprotected (normal housing)	
Number of Floors		1
Number of Basements		0
Internal Wall Lining	Gypsum board (e.g. Gib board, Elephant board)	
Ceiling Lining	Pinex	
Material Generating Most Flame	Wood: Sawn, Finished timber	
Material Generating Most Smoke	Wood: Sawn, Finished timber	
Avenue of Flame Travel	Floor, ceiling failure	
Avenue of Smoke Travel	Door open	
Extent of Flame Damage	Confined to structure of origin	
Area of Flame Damage		80
Extent of Smoke Damage	Confined to structure of origin	
Area of Smoke Damage		150
Extent of Water Damage	Confined to structure of origin	
Area of Water Damage		100
Extent of Fire Control Damage	Confined to structure of origin	
Area of Fire Control Damage	derthe	10