

Agnes Owusu

From: WorkSafe online notifiable event submission <@>
Sent: Tuesday, 2 November 2021 10:12 am
To: Healthsafety Notification
Subject: Notifiable Event Submission

Categories: Pauline, Scene Clearance

Submission date

11/2/2021

Submission time

10:11:17 AM

What date did the event happen?

01/11/2021

What time did the event happen?

3 PM

notificationType

incident

Did the event involve any of the following?

None of these

Notification method

web form

Notification Reference ID

ON-b44c088f-d7f0-4742-bae1-7614393608e6

How did the event happen?

Staff were working on the top of Dome 2 applying a sealant tape. Noticed smoke coming out of the top of the dome. They used their fire extinguisher on the area they were in, while doing this, s9(2)(a) leg came into contact with the side of the dome which caused a minor burn. Seen by ambulance staff and advised to get it checked to see if any fiber glass from the dome was in the injury. I also reported this over the phone at 3.31pm on 1 November 2021. The phone call lasted 9 minutes from that time.

What is the address where the event happened?

Shuttle Drive, Bromley, Christchurch, New Zealand

Describe where at the address the event happened.

Trickle Filters at the Waste Water Treatment Plant in Christchurch

What item or substance was directly involved with the incident?

I don't know

Incident type

Injury

Was it an injury or an illness?

Injury

Has the scene been preserved?

Yes

Has your business or organisation begun investigating the event?

Yes

Has another government organisation been notified?

Fire and Emergency New Zealand

Did the incident put someone's health and safety seriously at risk?

Yes

Your name

s9(2)(a)

Your email address

s9(2)(a)@goleman.co.nz

Your phone number

s9(2)(a)

Your job title or role

Health and Safety Manager

Legal name

EXTERIOR BUILDING CARE GOLEMAN LIMITED

Trading name

No trading name

Who should we contact about this notification?

s9(2)(a)

Email address for the contact person

s9(2)(a)@goleman.co.nz

Physical address

20 Gasson Street, Sydenham, Christchurch

Direct dial phone number for the contact person

s9(2)(a)

NZBN

9429032436549

Industry

Arts, Recreation and Other Services

Website

www.goleman.co.nz

Are there Health & Safety representatives at the workplace?

Yes

Have any of them received the NZQA training?

Yes

Postal address

PO Box 10202

How many people were hurt or became sick during the incident?

1

Victim 1

What is their name?

s9(2)(a)

What is their gender?

Male

What is their phone number?

s9(2)(a)

What is the person's relationship to your business or organisation?

Your employee

What is their job?

Technician or Trades Worker

Body Part

s9(2)(a)

How were they hurt?

Contact with heat or cold

How long has the person worked at the business or organisation?

6 months - a year

How many hours had they worked before the event happened?

7 hours 30 minutes

Have you (or anyone else) called us already about this event?

Yes