

# Traffic Crash Report - External Copy

## Date/Time and Location

CARD Event #:	P046089926	DOCLOC #:	210408/1227
Occurrence ID #:	263120044181	Occurred Date/Time:	07/04/2021 15:51
Location Description:	ULSTER STREET, WHITIORA, HAMILTON CITY		
Location Type:	Point Of Impact	Side Road or Feature:	
GPS Coordinates:	-37.776340, 175.267273		
Reported By:	VKCJ43		

## What Happened

Officer Notes:	TBA
Objects Hit:	Holden Commodore LT WAGON 2.0PT/9AT vehicle urgent duty driving collided with Honda Crv RVI 5D AT 2.4 WAG vehicle which turned in front of police vehicle.
Crash Diagram:	See final page of this report.

## Why Crash Happened

Road & Roadside Factors:	4 lanes. Two way road with grass verge. Governed by 60km/h speed zone. Medium turning bay.
Road User Factors:	Drivers to be interviewed.
Vehicle Factors:	Both vehicles with current wof.
Speed Factors:	To be ascertained from drivers. Driver of Honda vehicle turning into Alcamo motel from Ulster street at low speed.
Environmental Factors:	Dry road. Bright sun.

## Vehicles Involved

Vehicle: LLP415, 2018 Holden COMMODORE, Stationwagon, Car White

Vehicle Type:	Car	CAS Vehicle Type:	Car/Wagon
Primary Colour:	WHITE	Secondary Colour:	N/A
WoF/CoF Expiry:	02/07/2021	TSL:	N/A
Additional Devices:		Total Passengers (Front):	1
Total Passengers (Rear)		Total Passengers (Other):	
Vehicle Usage:	Police		

## SPEED AND TRAVEL DIRECTION

Road Travelled On:	ULSTER STREET, WHITIORA, HAMILTON	Travel Direction:	East
State Before Crash:	Moving forward	Suspected Speed Before Crash:	kmh
Too Fast for Conditions?			

## DAMAGE SEVERITY AND LOCATION

Damage Severity:	<ul style="list-style-type: none"><li>Minor/moderate</li></ul>	Specific Damage Location:	<ul style="list-style-type: none"><li>Front - 1</li><li>Front - 6</li></ul>
------------------	--	---------------------------	---

## DRIVER DETAILS

[REDACTED]		(24yrs)
Gender:	Female	
Address:	(Work Address) 12 ANZAC PARADE, HAMILTON CENTRAL, HAMILTON CITY 3204	
Phone Number:	(Home) [REDACTED] (Unconfirmed)	Email: [REDACTED]
Driver's Comments:	To be interviewed.	

## INJURIES

Injury Scale:	None	
Restraint Used:	Yes	Supplementary Devices: ● Airbag Deploy

## LICENCE DETAILS

NZ Licence #:	[REDACTED]	Licence Conditions Met?:	Yes
Licence Type:	Full	Licence Status:	Current

## JOURNEY INFORMATION

Came From:		Day Start Time:	
Company Vehicle?	Yes		
Journey Part of Work?	Yes	Journey Purpose:	Work related trip
Hours of Sleep: (In the last 24 hours)		Hours of Driving:	
Hours Worked: (Since last 24 hour rest period)		Hours Worked: (Since last 10 hour rest period)	
Hours Worked: (Since last 30 minute rest period)		Last Rest Time:	
Last Rest Location:			

## IMPAIRMENT

Passive Breath Test:	Negative	Breath Screening Test:	Screen Negative
Evidential Breath Test:		Breath Reading:	
Drugs Involved:	Not Suspected		
Blood Tested:	Not Done		

**PASSENGER DETAILS (1)**

[REDACTED]

Passenger's Comments:

Disclosed to fyi-request-18445-3fad3abd@requests.fyi.org.nz under the Official Information Act 1982

Vehicle: [REDACTED] 2004 Honda CRV, Light Van, Commercial Vehicle Gold

Vehicle Type:	Commercial Vehicle	CAS Vehicle Type:	Van
Primary Colour:	<span style="background-color: yellow; border: 1px solid black;">GOLD</span>	Secondary Colour:	N/A
WoF/CoF Expiry:	28/10/2021	TSL:	N/A
Additional Devices:		Total Passengers (Front):	1
Total Passengers (Rear):	1	Total Passengers (Other):	
Vehicle Usage:	Private		

### SPEED AND TRAVEL DIRECTION

Road Travelled On:	ULSTER STREET, WHITIORA, HAMILTON	Travel Direction:	West
State Before Crash:	Moving forward	Suspected Speed Before Crash:	kmh
Too Fast for Conditions?			

### DAMAGE SEVERITY AND LOCATION

Damage Severity:	<ul style="list-style-type: none"><li>Minor/moderate</li></ul>	Specific Damage Location:	<ul style="list-style-type: none"><li>Right - 3</li><li>Left - 4</li></ul>
------------------	--	---------------------------	--

## DRIVER DETAILS

[REDACTED]		(84yrs)
Gender:	Female	
Address:	(Home Address) [REDACTED]	
Phone Number:	(Home) [REDACTED] (Unconfirmed)	Email:
Driver's Comments:	To be interviewed.	

## INJURIES

Injury Scale:	None	
Restraint Used:	Yes	Supplementary Devices:

## LICENCE DETAILS

NZ Licence #:	[REDACTED]	Licence Conditions Met?:	Yes
Licence Type:	Full	Licence Status:	Current

## JOURNEY INFORMATION

Came From:	Unknown	Day Start Time:	
Company Vehicle?	No		
Journey Part of Work?	No	Journey Purpose:	Personal Travel eg: Shopping, sports, visiting friends

## IMPAIRMENT

Passive Breath Test:	Negative	Breath Screening Test:	Screen Negative
Evidential Breath Test:		Breath Reading:	
Drugs Involved:	Not Suspected		
Blood Tested:	Not Done		

**PASSENGER DETAILS (2)**

[REDACTED]

Passenger's Comments: \_\_\_\_\_

[REDACTED]

Passenger's Comments: To be interviewed.

Disclosed to fyi-request-18445-3fad3abd@requests.fyi.org.nz under the Official Information Act 1982










## Environment and Road Conditions

Speed Limit:	60	Temporary Speed Limit:	
Road Curvature:	Straight		
Road Type:	2-Way		
Total Lanes:	4	Road Feature:	None
Gradient:	Flat Road	Surface Type:	Sealed
Surface Moisture:	Dry	Surface Condition(s):	
Special Purpose Lane:	Cycle	Road Markings:	<ul style="list-style-type: none"><li>• No Stopping Lines/Sign</li><li>• Flush Median</li></ul>
Precipitation:	Fine	Weather:	
Barriers:	<ul style="list-style-type: none"><li>• None</li></ul>		
Natural Light:	Bright Sun	Street Light:	Off
Crash Relates to Intersection?	No	Junction:	None



## Crash Diagram



Date Uploaded: 07/04/2021 22:04

## Photos

There are no photos attached to this Traffic Crash.