

Case Summary Report

Case #: 200105/4806

Current Assignment: Filed,
Waikato District HQ

Assigned: 19/10/2020 14:00:18

Offences

[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]

1V - Vehicle Collision

[REDACTED]

Date/Time: 04/01/2020 18:50:00 to 04/01/2020 18:50:00

Reported: 04/01/2020

Location: (At) [REDACTED] TE RAPA ROAD, BEERESCOURT, HAMILTON CITY 3200

Persons

Gender	Family Or Nickname	First Name	Birth Date	Age	Links
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]

Narrative

[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]

Created by WHN737 06/01/2020 07:07

Traffic Crash Occurred Date/Time: 04/01/2020 18:50

=====

WHAT HAPPENED

=====

Officer Notes:

Vehicle has performed a sustained skid on Forest Lake Road. Police have subsequently located the vehicle on Ridout Street and attempted to stop it. The vehicle has fled at speed and eventually crossed the centreline while turning right from Storey Avenue to Te Rapa straight. He has lost control and his vehicle has rotated 160 degrees with the drivers back side colliding with a concrete fence. The vehicle has come to a stop briefly on the lawn. The vehicle has then driven off and Police have located it abandoned on Mill Street. The Police dog handler and Hamilton City Camera footage located the driver and passenger of the vehicle. Witness statements confirmed the driver and passage.

Objects Hit:

Concrete fence. Minimal damage.

=====

WHY CRASH HAPPENED

=====

Road & Roadside Factors:

Nil

Road User Factors:

Alcohol, speed, insufficient licence and experience and manner of driving.

Vehicle Factors:

Nil.

Speed Factors:

Vehicle travelling in excess of speed limits throughout Maeroa/Forest Lake.

Environmental Factors:

Nil.

██

██

██

