

Case Summary Report





Created by MTM832 19/03/2020 15:03

Traffic Crash Occurred Date/Time: 13/03/2020 19:32

	=============
THE THAT HAD DEALED	
WHAT HAPPENED	
=======================================	
Officer Notes:	-
Velida Delica anno del	t
Vehicle parked outside address on Pukete Road. Police engaged ?Driver of was attempting to evade police by driving on the footpa	
been spiked. In doing so the front left of the made contact with the	
. The police pursuit has ended and the driver of	ustody. The driver of
approached police to advise of the damage to his vehicle. Event number le	ft with driver
	- Mat
Objects Hit:	la l
?Front left of has made contact with the rear right hand side of	during a police
pursuit.	KIIO
	0,
WHY CRASH HAPPENED	
	_
Road & Roadside Factors:	
N/A	
	_
Road User Factors:	
Fashidden driver in a stelen vahide the mating to fine from Delice	
Forbidden driver in a stolen vehicle attempting to flee from Police.	
	-
Vehicle Factors:	
Vehicle had been spiked and tyres were disintegrating	
verlice had been spined and tyres were distillegrating	
	-
Speed Factors:	
N/A	
	-
Environmental Factors:	
N/A	



325000313862 **CARD Event:** P041318615 Occurrence ID:

Disclosed to randomatata and the state of th