

SMS Incident Report


22/05/2017 11:02:34

Summary

CAD Number F2310716 **Status** Closed
Station Mangere Station
Incident Started 20/05/2017 17:41:47 **Incident Ended** 20/05/2017 18:30:50
Incident Type 5199: Special service call - not classified above
Common Name
Address 273B KIRKBRIDE ROAD MANGERE
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 143509
Map Grid E 1759612 **Map Grid N** 5906303
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 20/05/2017 18:30:50
Report Completed 18:37, Sun 21 May 2017 by Theunis Wedzinga

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
MANG351	P1	17:43:46 20 May 2017	17:45:43 20 May 2017	17:45:43 20 May 2017	17:59:08 20 May 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
MANG351	00:01:59	00:01:57	00:03:56	00:17:21

Notifications

Date	Time	Party Notified
20 May 2017	17:43:01	INJURIES

Message Log

Time	Message
17:42:31	INC INFO: TREE FALLEN ONTO HOUSE
17:42:33	** LOI search completed at 20/05/17 17:42:33
17:42:53	EVERYONE IS OUT
17:43:40	** Recommended unit MANG351 for requirement PUMP (>0.8 km)
17:43:48	TREE HAS FALLEN ON THE KITCHEN ROOF
17:44:37	██████ LIVES ALONE AND IS VERY CONCERNED
17:45:11	SHE IS VERY UPSET AND NOT SURE WHAT TO DO NEXT
17:45:27	SHE IS UNSE OF THE EXTENT OF DAMAGE DONE TO HER HOUSE
17:45:44	Unit MANG351 [K55 : SPECIAL SERVICE EVENT]
17:47:23	UNSURE OF EXTENT OF DAMAGE
17:50:41	Unit MANG351 [KC : UNIT CALLING]
17:51:15	Unit MANG351 [SITREP :] SO WEDZINGA. TREE LANDED ON ROOF. NO STRUCTURE DAMAGE.
17:51:15	INVESTIGATING
17:57:07	Unit MANG351 [KC : UNIT CALLING]
17:58:57	Unit MANG351 [STOP : MESSAGE] OCCUPANT TO ORGANISE ARBORIST TO REMOVE TREE
17:59:09	Unit MANG351 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
18:30:49	UNIT MANG351 RESPONSE TIME [NULL] ADJUSTED TO
18:30:49	** Assigned Result Code: NAT1, Detailed Event Type: 9900, Qualifier 1: Q1,
18:30:49	Qualifier 2:

Incident

CAD Number	F2310716
Incident Reporter	Theunis Wedzinga
Incident Controller	SO Wedzinga
Distance Travelled (km)	2
Delay In Receiving Call	

Property Details

Occupant	
Building Owner	
General Property Use	Flat, Apartment, Home unit
Special Property Use	Flats, Apartments, Units 1 to 2
Purpose Group	

Actions

Persons Reported Trapped

Evacuation Status

Action Prior 1

Action Prior 2

Action Taken Investigation Only (Non-Fire related)

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	0

Origin

Location

Level

Equipment Used

Quantity	Equipment
0	No equipment used

Equipment Involved

Equipment Involved

Year

Make

Model

Comments

5/21/2017 6:36:41 PM

Reporter Comments

Small tree down on roof of house. No structural damage or any damage. Tree from the neighbours who will organise removal of tree via insurance.

Theunis Wedzinga

Released under the Official Information Act