# **SMS Incident Report**

05/09/2017 08:43:24

**Summary** 

CAD Number F2370764 Status Closed

**Station** Ngongotaha Volunteer Fire Brigade

Incident Started 29/08/2017 22:33:00 Incident Ended 29/08/2017 23:20:01

**Incident Type** 4402: Arcing, shorted electrical equipment

**Common Name** 

Address 18A BEAUMONT ROAD NGONGOTAHA

Alarm Method 111 Telephone Alarm Level 1

**PFA Number** 

**Zone** 188201

**Map Grid E** 1881875 **Map Grid N** 5779877


First Caller Contact

Incident Closed 29/08/2017 23:39:48

Report Completed 18:40, Mon 04 Sep 2017 by

#### Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
NGON821	P1	22:33:46 29 Aug 2017	22:37:24 29 Aug 2017	22:38:39 29 Aug 2017	23:22:13 29 Aug 2017
NGON822	P2	22:38:11 29 Aug 2017	22:38:22 29 Aug 2017	22:39:19 29 Aug 2017	22:53:37 29 Aug 2017
ROTO811	P1	22:33:49 29 Aug 2017	22:35:09 29 Aug 2017	22:41:07 29 Aug 2017	22:53:23 29 Aug 2017



# **Elapsed Times**

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
NGON821	00:00:46	00:04:53	00:05:39	00:49:13
NGON822	00:05:11	00:01:08	00:06:19	00:20:37
ROTO811	00:00:49	00:07:18	00:08:07	00:20:23

# **Notifications**

Date	Time	Party Notified
29 Aug 2017	22:34:35	UNISON
29 Aug 2017	22:57:36	UNISON ETA JUST UNDER 10 MINS

# **Message Log**

Time Message		
22:33:27	INC INFO: POWERBOX ON FIRE	
22:33:28	** LOI search completed at 29/08/17 22:33:28	
22:33:39	** Recommended unit NGON821 for requirement PUMP (>0.2 km)	
22:33:39	** Recommended unit ROTO811 for requirement PUMP (>5.6 km)	
22:33:58	AL: PAGING ACK RECEIVED FROM STATION 1882 at 29/08/17 22:33:57	
22:35:05	ATTACHED TO HOUSE	
22:35:09	Unit ROTO811 [ K1 : PROCEEDING TO INCIDENT]	
22:35:12	ADV CALLER TO WAIT OUTSIDE AND STAY AWAY	
22:37:25	Unit NGON821 [ K1 : PROCEEDING TO INCIDENT]	
22:38:08	Unit NGON822 [ KC : UNIT CALLING]	
22:38:23	Unit NGON822 [ K1 : PROCEEDING TO INCIDENT]	
22:38:35	AL: PAGING ACK RECEIVED FROM STATION 1882 at 29/08/17 22:38:35	
22:38:40	Unit NGON821 [ K77 : NOTHING SHOWING]	
22:39:20	Unit NGON822 [ K2 : IN ATTENDANCE AT INCIDENT]	
22:40:26	Unit NGON821 [ KC : UNIT CALLING]	
22:41:03	Unit NGON821 [ SITREP : ] SSO SWITCH BOARD SMOULDERING	
22:41:08	Unit ROTO811 [ K2 : IN ATTENDANCE AT INCIDENT]	
22:41:14	Unit NGON821 [ K11E : ELECTRICAL AUTHORITY REQUIRED]	
22:52:43	Unit NGON822 [ K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]	
22:53:24	Unit ROTO811 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
22:53:38	Unit NGON822 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
22:54:40	Unit NGON821 [ KC : UNIT CALLING]	
22:55:02	Unit NGON821 [ SITREP : ] ETA FOR POWER REQ	
22:57:44	Unit NGON821 [COMCEN COM : MESSAGE] ETA PASSED	
23:19:38	Unit NGON821 [ KC : UNIT CALLING]	
23:20:02	Unit NGON821 [ K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] POWER IN	
23:20:02	ATT	
23:22:14	Unit NGON821 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
23:39:48	** Assigned Result Code: STRU, Detailed Event Type: 1500, Qualifier 1: Q1,	
23:39:48	Qualifier 2:	

Incident

CAD Number F2370764

**Incident Reporter** 

Incident Controller SSO

1

Distance Travelled (km)

**Delay In Receiving Call** 

### **Property Details**

**Occupant** 

**Building Owner** 

General Property Use Flat, Apartment, Home unit

Special Property Use Lawn area, Backyard, Garden area, Patio area

**Purpose Group** 

#### **Actions**

**Persons Reported Trapped** 

**Evacuation Status** 

Action Prior 1

**Action Prior 2** 

Action Taken Extinguishment only: Includes isolating fuel/power supply

#### Origin

**Location** Transformer, Switch gear, Electrical control board

**Level** Ground level

# **Equipment Used**

Quantity	Equipment	
1	Vehicle Radio (LMR)	
3	Handheld Radio (or Cellphone)	
1	Thermal Imaging Camera	
1	CO2 extinguisher	

#### **Equipment Involved**

**Equipment Involved** 

Year

Make

Model

# **Comments**

9/4/2017 6:39:42 PM

**Reporter Comments** 

Main switch has burnt out coursing a fire in main switch board fire stayed with in switch board