

Enquiry: 2647644 Logged by: Iain McCarter on 30/01/2018 09:04

Service: Street Cleaning Classification: Request for Service
 Subject: Road and channel Enquiry Ref: R[59/17366].....

Desc.: cycle way between Tamar St and Adelaide Rd, heading towards the City
 Description:
 Tacks on the cycle way in areas other than near the playcentre
 Other comments:
 Hi, my partner received a puncture in his tire yesterday as well - we found the tack still located in the tire yesterday evening after seeing the news article. We just wanted to let you know as he cycles in an area a long way from the playcentre in case the clean up had focused only in this area referenced in the media.he cycles along the parade from Tamar street up towards Adelaide Road.

Site: The Parade (R1505), Island Bay, Wgtn
 Site Address: The Parade Area: Island Bay
 Location: section 7(2)(a) Ward: Southern
 Island Bay
 Wgtn

Contact: section 7(2)(a)
 Telephone: not provided
 Email: section 7(2)(a)

Customer: 2559330 Time: 30/01/2018 09:04 Method: E-Mail

Name: section 7(2)(a) Telephone: not provided
 Address: section 7(2)(a) Email: section 7(2)(a)
 Island Bay
 Wgtn

Current Status:

No. Effective	Status	Officer	Follow up Date
5	05/02/18 09:10:45 a.n Work Completed - Contractor	Fulton Hogan Sth - Non Urgent	
Notes: Road swept Completed - 1/2/2018 (RAMM ID: 633344)			

Status history:

No. Effective	Status	Officer	Notes
4	30/01/2018 09:30 Acknowledged - Contractor	Fulton Hogan Sth - Non Urgent	Assigned to Eco to action. (RAMM ID: 630423)
3	30/01/2018 09:13 Transferred to RAMM	Fulton Hogan Sth - Non Urgent	RAMM Dispatch ID=59/17366
2	30/01/2018 09:04 Enquiry Issued to Contractor	Fulton Hogan Sth - Non Urgent	section 7(2)(a)
1	30/01/2018 09:00 Enquiry Issued to Contractor	Fulton Hogan Sth - Non Urgent	

Revised Status:

Enquiry: 2647229	Logged by: David Brough	on 29/01/2018 08:53	
Service: Road Dangerous Hazard (Wk Hrs)	Classification: Request for Service		
Subject: Hazard On Road	Enquiry Ref: R[59/17262].....		
Desc.: Caller has advised there are at least 30 tacs on the cycle way near the child care centre on the Parade. She says that they are all approx drawing pin sized. She says that herself and others picked up quite a few tacs last night that were near road. Have logged as dangerous hazard as this resulted in a cyclist having wheels punctured last night.			
Site: The Parade (R1505), Island Bay, Wgtn			
Site Address: The Parade	Area: Island Bay		
Location: section 7(2)(a)	Ward: Southern		
	Contact: section 7(2)(a)		
	Telephone: section 7(2)(a)		
Customer: 2558919	Time: 29/01/2018 08:53	Method: Telephone Call	
Name: section 7(2)(a)	Telephone: section 7(2)(a)		
Address:			
Current Status:			
No. Effective	Status	Officer	Follow up Date
7	30/01/18 08:40:59 a.n Work Completed - Contractor	Fulton Hogan Sth - Urgent	
Notes: Tacks removed from the road. (RAMM ID: 630371)			
Status history:			
No. Effective	Status	Officer	Notes
6	29/01/2018 10:31 Work Completed	Fulton Hogan Sth - Urgent	
5	29/01/2018 10:26 Information Added - relog	Fulton Hogan Sth - Urgent	Further complaints have been received via Social Meida, if possible could the surrounding area be checked as well HP
4	29/01/2018 09:14 Acknowledged	Fulton Hogan Sth - Urgent	
3	29/01/2018 09:03 Transferred to RAMM	Fulton Hogan Sth - Urgent	RAMM Dispatch ID=59/17262
2	29/01/2018 08:49 Enquiry Issued to Contractor	Fulton Hogan Sth - Urgent	29 Jan 8.56am called through to Fulton Hogan. DB
1	29/01/2018 08:49 Enquiry Issued to Contractor	Fulton Hogan Sth - Urgent	
Revised Status:			