

SMS Incident Report


26/02/2018 09:09:59

Summary

CAD Number F2481272 **Status** Closed
Station Grey Lynn Station
Incident Started 14/02/2018 10:20:39 **Incident Ended** 14/02/2018 10:33:24
Incident Type 7103: False Alarm: Defective Apparatus K-46-3
Common Name NORTH SHORE HOSPITAL BUILDING 03 TRADE WORKSHOPS
Address / Shea Terrace Takapuna
Alarm Method Automatic PFA Call **Alarm Level** 1
PFA Number 115170
Zone 148001
Map Grid E 1756740 **Map Grid N** 5927739
First Caller **First Caller Contact**
Incident Closed 14/02/2018 11:05:51
Report Completed 10:2, Fri 23 Feb 2018 by Mark Shaw

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
GREY261	P1	10:20:52 14 Feb 2018	10:22:18 14 Feb 2018	10:26:15 14 Feb 2018	10:33:56 14 Feb 2018
BIRK821	P1	10:20:55 14 Feb 2018	10:22:33 14 Feb 2018	10:30:23 14 Feb 2018	10:41:56 14 Feb 2018



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
GREY261	00:00:13	00:05:23	00:05:36	00:13:17
BIRK821	00:00:16	00:09:28	00:09:44	00:21:17

Notifications

Date	Time	Party Notified
14 Feb 2018	10:32:42	IGNORE ABOVE COMCEN COM

Message Log

Time	Message
10:20:40	AL: 115170 10:20:39 INITIAL - AL
10:20:42	** LOI search completed at 14/02/18 10:20:42
10:20:45	** Recommended unit GREY261 for requirement PUMP (>1.3 km)
10:20:45	** Recommended unit BIRK821 for requirement PUMP (>4.8 km)
10:21:12	NO ACCESS NUMBER
10:22:19	Unit GREY261 [K1 : PROCEEDING TO INCIDENT]
10:22:33	Unit BIRK821 [K1 : PROCEEDING TO INCIDENT]
10:26:16	Unit GREY261 [K77 : NOTHING SHOWING]
10:28:15	Unit GREY261 [KC : UNIT CALLING]
10:28:43	Unit GREY261 [SITREP :] SO SHAW - PANEL SHOWING FIRE ZONE 3 LEFT HAND SIDE
10:28:43	REPORTS OF AGENT WORKING ON SYSTEM
10:29:38	Duplicate Event:Location = 132 SHAKESPEARE RD,TAKAPUNA,AUCKLAND: @NORTH SHORE
10:29:38	TRADE WORKSHOP
10:29:38	A16 -TRADE WORKSHOP
10:29:38	HOSPITAL BUILDING 27 DIALYSIS CENTRE, Type = STRU - STRUCTURE FIRE, Caller Name
10:29:38	INC INFO: ALARM ACTIVATION - COMMERCIAL
10:29:38	= WAITEMATA DISTRICT HEALTHBOARD, Caller Ph Number = [REDACTED] Caller Address
10:29:38	= 132 SHAKESPEARE ROAD, TAKAPUNA, AUCKLAND CITY, Call Source = 111Inc InfoALARM
10:29:38	ACTIVATION - COMMERCIAL, Event Source = North AES
10:29:38	End of Duplicate Event data
10:30:23	Unit BIRK821 [K2 : IN ATTENDANCE AT INCIDENT]
10:32:24	Unit TAKA807 [COMCEN COM : MESSAGE] CAN YOU ADVISE IF FIWAITEM3 IS STILL IN
10:32:24	ATTENDANCE?
10:33:11	Unit GREY261 [KC : UNIT CALLING]
10:33:24	Unit GREY261 [K46-3 : STOP MESSAGE: FALSE ALARM DEFECTIVE APPARATUS]
10:33:57	Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
10:41:58	Unit BIRK821 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:05:51	** Assigned Result Code: STRU, Detailed Event Type: 7100, Qualifier 1: Q1,
11:05:51	Qualifier 2:

Incident

CAD Number	F2481272
Incident Reporter	Mark Shaw

Incident Controller
Distance Travelled (km)
Delay In Receiving Call

False Alarm

Detector Type Thermal detector
False Alarm Cause Equipment | Defect detector - corrosion
Other Cause Detector head corroded. Had been looked at previously by alarm agent.

Property Details

Occupant
Building Owner
General Property Use Hospital, Hospice, Rest home, Rehab centre
Special Property Use Manufacture: Machinery, Engines, Parts
Purpose Group

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	0

Released under the Official Information Act