# **SMS Incident Report**

19/02/2018 14:55:22

Summary			X
CAD Number	F2455653	Status	Closed
Station	Grey Lynn Station		
Incident Started	06/01/2018 17:57:38	Incident Ended	06/01/2018 19:03:13
Incident Type	1102: Structure fire with no damage		× O
Common Name			2
Address	/ 10 Bond Street Grey Lynn		
Alarm Method	111 Telephone	Alarm Level	1
PFA Number			
Zone	142624		
Map Grid E	1755555	Map Grid N	5918551
First Caller		First Caller Contact	
Incident Closed	06/01/2018 19:03:13	SO.	
Report Completed	20:4, Sat 06 Jan 2018 by Martin Can	npbell	

#### Responses

\_

Call Sign	Туре	Station Alert	Enroute T	ime	Arri	val Time		Depa	rted
GREY261	P1	17:58:43 06 Jan 2018	18:00:33 06 Ja	an 2018	18:01:53	06 Jan 201	8 18:	16:48 06	Jan 2018
AUCK207	PR	17:58:46 06 Jan 2018	17:59:47 06 Ja	an 2018	18:02:37	06 Jan 201	8 18:	12:09 06	Jan 2018
Start->Alert	7 min	10 min							
	2								
	2		15 min						

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
GREY261	00:01:05	00:03:10	00:04:15	00:19:10
AUCK207	00:01:08	00:03:51	00:04:59	00:14:31

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside NZ Fire and Emergency without prior approval

Message Log	
Time	Message
17:58:28	INC INFO: SMOULDERING WIRING IN ROOF
17:58:29	** LOI search completed at 06/01/18 17:58:29
17:58:36	** Recommended unit GREY261 for requirement PUMP (>0.6 km)
17:58:36	** Recommended unit AUCK207 for requirement PUMP (>1.7 km)
17:58:55	IN KITCHEN CEILING
17:59:31	OCCUPANTS HAVE TURNED THE POWER TO HOUSE OFF
17:59:48	Unit AUCK207 [ K1 : PROCEEDING TO INCIDENT]
18:00:34	Unit GREY261 [ K1 : PROCEEDING TO INCIDENT]
18:01:54	Unit GREY261 [ K77 : NOTHING SHOWING]
18:02:38	Unit AUCK207 [ K2 : IN ATTENDANCE AT INCIDENT]
18:04:52	Unit GREY261 [ KC : UNIT CALLING]
18:05:12	Unit GREY261 [ SITREP : ] SO CAMPBELL INV SMELL OF SMOKE IN CEILING TIC IN USE
18:12:10	Unit AUCK207 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
18:16:20	Unit GREY261 [ KC : UNIT CALLING]
18:16:45	Unit GREY261 [ STOP : MESSAGE] FIRE IN DOMESTIC REFRIGERATOR ISOLATED FROM POWER
18:16:45	SUPPLY
18:16:50	Unit GREY261 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
19:03:13	** Assigned Result Code: STRU, Detailed Event Type: 1500, Qualifier 1: Q1,
19:03:13	Qualifier 2:

Incident	×Co	
CAD Number	F2455653	
Incident Reporter	Martin Campbell	
Incident Controller		
Distance Travelled (km)		
Delay In Receiving Call		
Dranauty Dataila		
Property Details		
Occupant	Rented property	
Occupant Building Owner	Rented property Single house	
Occupant Building Owner General Property Use		
Occupant Building Owner General Property Use Special Property Use	Single house	
Occupant Building Owner General Property Use Special Property Use Purpose Group	Single house	
Property Details Occupant Building Owner General Property Use Special Property Use Purpose Group Actions Persons Reported Trappe	Single house Single house	

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside NZ Fire and Emergency without prior approval

### Action Prior 1 Action Prior 2

Action Taken

Age of Person

**FAIP Service Offered** 

Ethnicity Gender Extinguishment only: Includes isolating fuel/power

## Civilians

Civilians	
Civilians Rescued	
<b>Civilians Extricated</b>	
<b>Civilians Assisted</b>	
Civilians Evacuated	
Origin	
	Citchen, Cooking area
Level	Ground level
	×O*
Equipment Used	
Quantity	Equipment
1	Equipment Not Listed
Equipment Involved	C C C C C C C C C C C C C C C C C C C
Equipment Involved	
Year	<b>O</b>
Make	Fisher and Paykel (Elba)
Model	N249T
Fire	
Arrival Condition	Out on arrival
Heat Source	Heat from electrical equip: Defective or faulty
Termination Stage	
First Object Ignited	
First Object Material	
Second Object Ignited	
Second Object Material	
Indicated Cause	Other electrical failure
Certainty of Cause	Medium

FAIP Service Accepted No

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside NZ Fire and Emergency without prior approval

No person involved

No

#### Comments

	1/6/2018 8:04:32 PM	Reporter Comments
Burnt out electrical part in DOMESTIC FRIDGE. undetermir	ned electrical fault	
		Martin Campbell
		ACT
		ailo.
	niori	
	C C C	
	O,	
2 er the		
2 Ur		
Released une		
2		
20		

4/4