17/12/2018		Enquiry Trace Form - Preview				
Enquiry	Withheld under se	Logged by:	Withheld under section 7(2)(a)	on 08/05/20	18 20:56	
Service	Service: Street Cleaning			Classification: Complaint		
Subject: Broken Bottles / Glass			Enquiry	Ref: R[57/12521]		
Desc.	Victoria St. Can this I	been cleaned up	please as it has been this w	lot of broken glass on the cycle lane in this section ray for several weeks and it seems as though the swit sweeping rubble into the cycle lane.		
Site	: Victoria St (R1590),	Te Aro, Wgtn				
Site Address: Victoria St			Area: Te Aro			
Location: Victoria St, Te Aro			Ward: Lambton			
				Contact: Withheld under section 7		
2001011		<b>Time</b> : 08	/05/2018 20:56	20:56 <b>Method:</b> Social Media		
Name	Withheld under section 7					
Address	:					
Current Status:						
No. Effective	Status		Officer	Follow up Date		
5 08/05/2018	8 10:01:04 բ Work Com	npleted	Civic CBD			
Status history:						
No. Effective	Status		Officer	Notes		
4 08/05/201	8 21:15 Work Con	npleted	Civic CBD			
3 08/05/201	21:03 Transferred to RAMM		Civic CBD	RAMM Dispatch ID=57/12521		
2 08/05/201	8 21:01 Informatio	n Added	Civic CBD	Called through to Civic Contractors, Street Cleaning FD		
1 08/05/201	8 20:53 Enquiry Is	sued to Contract	or Civic CBD			

Revised Status:

Signed : ...... Date : ...... Time : ..... Name : .....