

ASBESTOS REGISTER SUMMARY

Refer to policy for full description 2.0 Records P3

Updated : 15/06/2012

Building	Identification	Assessment of exposure risk	Monitoring results	Risk Management plans	Inspection details	Details of person(s) exposed	Written assessment records	Register of any examination, inspection / maintenance / engineering controls	Register of inspection of enclosures, hygiene and transit facilities	Records of instruction, information and training	Records of respiratory protective equipment	Register of the use, state and location of asbestos products at all the hospital sites	Records of clearance certificates	Asbestos waste disposal record	PPE, Service, maintenance, cleaning and inspection records	Background asbestos dust level survey records	Notification to DoL of asbestos removal records	Location, state and type of asbestos used / installed	Records of sampling and analysis procedures	Risk assessment done and area notified if appropriate
3 Pharmacy	03-001	0			SPL		YES													
	neg																			
	03-002	21	A		SPL		YES	Removed 30/06/2011												
Subfloor Soil	03-002	21	A		SPL		YES	Removed 30/06/2011												
Subfloor Timbers	03-003	21	A		SPL		YES	Removed 30/06/2011												
<p>WDHB B3.pdf</p> <p>Asbestos Management Report A-00724 - Building 3, Kitchen Block, Waikato Hospital.pdf</p> <p>A-00724 Asbestos Management Plan.docx</p> <p>C = Chrysotile (White) Asbestos A = Amosite (Brown) Asbestos Cr = Crocidolite (Blue) Asbestos</p> <p>pos = positive neg = negative</p> <p>SPL = Sampled SP = Strongly Presumed P = Presumed</p>																				