

Version 2



Statement of Claim Checklist / Repair Strategy

Date: 12.1.2011
 Author: P SIMPSON

CTM/2010/058596

JULIE HAMPTON
 25 WESTFIELD AVENUE
 TEMPLETON
 CHRISTCHURCH 8042



LA: P SIMPSON

Estimator: A Fletcher

Room	Earthquake Damage Y/N	Walls ✓	Ceiling ✓	Floor ✓	Repair Strategy
62 x 4.6 Lounge & Hall	Y	✓			RAKE, STOP AND PAINT Ceilings @ 300 ALL WALLS (LOUNGE + HALL) Replace Damaged Carpet 34 sqm
6.3 x 2.5 Dining Room	Y	✓			RAKE, STOP AND PAINT Ceilings @ 300 ALL WALLS
Kitchen					
Family Room					
Bedroom 1	N				
1st Floor Ensuite	N				
2.2 x 4.5 Bedroom 2	Y	✓			RAKE, STOP AND PAINT Ceilings @ 300 ALL WALLS
2.2 x 6.5 Bedroom 3	Y	✓			RAKE, STOP AND PAINT Ceilings @ 300 ALL WALLS

gsp

JULIE HAMPTON
 25 WESTFIELD AVENUE
 TEMPLETON
 CHRISTCHURCH 8042




SOC / Repair Strategy - Page 2

Version

Room	Earthquake Damage	Walls	Ceiling	Floor	Repair Strategy
	Y/N	✓	✓	✓	
3.5x3.4 Bedroom 4	✓	✓			RAKE, STOP AND PAINT CROWN @ 200 ALL WALLS
D/Smis Bathroom	N	/			
1.4x 900 Toilet 1	✓	✓			RAKE, STOP AND PAINT ALL WALLS (NAIL POPPING)
Toilet 2					
Office / Study					
Rumpus					
Entry / Hall(s)	Y				
3.5x1 Stairwell	✓		✓		RAKE, STOP (S-2 + 1 Crown AND PAINT CEILING ONLY)
3.5x1.8 Laundry	Y	✓			RAKE, STOP + PAINT Crown @ 200 ALL WALLS - 1M
Garage	N				
Conserv Other	N				

JULIE HAMPTON
 25 WESTFIELD AVENUE
 TEMPLETON
 CHRISTCHURCH 8042

Versik



Item		Event Damage	Repair Strategy
		Y / N	
Roof		N	
EXTERNAL WALLS	North	Y	GRAND OUT REPOINT STEPPED CRACKING N + S + E WALLS 10 M 6 hrs
	South	Y	
	East	Y	
	West	Y	DORMER REMOVE REPLACE BROKEN W/B AND REPOINT 4 SQ M 4 HRS \$50 MORE
Decks		N	
CHIMNEY	Base		
	Ceiling Cavity		
	Above Roof		
	Fireplace		

FWE
2/0

grx!
trichis

CLM/2010/058596

JULIE HAMPTON
 25 WESTFIELD AVENUE
 TEMPLETON
 CHRISTCHURCH 8042

SOC / Repair Strategy - Page 4

Versic [REDACTED]

Item	Event Damage	Repair Strategy
	Y/N	
Foundations	Y	Grind out REPLASTER CRACK 02 (1 Hr)
Piling	N/P	
Services	N	
Other Dwelling Items	N	
Outbuildings	N	
Land & Retaining Walls <i>(Discuss with Supervisor)</i>	N	

Supplementary Notes:

Photos of carpet sited, carpet.
 Water damaged in Sept event. plus wine bottles
 broken fallen from shelves sited

I confirm the rooms and areas listed above have been inspected by an EQC representative.

Damage caused by the event has been noted and to my knowledge there are no other areas of damage resulting from the event.

Signature of Claimant: Julie Hampton Dated: 12-1-11

NOTE: THIS FORM IS TO BE COMPLETED IN THE CLAIMANT'S PRESENCE.

.....
 Initials)