

Case Summary Report

Case #: 210827/4341 **ASSOCIATED TO 210826/0416 FILES**

Current Assignment: Filed, BHBZ75 - HOTENE WILSON, BUDDY Hamilton City Area HQ **Assigned:** 24/01/2022 15:35:10

Offences

1V - Vehicle Collision

Date/Time: 22/08/2021 03:30:00 to 22/08/2021 03:30:00 **Reported:** 22/08/2021

Location: (At) KAHIKATEA DRIVE, FRANKTON, HAMILTON CITY 3204

Persons

Gender	Family Or Nickname	First Name	Birth Date	Age	Links
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]

Narrative

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

Created by BHN171 (on behalf of JTNE82) 27/08/2021 19:01

Supervisor's Comments:
For entering and returning to reporting member

Traffic Crash Occurred Date/Time: 22/08/2021 03:30

=====
=====
WHAT HAPPENED
=====
=====

Officer Notes:

This vehicle was involved in numerous failing to stop for police prior to crashing.

The vehicle was travelling south down KAHIKATEA DRIVE, it has driven over the centre island and has lost control crossing into the oncoming lane. The vehicle mounted the footpath it took out the street sign. And business sign crossed over the road. And still travelling at speed has mounted an embankment (1M) and has hit a fixed pole before coming to a stop.

Objects Hit:

The vehicle must have been travelling in the middle of the road. It has drive over the centre island and lost control. The vehicle has hit the Street sign, crossed the centre line and intersection. The vehicle continued up a step embankment

=====
=====
WHY CRASH HAPPENED
=====
=====

Road & Roadside Factors:

Nil.

Road User Factors:

Nil.

Vehicle Factors:

Stolen vehicle.

Speed Factors:

Police believe speed was a factor due to the damage.

Environmental Factors:

Nil.

Occurrence ID: 144960755143 **CARD Event:** P047631303

.....
Initial Actions

