

Job Period 01-06-2024 - 12-05-2026

521968 - GWRC - Airport Bus Stabling Yards - Drawings
525356 GWRC Maintenance
525564 GWRC Maintenance
526162 - GWRC - Beacon Hill - camera masking
526206 - GWRC Kauri St Bus Depot
526281 GWRC Maintenance
526461 - GWRC - Bus Hubs - Daily CCTV camera checks - May 2026
523287 GWRC Maintenance
523525 GWRC Maintenance
524023 GWRC Maintenance
524704 GWRC Maintenance
525431 - GWRC - Bus Hubs - Daily CCTV camera checks - December 2025
525823 - GWRC - Bus Hubs - Daily CCTV camera checks - February 2026
526041 - GWRC 7000 Controllers
526044 - GWRC - Bus Hubs - Daily CCTV camera checks
526159 - GWRC - Newtown Bus Hub - Cam 1 no connection – No browse – No ping
526275 - GWRC - Bus Hubs - April 2026 Daily CCTV camera checks
526437 - GWRC - Houghton Bay - Check mains power v UPS
526481 - GWRC - Revera - Failed hard drive
522011 - GWRC - Miramar Driver Toilets - all cameras offline
522620 - GWRC- Wgtn- PTZ needs cleaning
523787 - GWRC - VMS offline
523850 - GWRC - Jville Bus Hub - Replace 3x UPS
523851 - GWRC - Kilbirnie Bus Hub - Replace failed UPS
523894 - GWRC - Thorndon Bus Hub camera 3 offline
524257 - GWRC - Johnsonville Bus Driver Toilet CCTV
524493 - GWRC - Newtown Bus Hub A - Cam 1 No connection and Cam 2 obscured
524518 - GWRC - Newtown Bus Camera 2 blurred
524620 - GWRC - Miramar Bus Hub B - Failed UPS
524729 - GWRC - 248 Thorndon Quay - live feed and playback drop off
524738 - GWRC Mairangi Driver Toilet - Camera 2 offline
525005 - GWRC - Lambton - CCTV footage
525264 - GWRC - Jville Bus HUB Bus Vs Streetlight pole
525620 - GWRC - Lyall Bay Driver Toilet - Vandalized Camera
525675 - GWRC - Kilbirnie Bus Hubb - CCTV offline
525872 - GWRC - Newtown Bus Hub A - something stuck over the camera
525891 - GWRC - Newtown Hospital Bus Hub - stickers on cameras
525905 - GWRC - Newtown Hospital Bus Hub - Clean all cameras
525983 - GWRC - Newtown Bus Hub - stickers on cameras
525997 - GWRC - Jville Bus Hub - cameras offline
526000 - GWRC - Mairangi BDT - Camera 4 needs cleaning
526040 - GWRC - Newtown Bus Hub - cameras stickered
526102 - GWRC - Houghton Bay - camera needs a clean
526231 - GWRC - Highbury Bus Driver Terminal - Cam 3 cleaning (has bugs)
526308 - GWRC - Houghton Bay Terminus - All cameras no connection
526314 - GWRC - Lyall Bay Terminus Driver Toilet - all cameras offline
519689 GWRC Maintenance

519690 GWRC Maintenance
520118 GWRC Maintenance
520127 - GWRC - Brooklyn Bus Hub - CCTV offline
520173 - GWRC - Houghton Bay Bus Hub - signage over camera view
520195 - GWRC - Houghton Bay Bus Hub - CCTV offline
520481 - GWRC - Kilbirnie Bus Hub - UPS
520741 - GWRC - Karori Bus Driver Toilet CCTV offline
520799 - GWRC - Metlink Toilet - VR01 Connectivity to routers - Miramar
520824 - GWRC- City busses PTZ is pointing straight down
520842 - GWRC - Porirua Station- Camera 39 required cleaning due to tagging
520854 - GWRC- Highbury, Houghton Bay and Mairangi are offline.
521121 GWRC Maintenance
521148 - GWRC- Thordon- Camera 1 and 2 recording state is unavailable
521198 - GWRC - Miramar Bus Driver Terminal - Cameras 1-3 no connection, offline
521325 GWRC Maintenance
521327 GWRC Maintenance
521367 - GWRC - Karori Bus Hub - Cameras offline
521383 - GWRC- Kilbirnie Bus Hub A UPS issues
521559 - GWRC Bunny St- Camera 4 no connection
521594 - GWRC - Bunny St Bus Shelter - replace 4x domes
521636 GWRC Maintenance
521784 - GWRC- Kilbirnie Bus Hub- Camera 2 in shelter A isn't working
521810 GWRC Maintenance
521841 - GWRC - Karori Bus Hub - Camera A 1 needs cleaning
522218 - GWRC- EMU- Recording system issues
522265 - GWRC - Brooklyn Bus Hub - all cameras offline
522339 GWRC Maintenance
522397 - GWRC - Lyall Bay Bus Terminal - Cameras need a clean
522461 - GWRC - Brooklyn Shelter B - UPS failed
522498 - GWRC - Miramar Terminus Driver toilet - CCTV footage
522519 - GWRC - Highbury Terminus - CCTV footage
522529 - GWRC - Houghton Bay Terminus - Focus Camera 2
522591 - GWRC - Lyall Bay Driver Toilets - spider webs on camera
522700 - GWRC- Miramar Bus Hub- Toilet footage for Camera 1 and 2
522704 - GWRC- Wilton Driver Toilets- Footage extractions
522710 GWRC Maintenance
522711 GWRC Maintenance
523669 - GWRC - Bus Hubs - Daily CCTV camera checks
523704 - GWRL - Paraparaumu & Waikanae Stations IQP checks
524474 - GWRC - Bus Hubs - Daily CCTV camera checks - September 2025
524754 - GWRC - Bus Hubs - Daily CCTV camera checks October
524991 - GWRC - Paraparaumu Bus Hub - Cam4 no connection
525106 - GWRC - Bus Hubs - Daily CCTV camera checks - November
525617 - GWRC - Bus Hubs - Daily CCTV camera checks - January 2026

Greater Wellington Regional Council
Metlink Security Contract
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Metlink Security Contract
Greater Wellington Regional Council
Greater Wellington Regional Council
Metlink Security Contract
Metlink Security Contract
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Metlink Security Contract
Greater Wellington Regional Council
Metlink Security Contract
Greater Wellington Regional Council
Metlink Security Contract
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Metlink Security Contract
Metlink Security Contract
Greater Wellington Regional Council
Metlink Security Contract
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council
Greater Wellington Regional Council