

# SMS Incident Report


02/06/2017 11:58:17

## Summary

**CAD Number** F2308314 **Status** Closed  
**Station** Otara Station  
**Incident Started** 16/05/2017 18:55:45 **Incident Ended** 16/05/2017 20:23:35  
**Incident Type** 4499: Electrical hazard - not classified above  
**Common Name**  
**Address** 5 TONUU COURT FLAT BUSH  
**Alarm Method** 111 Telephone **Alarm Level** 1  
**PFA Number**  
**Zone** 143303  
**Map Grid E** 1769281 **Map Grid N** 5907039  
**First Caller** **First Caller Contact** ██████████  
**Incident Closed** 16/05/2017 20:23:35  
**Report Completed** 19:59, Wed 17 May 2017 by Gavin Maxwell

## Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
OTAR331	P1	18:57:09 16 May 2017	18:58:31 16 May 2017	19:02:12 16 May 2017	19:36:59 16 May 2017
PAPA347	PR	18:57:05 16 May 2017	18:58:35 16 May 2017	19:04:30 16 May 2017	19:04:39 16 May 2017



## Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
OTAR331	00:01:24	00:05:03	00:06:27	00:41:14
PAPA347	00:01:20	00:07:25	00:08:45	00:08:54

**Notifications**

Date	Time	Party Notified
16 May 2017	18:58:15	VECTOR
16 May 2017	19:11:30	CHORUS
16 May 2017	19:14:05	CHORUS REF # 51046551

**Message Log**

Time	Message
18:56:39	INC INFO: CAR V POWER BOX
18:56:41	** LOI search completed at 16/05/17 18:56:41
18:56:54	** Event Priority changed from 2 to 1 at: 16/05/17 18:56:54
18:56:54	** Event Type changed from MIN to RESC at: 16/05/17 18:56:54
18:56:59	** Recommended unit PAPA347 for requirement RESCUE (>3.4 km)
18:56:59	** Recommended unit OTAR331 for requirement PUMP (>1.7 km)
18:57:21	AFFECTING 3 HOUSES.
18:57:46	CALLER STATED NO AMB REQUIRED
18:58:32	Unit OTAR331 [ K1 : PROCEEDING TO INCIDENT]
18:58:36	Unit PAPA347 [ K1 : PROCEEDING TO INCIDENT]
18:59:07	NOONE INJURED JUST DAMAGE TO POWERBOX.
19:02:12	Unit OTAR331 [ K55 : SPECIAL SERVICE EVENT]
19:04:31	Unit PAPA347 [ K2 : IN ATTENDANCE AT INCIDENT]
19:04:40	Unit PAPA347 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
19:05:27	Unit OTAR331 [ KC : UNIT CALLING]
19:05:47	VECTOR ETA 40 MINS AS OF 19:05
19:06:14	Unit OTAR331 [ SITREP : ] SSO MAXWELL ONE CAR INTO POWER PLINTH NPT OR INJURED
19:06:14	PLINTH DAMAGED K11 POWER
19:06:49	Unit OTAR331 [COMCEN COM : MESSAGE] VEHICLE REG REQUIRED
19:07:35	Unit OTAR331 [ SITREP : ] VEHICLE REG = BWU903
19:07:41	****
19:07:51	FIR2POL: VEHICLE REG = BWU903
19:07:53	****
19:08:48	Unit OTAR331 [ KC : UNIT CALLING]
19:09:14	Unit OTAR331 [ SITREP : ] K11 TELECOMMUNICATION CO
19:22:54	Unit OTAR331 [ KC : UNIT CALLING]
19:23:38	Unit OTAR331 [ SITREP : ] STANDING BY AWAITING POWER AUTHORITY
19:36:15	Unit OTAR331 [ KC : UNIT CALLING]
19:36:51	Unit OTAR331 [ STOP : MESSAGE] POWER IN ATTENDANCE
19:37:01	Unit OTAR331 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
20:23:35	** Assigned Result Code: MIN, Detailed Event Type: 9900, Qualifier 1: Q1,

20:23:35	Qualifier 2:
----------	--------------

**Incident**

**CAD Number** F2308314  
**Incident Reporter** Gavin Maxwell  
**Incident Controller** SSO Maxwell  
**Distance Travelled (km)** 2  
**Delay In Receiving Call**

**Property Details**

**Occupant**  
**Building Owner**  
**General Property Use** Single house  
**Special Property Use** Lawn area, Backyard, Garden area, Patio area  
**Purpose Group**

**Actions**

**Persons Reported Trapped**  
**Evacuation Status**  
**Action Prior 1**  
**Action Prior 2**  
**Action Taken** Investigation Only (Non-Fire related)

**Comments**

5/17/2017 7:59:15 PM

Reporter Comments

Power plinth run over by car

Gavin Maxwell

Released under the Official Information Act