SMS Incident Report

29/08/2017 08:03:02

Summary

CAD Number F2369657 Status Closed

Station Taupo Station

Incident Started 28/08/2017 09:10:44 Incident Ended 28/08/2017 09:22:43

Incident Type 7103: False alarm: Defective

Common Name FARMERS TAUPO

Address UNKN0001 TUWHARETOA STREET TAUPO

Alarm Method Automatic PFA Call Alarm Level

PFA Number 250112 **Zone** 182101

 Map Grid E
 1867128
 Map Grid N
 5713227


First Caller First Caller Contact

Incident Closed 28/08/2017 10:25:31

Report Completed 15:46, Mon 28 Aug 2017 by Sean McAvinue

Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
TAUP217	PR	09:11:04 28 Aug 2017	09:12:21 28 Aug 2017	09:14:00 28 Aug 2017	09:23:06 28 Aug 2017
TAUP211	P1	09:11:04 28 Aug 2017			09:17:28 28 Aug 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
TAUP217	00:00:20	00:02:56	00:03:16	00:12:22
TAUP211	00:00:20			00:06:44

Message Log

Time	Message	
09:10:44	AL: 250112 09:10:44 INITIAL - AL	
09:10:44	PANEL: BY MAIN ENTRANCE	
09:10:45	** LOI search completed at 28/08/17 09:10:45	
09:10:52	** Recommended unit TAUP217 for requirement PUMP (>0.6 km)	
09:10:52	** Recommended unit TAUP211 for requirement PUMP (>0.6 km)	
09:12:22	Unit TAUP217 [K1 : PROCEEDING TO INCIDENT]	
09:12:30	Unit TAUP217 [K1 : PROCEEDING TO INCIDENT]	
09:12:38	Unit TAUP217 [K1 : PROCEEDING TO INCIDENT]	
09:14:01	Unit TAUP217 [K77 : NOTHING SHOWING]	
09:15:58	Unit TAUP217 [KC : UNIT CALLING]	
09:16:43	Unit TAUP217 [SITREP :] SO MCAVENUE IPS ZONE 7 SMOKE DETECTORS INV	
09:16:56	Unit TAUP217 [KC : UNIT CALLING]	
09:17:22	Unit TAUP217 [K28-1 : RETURN OTHER RESPONDING UNITS] TAUP211	
09:17:29	Unit TAUP211 [K7 : AT NORMAL STATION]	
09:21:11	Unit TAUP217 [KC : UNIT CALLING]	
09:21:56	Unit TAUP217 [KC : UNIT CALLING]	
09:22:43	Unit TAUP217 [K46-3 : STOP MESSAGE: FALSE ALARM DEFECTIVE APPARATUS]	
09:23:08	Unit TAUP217 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
09:31:50	Unit TAUP217 [SITREP :] SO MCAVENUE ALARM AGENT IN ATT	
10:25:30	** Assigned Result Code: STRU, Detailed Event Type: 7100, Qualifier 1: Q1,	
10:25:30	Qualifier 2:	

Incident

CAD Number	F2369657
Incident Reporter	Sean McAvinue
Incident Controller	SO Sean McAvinue

Distance Travelled (km)

Delay In Receiving Call

False Alarm

Detector Type	Smoke detector
False Alarm Cause	Equipment Unable to classify
Other Cause	Undtermined activation

Property Details

Occupant

Building Owner

SMS Incident Report F2369657 3/3 29/08/2017 08:03:02

General Property Use Shop, Shopping mall, Supermarket, Service station, Car yard, Other sales use

Special Property Use Toy shop

Purpose Group CM - Crowd Merchandising

Comments

8/28/2017 3:46:13 PM

Reporter Comments

zeleased under the official Intorni Smoke detector in zone 7 operated. No sign of fire. Area cleared using TIC. Manager advised had a defective detector swapped out different area 6 weeks ago.

Sean McAvinue