

17/12/2018

Enquiry Trace Form - Preview

Enquiry: [Withheld under section 7(2)(a)]	Logged by: [Withheld under section 7(2)(a)]	on 08/05/2018 20:52
Service: Street Cleaning	Classification: Complaint	
Subject: General Enquiries/Complaints	Enquiry Ref: R[57/12710].....	
Desc.: On Victoria St, between Vivian and Abel Smith St. Have noticed lots of broken glass in the last month or so, and seems like the road sweeper just sweeps it into the bike lane and leaves it there. Its been this way for the past several weeks. Honestly looks like the cycle lane doesnt get any attention and only the rubble swept into it. Would be interested in the outcome of this request. Can an update on action be passed through to [Withheld under section 7(2)(a)] Social Media Team so that she can update the customer as the request came through WCC social media channel.		

Site: Victoria St (R1590), Te Aro, Wgtn	Area: Te Aro
Site Address: Victoria St	Ward: Lambton
Location: Victoria St, Te Aro	Contact: [Withheld under section 7(2)(a)]

Customer: [Withheld under section 7(2)(a)]	Time: 08/05/2018 20:52	Method: Social Media
Name: [Withheld under section 7(2)(a)]	Address:	

Current Status:				
No.	Effective	Status	Officer	Follow up Date
4	17/05/2018 06:00:50	Work Completed - Contractor	Civic CBD	
Notes: This was hand swept last week and this enquiry has only just come through today - site cleared - Job completed - 17.05.18 Jude				
NAR - ECC (RAMM ID: 673679)				

Status history:				
No.	Effective	Status	Officer	Notes
3	16/05/2018 15:23	Transferred to RAMM	Civic CBD	RAMM Dispatch ID=57/12710
2	16/05/2018 15:20	Re-Logged	Civic CBD	
1	08/05/2018 20:42	Request Logged	[Withheld under section 7(2)(a)]	

Revised Status:

Name : Signed : Date : Time :