30/01/2019	⊏nqui	ry Trace Form - Prev	iew	
Enquiry: Withheld under so	Logged by:	Withheld under section 7(2)(a)	<b>on</b> 26/05/2018 11:56	
Service: Traffic Ligh	nts	Classification:	Request for Service	
Subject: Timing and	d Phasing			
<b>Desc.:</b> Caller advised phasing is off at Victoria St intersection with Karo Dr and traffic from Victoria St is often stuck when traffic from Karo Dr is on a red light. Please contact.				
Site: Karo Drive (R2204), Te Aro, Wgtn				
Site Address: Karo Drive	•		Area: Te Aro	
Location: INT Karo Dr and Victoria St			Ward: Lambton	
			Contact: Withheld under section 7(2	
			Telephone: Withheld under section 7	
Customer: Withheld under st	<b>Time</b> : 26	/05/2018 11:56	Method: Telephone Call	
Name: Withheld under section	on 7(2		Telephone: Withheld under section 7	
Address:				
Current Status:				
No. Effective	Status	Officer	Follow up Date	
2 21/08/2018 11:08:04 ε	Completed	Steen Bohanna		
Notes: No fault found.				
Recent reports of poor co-ordination between the 2 intersections. Will consider changes if necessary.				
Status history:				
No. Effective	Status	Officer	Notes	
1 26/05/2018 11:50	Request Logged to RT	Tim Kirby		
Revised Status:				